

Estimation

№ E-002-00210

Test Drive Technologies 17715 St Rose Rd St Rose, IL 62230 Tel: 636-388-8378

steve@testdrivetech.com http://www.testdrivetech.com

Name: Removed For Privacy Protection

Address: 17715 St Rose Rd, St Rose, IL 62230

Date: 6/19/2017 2:03 PM

Make: Mercedes-Benz

Model: CLK

Year: 2005

Color: Black Mileage: 68928

Tag #:


R.O. #:


VIN #: WDBTK65J35F132135

Stock #:

Advisor:

Customer's Signature





Wheels

LF RF

☐ LR ☐ RR

Legend X EXTERIOR ISSUE TIRE REPLACEMENT X ELECTRICAL ISSUE MECHANICAL ISSUE # INTERIOR ISSUE

| # | Service | Amount |
|----|---|----------------|
| 01 | EXTERIOR ISSUE | \$1,500.00 |
| | LR QUARTER PANEL - PREVIOUS POOR REPAIR, SANDING MARKS IN FILLE EXISTS | ER, DENT STILL |
| 02 | EXTERIOR ISSUE | \$50.00 |
| L | RR ROCKER PANEL - LOOSE LOWER TRIM | |
| 03 | EXTERIOR ISSUE | \$0.00 |
| | REAR BUMPER - PANEL REPLACED | |
| 04 | EXTERIOR ISSUE | \$1,000.00 |
| | FRONT BUMPER - MOUNTING TAB BROKEN | |
| 05 | EXTERIOR ISSUE | \$500.00 |
| | LF HEADLAMP - HOUSING CRACKED ON TOP | |
| 06 | EXTERIOR ISSUE | \$100.00 |
| | LF DOOR - SCRATCHES IN FINISH UNDER HANDLE | |
| 07 | EXTERIOR ISSUE | \$500.00 |
| | REAR GLASS - BROKEN IN LOWER RIGHT CORNER | |

| 08 | REPLACE TIRE RF TIRE - NON-MATCHING SIZE, LOW ON TREAD | \$120.00 |
|----|---|-------------------|
| | REPLACE TIRE | \$120.00 |
| 09 | LF TIRE - UNEVEN TIRE WEAR | \$120.00 |
| 10 | REPLACE TIRE | \$120.00 |
| 10 | LR TIRE - NON-MATCHING SIZE, UNEVEN WEAR | φ120.00 |
| 11 | REPLACE TIRE | \$120.00 |
| •• | RR TIRE - NON-MATCHING TIRE SIZE, NON-MATCHING BRAND, LOW ON TR | · |
| 12 | EXTERIOR ISSUE | \$100.00 |
| | RF WHEEL - CURB RASH, UNPROFESSIONAL REPAIR | Ψ100100 |
| 13 | EXTERIOR ISSUE | \$100.00 |
| | LF WHEEL - CURB RASH | 7 |
| 14 | EXTERIOR ISSUE | \$100.00 |
| | LR WHEEL - CURB RASH, UNPROFESSIONAL REPAIR | , |
| 15 | EXTERIOR ISSUE | \$100.00 |
| | RR WHEEL - CURB RASH, UNPROFESSIONAL REPAIR, FINISH PEELING | |
| 16 | MECHANICAL ISSUE | \$500.00 |
| | POWER STEERING HOSE - LEAK ON LEFT SIDE OF MOTOR | |
| 17 | MECHANICAL ISSUE | \$500.00 |
| L | ENGINE - OIL LEAK FROM L&R VALVE COVERS | |
| 18 | INTERIOR ISSUE | \$250.00 |
| | SHIFTER CONSOLE - LOOSE, BROKEN CLIPS | |
| 19 | INTERIOR ISSUE | \$1,000.00 |
| | RF CARPET - HOLES IN CARPET AT CENTER DASH NEAR PASSENGER FEE | T ON LEFT |
| 20 | INTERIOR ISSUE | \$250.00 |
| | LF DOOR PANEL - WORN, STAINED | |
| 21 | INTERIOR ISSUE | \$250.00 |
| | STEERING WHEEL - WORN, STAINED | |
| 22 | INTERIOR ISSUE | \$250.00 |
| | LF SEAT - SEAT BOTTOM STITCHING WEAR | |
| 23 | INTERIOR ISSUE | \$300.00 |
| | TRUNK AREA - CARGO PROTECTIVE COVER STRUTS NOT CONNECTED / B | |
| 24 | ELECTRICAL ISSUE | \$25.00 |
| | RR LIGHT - PARKING LAMP INOP | |
| 25 | ELECTRICAL ISSUE | \$25.00 |
| | LICENSE PLATE LIGHT - RS BULB INOP | φ 7 000 00 |
| | Total: | \$7,880.00 |