

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES

ST Rose, ILLINOIS 62230 www.TestDriveTech.com PHONE: 636-388-8378

EMAIL: INFO@TESTDRIVETECH.COM



Vehicle Identification

VIN 1Q87G9N594578

Year: 1979

Make: CHEVROLET

Model: CAMARO Mileage: 99334 (TMU)

Hours: NA

Inspection Date: 10/10/2017

Trim: COUPE

Vehicle Type: COUPE

Number of Doors: 2

Engine Size: 305 CID V8 **Transmission Type: AUTO 3 SPEED**

Driveline Type: RWD

Section Notes: VIN VERIFIED BY VIN TAG ON DASH. VEHICLE CONDITION DOES NOT MATCH MILEAGE.

How Each Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "I" represents the best of the best and cream of Inspection Section Is the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

Left Front Fender	6.0	Right Front Fender	6.0
Left Hood Cowl	6.0	Right Hood Cowl	6.0
Left Front Door	6.0	Right Front Door	6.0
Left Center B-Pillar	NA	Right Center B-Pillar	NA
Left Rear Door	NA	Right Rear Door	NA
Left C-Pillar	6.0	Right C-Pillar	6.0
Left Quarter Panel	6.0	Right Quarter Panel	6.0
Left Rocker Panel	6.0	Right Rocker Panel	6.0
Section Condition Grade	6.0	Section Condition Grade	6.0

Section Notes: ALL PANELS REQUIRE A FULL SAND / STRIP TO BARE METAL. ROUGH FILLER FOUND ON SEVERAL PANELS INCLUDING THE QUARTER PANELS.

Front Body Condition

Rear Body Condition

Hood	6.0	Trunk	6.0
Front Bumper	6.0	Rear Bumper	6.0
Headlamps	6.0	Tail Lamps	6.0
Windshield Cowl	6.0	Deck Cowl	6.0
Front Roof Top	6.0	Rear Roof Top	6.0
Section Condition Grade	6.0	Section Condition Grade	6.0

HOOD IS NOT ALIGNED PROPERLY AND CATCHES THE FRONT GLASS.

Section Notes: TRUNK LOCK IS DAMAGED. FINISH ON ALL PANELS IS BEYOND REPAIR.

FILLER FOUND IN ROOF PANEL. BUMPERS ARE IN ROUGH CONDITION AS WELL.

Front Interior Condition

Rear Interior Condition

Front Seat Type	BUCKETS	Rear Seat Type	BENCH
Dashboard Condition	6.0	3rd Seat Present	NA
Steering Wheel Condition	6.0	Rear Seat Condition	6.0
Driver Seat Condition	6.0	Rear Deck Condition	6.0
Passenger Seat Condition	6.0	Rear Carpet Condition	6.0
Front Carpet Condition	6.0	3rd Seat Condition	NA
Left Front Door Panel	6.0	Right Front Door Panel	6.0
Left Rear Door Panel	NA	Right Rear Door Panel	NA
Cargo Interior Sides	UNKNOWN	Cargo Floor & Roof UNI	KNOWN
Front Center Console / Arm Rest	6.0	Rear Center Console / Arm Rest	NA
Section Condition Grade	6.0	Section Condition Grade	6.0

Section Notes: INTERIOR OF VEHICLE SHOWS HEAVY WATER STAINS, URINE STAINS FROM RODENTS, CRACKING IN DASH, DETERIORATED REAR DECK, CRACKED STEERING WHEEL. INTERIOR WILL NEED FULL REPLACEMENT. SEATS HARDWARE MAY STILL BE OK.

Tire Condition

Wheel Condition

EL W CAPS	Wheel Type STE	14 INCH	Front Tire Size
6.0	Left Front Wheel Condition	6.0	Left Front Tire Tread
6.0	Right Front Wheel Condition	6.0	Right Front Tire Tread
6.0	Left Rear Wheel Condition	14 INCH	Rear Tire Size
6.0	Right Rear Wheel Condition	6.0	Left Rear Tire Tread
NOWN	Spare Tire / Wheel Present UNI	6.0	Right Rear Tire Tread
(NOWN	Jack / Emergency Tools Present UNI	NA	Valve Caps Present
6.0	Section Condition Grade	6.0	Section Condition Grade

TIRES ARE FLAT, DRY ROTTED. WHEELS ARE SUNK INTO ROCK AND

Section Notes: RUSTED.

Interior Option Operation

Exterior Option Operation

Left Front Seat Operation	6.0	Left Front Window Operation UNKNOWN	
Right Front Seat Operation	6.0	Right Front Window Operation UNKNOWN	
Rear Seat Operation	NA	Left Rear Window Operation NA	
Heater / Fan	6.0	Right Rear Window Operation NA	
Stereo Operation	6.0	Cargo Door Operation 6.0	
Navigation Operation	NA	Door Locks Operation UNKNOWN	
Front Seat Belts Present	YES	Windshield Wiper Operation UNKNOWN	
Rear Seat Belts Present	YES	Rear Defrost Operation UNKNOWN	
Section Condition Grade	6.0	Section Condition Grade 6.0	

Section Condition Grade BATTERY COMPLETELY DEAD. SELLER OFFERED TO JUMP BUT RODENTS

Section Notes: HAVE EATEN A LOT OF WIRING. TOO DANGEROUS TO ATTEMPT A START.

<u>Interior Lighting Condition</u> <u>Exterior Lighting Condition</u>

6.0	Low Beam Head Light Operation	UNKNOWN	Dash Lamps Operation
6.0	High Beam Head Light Operation	UNKNOWN	Interior Lighting Operation
6.0	Parking Lamp Operation	UNKNOWN	Map Lights Operation
6.0	4-Way Flasher Operation	6.0	Dome Lights Operation
6.0	Left Turn Operation	6.0	Hood Lamp Operation
6.0	Right Turn Operation	UNKNOWN	Seat Belt Light Operation
6.0	Section Condition Grade	6.0	Section Condition Grade

Section Notes: BATTERY COMPLETELY DEAD. SELLER OFFERED TO JUMP BUT RODENTS HAVE EATEN A LOT OF WIRING. TOO DANGEROUS TO ATTEMPT A

Engine Mechanical Condition Transmission Mechanical Condition

Trans Housing Condition UNKNOWN		4.0	Engine Block Condition
6.0	Tran Lines Condition	6.0	Engine Hoses Condition
6.0	Trans Fluid Condition	6.0	Engine Oil Leaks
6.0	Trans Fluid Leaks Condition	6.0	Fuel Leaks
6.0	Trans Cooler Condition	6.0	Air Filter Condition
6.0	Trans Shifter Condition	4.0	Radiator Condition
6.0	Section Condition Grade	5.3	Section Condition Grade

Section Notes: ENGINE SHOWS TO HAVE BEEN SITTING FOR A VERY LONG TIME. HOSES ARE ROTTED, BELTS ARE ROTTED. WIRING IS EATEN BY RODENTS. NOT ABLE TO INSPECT TRANSMISSION BECAUSE CAR WAS TOO LOW IN ROCK, LINES ARE DRY ROTTED, SHIFTER WOULD NOT MOVE.

Brakes Mechanical Condition Steering Mechanical Condition Front Brake Material 6.0 **Rack-n-Pinion Condition** NA Front Brake Rotors / Drums 6.0 **Tie Rods Condition** 6.0 **Rear Brake Material Steering Linkage Condition** 6.0 6.0 Steering Column Condition **Rear Brake Rotors / Drums** 6.0 6.0

Pump / Gearbox Condition

Alignment Condition

Electrical Systems Condition

6.0

6.0

Section Condition Grade 6.0 Section Condition Grade 6.0

6.0

UNKNOWN

Section Notes: VEHICLE HAS BEEN SITTING SO LONG. ROTORS ARE RUSTED, DRUMS ARE RUSTED. BRAKE LINES APPEAR TO BE ROTTED. BUSHINGS ARE ROTTED, FLUID IS THICK AND DARK.

BATTERY DEAD. WIRING EATEN BY RODENTS. BUSHINGS AND SEALS ARE

Front Shocks Condition 6.0 **Diagnostic Trouble Codes Present** NA **Rear Shocks Condition** 6.0 Check Engine Light On / Off NA **Bushings Condition** 6.0 Airbag Light On / Off NA **Sway Bar Links Condition** 6.0 ABS Light On / Off NA **Suspension Control Condition** 6.0 Wiring Condition 6.0 **Control Arms Condition Battery Condition** 6.0 **Section Condition Grade** 6.0 **Section Condition Grade** 6.0

Section Notes: ROTTED.

Suspension Mechanical Condition

Unibody Frame Condition

Brake Lines Condition

Parking Brake Operation

Conventional Frame Condition

6.0	Frame Rail Repair / Condition	6.0	A,B,C,D Pillar Repair / Condition
6.0	Cross Member Repair / Condition	4.0	Firewall Repair / Condition
4.0	Radiator Core Repair / Condition	6.0	Floor Pans Repair / Condition
6.0	Trunk Pan Repair / Condition	4.0	Apron Repair / Condition
6.0	Spring Pod Repair / Condition	6.0	Inner Quarter Repair / Condition
6.0	Torque Box Repair / Condition	6.0	Frame Rail Repair / Condition
6.0	Wheel House Repair / Condition	6.0	Rocker Panel Repair / Condition
5.7	Section Condition Grade	5.4	Section Condition Grade

Section Notes: VEHICLE SHOWS ROTTED INNER QUARTERS, FRAME IS SITTING IN ROCK, LIKELY ROTTED AS WELL.

Test Drive Results Condition Summary

Acceleration	6.0	Body	6.0
Shifting	6.0	Interior	6.0
Steering	6.0	Features / Options	6.0
Braking	6.0	Mechanical	6.0
Ride / Handling	6.0	Electrical	6.0
Rattles / Noises	6.0	Structural	6.0
Warning Lights	6.0	Test Drive	6.0
Section Condition Grade	6.0	Overall Vehicle Grade	6.0

Section Notes: BATTERY DEAD. DID NOT START BECAUSE OF DANGEROUS WIRING.

Inspectors Notes: VEHICLE HAS BEEN SITTING IN THIS SAME SPOT FOR A LONG PERIOR OF TIME. TIRES ARE FLAT, CAR IS SITTING ON THE FRAME IN THE ROCK AND MUCH OF THE CAR IS ROTTING AWAY. MICE HAVE EATTEN MUCH OF THE WIRING AND SOME OF THE INTERIOR. VEHICLE IS ONLY GOOD FOR MAJOR MECHANICAL PARTS.