

Recalls

NHTSA Recall Number: 14V-214

TC Recall Number: N/A

Date Released: 5/12/2014

Units Affected: 2014 Solitude 369RL & 305RE

Build Dates: 2/21/13 - 7/24/13

VIN Range: E1100057 - E1100665

Summary: Frigidaire Convection Microwave Touch Pads

Download Recall PDF (</sites/default/files/NHTSA%20Recall%20Campaign%2014V-214.pdf>)

NHTSA Recall Number: 14V-476

TC Recall Number: 2014-331

Date Released: 8/18/2014

Units Affected: 2014 Momentum 355TH, 380TH, 385TH

Build Dates: 6/24/13 - 3/21/14

VIN Range: E1100707 - E1101902

Summary: "Correct Track" Hanger Bolt Shear

Download Recall PDF (/sites/default/files/page-files/Recall%20NHTSA%2014V-476%20Correct%20Track%20-%20Owner%20Letter_0.pdf)

NHTSA Recall Number: 15V-212

TC Recall Number: 2015-154

Date Released: 4/14/2015

Units Affected: 2015/2016 Reflection 303RLR, 308BHTS & 313RLTS w/5200# Axles, and 2016 Solitude 375RE w/7000# Axles

Build Dates: Reflection 3/12/15 - April 6, 2015, Solitude 4/30/15 - 5/7/15

VIN Range: Reflection F3302871 - G3303180, Solitude G1104904 - G1104909

Summary: "Tru-Ryde" Wheel Hub Stud Shear

Download Recall PDF (</sites/default/files/NHTSA%20Recall%20Campaign%2015V-212.pdf>)

NHTSA Recall Number: 15V-518

TC Recall Number: 2015-379

Date Released: 9/4/2015

Units Affected: 2014-2016 Reflection 337RLS, 323BHS, 317RST

Build Dates: 9/5/13 - 6/30/15

VIN Range: E1200129 - G3304306

Summary: Incorrect Size Axles (5200# vs. 6000#)

Download Recall PDF (</sites/default/files/NHTSA%20Recall%20Campaign%2015V-518.pdf>)

NHTSA Recall Number: 15V-822

TC Recall Number: N/A

Date Released: 1/11/2016

Units Affected: 2016 Momentum

Build Dates: 9/2/15 - 11/12/15

VIN Range: G1202200 - G1202405

Summary: Incorrect Fed Label Information (UVW & CCC)

Download Recall PDF (</sites/default/files/NHTSA%20Recall%20Campaign%2015V-822.pdf>)

NHTSA Recall Number: 16V-355

TC Recall Number: 2016-241

Date Released: 6/6/2016

Units Affected: 2016-2017 Reflection Fifth Wheels & Reflection Travel Trailers and Imagine Travel Trailers

Build Dates: 1/15/16 - 5/4/16

VIN Range: G3306600 - H3308256 and G3401435 - H3402004

Summary: Possible Defective 2-Stage LP Regulator

Download Recall PDF (/sites/default/files/page-files/Recall%20NHTSA%2016V-355%20LP%20Regulator%20Owner%20Letter_1.pdf)

NHTSA Recall Number: 16V-717

TC Recall Number: 2016-496

Date Released: 10/28/2016

Units Affected: 2015-2017 Reflection FW Models 357BHS and 367BHS

Build Dates: 11/12/2014 - 9/22/2016

VIN Range: F3301786 - H3310370

Summary: Incorrect Fed Label Information (GAWR)

Download Recall PDF (</sites/default/files/page-files/NHTSA%20Recall%2016V717.pdf>)

NHTSA Recall Number: 16V-841

TC Recall Number: 2016-573

Date Released: 12/16/2016

Units Affected: 2015-2016 Momentum Toy Haulers and Solitude 379FL, 365DEN and 366DEN

Build Dates: 7/8/2014 - 8/31/2015

VIN Range: Momentum - F1102640 - G1104924, F1201300 - G1202194 and Solitude - F1102694 - G1105349

Summary: Exterior Roof Access Ladder Folding Hinge - "Top Hat" Sections May Have Defective Welds

Download Recall PDF (</sites/default/files/page-files/NHTSA%20Recall%2016V841.pdf>)

NHTSA Recall Number: 17V-271

TC Recall Number: 2017-225

Date Released: 5/15/2017

Units Affected: 2017-2018 Imagine Travel Trailers

Build Dates: 12/1/16 - 4/3/17

VIN Range: H6600065 - J6601893

Summary: Schwintek Slide Out Room Column Attachment Screw Shear

[Download Recall PDF \(/sites/default/files/page-files/Recall%2017V-271_TC%202017-225%20Web%20Site%20pdf.pdf\)](#)