



St Rose, Illinois 62230

www.TestDriveTech.com

Phone: 636-388-8378

Email: info@testdrivetech.com

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 6/19/2017

VIN: WDBTK65J35F132135
Year: 2005
Make: MERCEDES-BENZ
Model: CLK
Mileage: 68928
Hours: NA

Trim: CONVERTIBLE
Vehicle Type: COUPE
Number of Doors 2
Engine Size: 6 CYL
Transmission Type: AUTOMATIC
Driveline Type: RWD

How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Left Front Fender	3.0
Left Windshield A-Pillar	3.0
Left Front Door	3.0
Left Center B-Pillar	NA
Left Rear Door	NA
Left C-Pillar	3.0
Left Quarter Panel	5.0
Section Condition Grade	3.4

Right Side Body Condition

Right Front Fender	3.0
Right Windshield A-Pillar	3.0
Right Front Door	3.0
Right Center B-Pillar	NA
Right Rear Door	NA
Right C-Pillar	3.0
Right Quarter Panel	3.0
Section Condition Grade	3.0

Section Notes: UNSATSIFACTORY REPAIR FOUND TO THE LR QUARTER PANEL, SEVERAL SCRACHES AND SCUFFS THROUGHOUT THE ENTIRE VEHICLE

Front Body Condition

Hood	3.0
Front Bumper	5.0
Headlamps	4.0
Windshield Cowl	3.0
Front Roof Top	3.0
Section Condition Grade	3.6

Rear Body Condition

Trunk	3.0
Rear Bumper	2.0
Tail Lamps	3.0
Deck Cowl	3.0
Rear Roof Top	3.0
Section Condition Grade	2.8

Section Notes: REAR BUMPER HAS BEEN REPLACED, FRONT BUMPER HAS A BROKEN MOUNTING TAB, LF LAMP HOUSING IS CRACKED AND HAS BEEN GLUED IN WITH SEALANT.

Front Interior Condition

Front Seat Type	BUCKET
Dashboard Condition	3.0
Steering Wheel Condition	4.0
Driver Seat Condition	4.0
Passenger Seat Condition	4.0
Front Carpet Condition	5.0
Left Front Door Panel	4.0
Left Rear Door Panel	NA
Cargo Interior Sides	3.0
Section Condition Grade	3.9

Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	3.0
Rear Deck Condition	NA
Rear Carpet Condition	3.0
3rd Seat Condition	NA
Right Front Door Panel	3.0
Right Rear Door Panel	NA
Cargo Floor & Roof	5.0
Section Condition Grade	3.5

Section Notes: STEERING WHEEL SHOWS WEAR AND STAINED, DOOR PANELS SHOW WEAR AND STAINS, CARGO COVER IN TRUNK IS NOT ATTACHED / BROKEN.

Tire Condition

Tire Manufacture	MULTI
Front Tire Size	245/45R17
Left Front Tire Tread	6.0
Right Front Tire Tread	5.0
Rear Tire Size	225/45R17
Left Rear Tire Tread	5.0
Right Rear Tire Tread	5.0
Section Condition Grade	5.3

Wheel Condition

Wheel Type	ALLOY
Left Front Wheel Condition	5.0
Right Front Wheel Condition	5.0
Left Rear Wheel Condition	5.0
Right Rear Wheel Condition	5.0
Spare Tire / Wheel Present	3
Jack / Emergency Tools Present	YES
Section Condition Grade	5.0

Section Notes: TIRES ARE IN POOR CONDITION AND NEED REPLACED DUE TO LOW TREAD AND UNEVEN WEAR. WHEELS HAVE SCUFFS ALL AROUND THEM, CURB RASH AND SOME UNPROFESSIONAL REPAIRS.

Interior Option Operation

Left Front Seat Operation	3.0
Right Front Seat Operation	3.0
Rear Seat Operation	NA
3rd Seat Operation	NA
Stereo Operation	3.0
Navigation Operation	3.0
Front Seat Belts Present	YES
Rear Seat Belts Present	YES
Section Condition Grade	3.0

Exterior Option Operation

Left Front Window Operation	3.0
Right Front Window Operation	3.0
Left Rear Window Operation	3.0
Right Rear Window Operation	3.0
Cargo Door Operation	3.0
Door Locks Operation	3.0
Windshield Wiper Operation	3.0
Rear Wiper Operation	NA
Section Condition Grade	3.0

Section Notes: FEATURES AND OPTIONS WORKING WELL.

Interior Lighting Condition

Dash Lamps Operation	2.0
Interior Lighting Operation	2.0
Map Lights Operation	2.0
Dome Lights Operation	2.0
Hood Lamp Operation	NA
Seat Belt Light Operation	2.0
Section Condition Grade	2.0

Exterior Lighting Condition

Low Beam Head Light Operation	2.0
High Beam Head Light Operation	2.0
Parking Lamp Operation	5.0
4-Way Flasher Operation	2.0
Left Turn Operation	2.0
Right Turn Operation	5.0
Section Condition Grade	3.0

Section Notes: RR TAILLIGHT, TURN BULB AND LICENSE PLATE BULB INOP

Engine Mechanical Condition

Engine Block Condition	3.0
Engine Hoses Condition	3.0
Engine Oil Condition	3.0
Oil Leaks Condition	4.0
Air Filter Condition	4.0
Radiator Condition	3.0
Section Condition Grade	3.3

Transmission Mechanical Condition

Trans Housing Condition	3.0
Tran Lines Condition	3.0
Trans Fluid Condition	3.0
Trans Fluid Leaks Condition	3.0
Trans Cooler Condition	3.0
Trans Shifter Condition	3.0
Section Condition Grade	3.0

Section Notes: ENGINE VALVE COVERS LEAKING OIL, OIL IS DIRTY AS WELL AS AIR FILTER.

Brakes Mechanical Condition

Front Brake Material	2.0
Front Brake Rotors / Drums	3.0
Rear Brake Material	3.0
Rear Brake Rotors / Drums	3.0
Brake Lines Condition	3.0
Parking Brake Operation	3.0
Section Condition Grade	2.8

Steering Mechanical Condition

Rack-n-Pinion Condition	3.0
Tie Rods Condition	4.0
Steering Linkage Condition	3.0
Steering Column Condition	3.0
Pump / Oil Lines Condition	5.0
Alignment Condition	5.0
Section Condition Grade	3.8

Section Notes: FRONT BRAKE PADS ARE NEW, REARS ARE ABOUT 50%, ROTORS NOT RESURFACED OR REPLACED BRAKE PEDAL FEELS SOFT. STEERING NEEDS ALIGNMENT, LEAK FROM POWER STEERING LINE IN ENGINE BAY

Suspension Mechanical Condition

Front Shocks Condition	3.0
Rear Shocks Condition	3.0
Bushings Condition	3.0
Sway Bar Links Condition	3.0
Suspension Control Condition	3.0
Control Arms Condition	3.0
Section Condition Grade	3.0

Electrical Systems Condition

Diagnostic Trouble Codes Present	NO
Check Engine Light On / Off	OFF
Airbag Light On / Off	OFF
ABS Light On / Off	OFF
Wiring Condition	3.0
Battery Condition	4.0
Section Condition Grade	3.5

Section Notes: BATTERY FAILED LOAD TEST ALTHOUGH IT CURRENTLY STARTS VEHICLE.

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	3.0
Firewall Repair / Condition	3.0
Floor Pans Repair / Condition	3.0
Apron Repair / Condition	3.0
Inner Quarter Repair / Condition	3.0
Frame Rail Repair / Condition	3.0
Rocker Panel Repair / Condition	3.0
Section Condition Grade	3.0

Conventional Frame Condition

Frame Rail Repair / Condition	3.0
Cross Member Repair / Condition	3.0
Radiator Core Repair / Condition	3.0
Trunk Pan Repair / Condition	3.0
Spring Pod Repair / Condition	3.0
Torque Box Repair / Condition	3.0
Wheel House Repair / Condition	3.0
Section Condition Grade	3.0

Section Notes: UNIBODY AND FRAME IS IN GOOD CONDITION.

Test Drive Results

Acceleration	3.0
Shifting	3.0
Steering	5.0
Braking	4.0
Ride / Handling	4.0
Rattles / Noises	5.0
Warning Lights	2.0
Section Condition Grade	3.7

Condition Summary

Body	3.2
Interior	3.7
Features / Options	3.0
Mechanical	3.1
Electrical	2.6
Structural	3.0
Test Drive	3.7
Overall Vehicle Grade	3.2

Section Notes: RUNS AND SHIFTS OK BUT PULLS TO THE RIGHT, VIBRATION IN STEERING WHEEL FROM 30-60 MPH AND BRAKE PEDAL IS SOFT SHOWING BRAKES NEED BLED. RATTLE HEARD IN LR BODY PANEL.

Inspectors Notes: VEHICLE SHOWS TO HAVE BEEN IN A COUPLE ACCIDENTS AND NOT FULLY REPAIRED PROPERLY. VEHICLE STILL NEEDS SOME MECHANICAL AND COSMETIC ISSUES RESOLVED AS WELL AS THE REAR LIGHTS FIXED AND REAR GLASS REPLACED.