



Test Drive Technologies Vehicle Inspection Report

17715 St Rose Rd
 St Rose, IL 62230
 Tel: 636-388-8378
 steve@testdrivetech.com
 http://www.testdrivetech.com


Date	Inspection #
11/30/2016	E-002-00153
Estimate Written By:	
Steven Paul	


HD Vehicle Information	
HD Vehicle Info	
Year	2012
Make	Sprinter / Airstream
Vehicle Identification Number (VIN)	WD3PF4CD9C5624349
Model	3500 / Interstate
Mileage	35754
Color	Black
Cab Type	Sleeper
Engine Size / Model	V6 / 3.0L
Fuel Type	Diesel
Transmission Speed / Model	5 Speed Automatic
Transmission Type	Full Automatic
Number of Keys	2
Options	
Roof Type / Condition	
Power / Manual Sunroof	Hard Top
Seat Coverings	
Seat Upholstry Type	Leather
Overall Condition	Checked And OK'd
Power / Manual Locks	
Power / Manual Locks	Power Locks
Keyless / Remote Entry	Yes
Overall Condition	Checked And OK'd
Power / Manual Windows	
Power / Manual Windows	Power Windows
Express Up / Down	Yes
Overall Condition	Checked And OK'd
Power / Manual Mirrors	
Power / Manual Mirrors	Power Mirrors
Overall Condition	Checked And OK'd
Heated	Yes




Options	
Power / Manual Seats	
Power / Manual Driver Seat	Manual Seat
Power / Manual Passenger Seat	Manual Seat
Overall Condition	Checked And OK'd
Power / Manual Sliding Doors	
Power / Manual Sliding Doors	Manual Door
Overall Condition	Checked And OK'd
Power / Manual Tailgate	
Power / Manual Liftgate	Manual Tailgate
Overall Condition	Checked And OK'd
Entertainment	
Stereo Type	AM / FM / Single CD
Speakers Condition	Checked And OK'd
Stereo Condition	Checked And OK'd
Aux Inpu / USB Input / iPod Input	Yes
Sirius / XM Radio Subscription	Yes
On Board Car Phone Operational	Yes
Bluetooth Connection Operational	Yes
Navigation	
Equipped	Yes
Overall Condition	Checked And OK'd
Electrical - Late Model	
Heating / AC System	
Fan Operational	Yes
Controls Responding	Yes
Circulate / Fresh Air Door Operational	Yes
Factory Heating	Yes
Heating Type	Engine Coolant
AC Equipped	Yes
AC Compressor Operational	Yes
Condensor Condition	Checked And OK'd
ECM / OBD	
Check Engine Light On	No
System Self Check Pass	Yes
Codes Present	No
Aftermarket Programming	No
ABS - Mechanical	
ABS Self System Check Performed (Bulb Working)	Yes
ABS Warning Light On	No
SRS / AirBag - Mechanical	
SRS Self System Check Performed (Bulb Working)	Yes
SRS Warning Light On	No
All Sensors In Place	Yes
TCM / Traction Control	
Equipped	Yes

Electrical - Late Model	
TCM / Traction Control	
System Type	Active
Overall Condition	Checked And OK'd
Entertainment	
Stereo Type	AM / FM / Single CD
Speakers Condition	Checked And OK'd
Stereo Condition	Checked And OK'd
Aux Inpu / USB Input / iPod Input	Yes
Sirius / XM Radio Subscription	Yes
On Board Car Phone Operational	Yes
Bluetooth Connection Operational	Yes
Wiring	
Factory Wiring	Yes
Cuts	No
Splices	No
Misc Wires in Fusebox	No
Missing Connectors	No
Overall Condition	Checked And OK'd
Exterior Lighting	
4 Way / Hazard Lamps Operational	Yes
Front Left Parking Light Operational	Yes
Front Left Turn Lamp Operational	Yes
Left Mirror Turn Indicator Operational	Yes
Front Left Low Beam Lamp Operational	Yes
Front Left High Beam Lamp Operational	Yes
Front Left Driving / Fog Lamp Operational	Yes
Front Right Parking Light Operational	Yes
Front Right Turn Lamp Operational	Yes
Right Mirror Turn Indicator Operational	Yes
Front Right Low Beam Lamp Operational	Yes
Front Right High Beam Lamp Operational	Yes
Front Right Driving / Fog Lamp Operational	Yes
Rear Left Parking Lamp Operational	Yes
Rear Left Turn Lamp Operational	Yes
Rear Left Brake Lamp Operational	Yes
Rear Right Parking Light Operational	Yes
Rear Right Turn Lamp Operational	Yes
Rear Right Brake Lamp Operational	Yes
Center Rear Brake Lamp Operational	Yes
Reverse Lamps Operational	Yes
Interior Lighting	
Lights Operational When Door Opened	Yes
Front Headliner Lamp Operational	Yes
Instrument Cluster Lamps Operational	Yes
Glovebox Lamp Operational	Yes

Electrical - Late Model	
Interior Lighting	
Cargo Area Lamp Operational	Yes
Motorhome Specific Checks	
HD - Mechanical Checks	
Brake System Type	Hydraulic Brakes
Front Brake Type	Disc
Front Brake Caliper / S-Cam Condition	Checked And OK'd
Front Brake Disc / Drum Condition	Checked And OK'd
Rear Brake Type	Disc
Rear Brake Caliper / S-Cam Condition	Checked And OK'd
Rear Front Brake Disc / Drum Condition	Checked And OK'd
RV - Exterior (info)	
Number of Doors	3
Number of Awnings	1
Power Awnings	Yes
Power Entry Steps	Yes
Sky Lights	Yes
Number of Roof Vents	2
Exterior Shower	Yes
Towing - Hitch Type	Hidden / Recessed Hitch
RV - Exterior - Inspection	
Walls Condition	Checked And OK'd
Entry Door Condition	Checked And OK'd
Awnings Condition	Checked And OK'd
Exterior Glass Condition	Checked And OK'd
Exterior Lighting Condition (lens only)	Checked And OK'd
Bumpers Condition	Future Attention Needed
Cargo Doors Condition	Checked And OK'd
Cargo Area Condition	Checked And OK'd
Roof Condition	Checked And OK'd
Exterior Sealant Condition	Checked And OK'd
Windshield Condition	Checked And OK'd
Wiper Blade Condition	Checked And OK'd
Towing - Hitch Condition	Checked And OK'd
Comments	LOWER SIDE TRIM PANELS, FRONT AND REAR BUMPERS HAVE MANY LIGHT SCRATCHES IN THE CLEAR COAT AS IF THEY WERE SCRUBBED WITH A SCOTCH BRIGHT PAD. LOOKS LIKE THEY CAN BE BUFFED OUT PROFESSIONALLY
RV - Holding Tanks - Inspection	
Tanks Winterized	No
Fresh Water Tank Condition	Checked And OK'd
Gray Water Tank Condition	Checked And OK'd
Waste Water Tank Condition	Checked And OK'd
Tanks Leaking	No
Propane Holding Tank Condition	Checked And OK'd

 Motorhome Specific Checks	
RV - Holding Tanks - Inspection	
Propane Holding Tank Full	No
Engine Fuel System Tank Condition	Checked And OK'd
Engine Fuel System Tank Leaks	No
Generator Fuel System Tank Condition	Checked And OK'd
Generator Fuel System Tank Leaks	No
Comments	LP TANK AT 1/4
RV - Interior Bathroom / Shower (info)	
Shower / Tub Type	Shower Only
Hot Tub Equipped	No
Vent Type	Manual Crank
RV - Interior Bathroom / Shower - Inspection	
Tub / Shower Condition	Checked And OK'd
Plumbing Leaks	No
Calking Condition	Checked And OK'd
Floor Condition	Checked And OK'd
Mildew Present	No
Cold Water Operational	Yes
Toilet Operation	Checked And OK'd
Lights	Checked And OK'd
Comments	Wasn't enough fresh water to fill hot water tank at time of inspection
RV - Interior Bedroom (info)	
Bed Size	Full
TV Type	Flat Panel
DVD Player Present	No
Gaming System Present	No
Separate Master Bathroom	No
Stereo System Present	No
RV - Interior Bedroom - Inspection	
Bed Condition	Checked And OK'd
Counter Condition	Checked And OK'd
TV Operation Condition	Checked And OK'd
Paneling Condition	Checked And OK'd
Door Condition	Checked And OK'd
Cabinetry Condition	Checked And OK'd
Closet Condition	Checked And OK'd
Lights Operation Condition	Checked And OK'd
RV - Instrumentation	
Volt Meter Present	Yes
Volt Meter Operation	Checked And OK'd
Fresh Water Holding Tank Guage Present	Yes
Fresh Water Holding Tank Guage Operation	Checked And OK'd
Gray Water Holding Tank Gauge Present	Yes
Gray Water Holding Tank Gauge Operation	Checked And OK'd
Black Water Holding Tank Gauge Present	Yes

 Motorhome Specific Checks	
RV - Instrumentation	
Black Water Holding Tank Gauge Operation	Checked And OK'd
Water Pump Power Display Present	Yes
Water Pump Power Display Operation	Checked And OK'd
Propane Tank Gauge Present	Yes
Propane Tank Gauge Operation	Checked And OK'd
RV - Interior Cockpit (info)	
Number of Seats	2
Seat Type	Bucket
Seat Material	Leather
Driver Power Seat	No
Passenger Power Seat	No
Seat Armrest	Yes
Overhead Lighting	Yes
Sun Visor Type	Manual
RV - Interior Cockpit - Inspection	
Driver Seat Condition	Checked And OK'd
Passenger Seat Condition	Checked And OK'd
Front Carpet Condition	Checked And OK'd
Overhead Lighting Condition	Checked And OK'd
Sun Visor Operation Condition	Checked And OK'd
RV - Interior Kitchen - Inspection	
Flooring Condition	Checked And OK'd
Table Condition	Checked And OK'd
Dining Area Curtain Condition	Checked And OK'd
Kitchen Area Curtain Condition	Checked And OK'd
Stove Condition	Checked And OK'd
Stove Burner Condition	Checked And OK'd
Microwave Oven Condition	Checked And OK'd
Refrigerator Condition	Checked And OK'd
Freezer Condition	Checked And OK'd
Sink Cover / Cutting Board Condition	Checked And OK'd
Countertop Condition	Checked And OK'd
Cabinet 1 Condtion	Checked And OK'd
Cabinet 2 Condtion	Checked And OK'd
Cabinet 3 Condtion	Checked And OK'd
Cabinet 4 Condtion	Checked And OK'd
Cabinet 5 Condtion	Checked And OK'd
Cabinet 6 Condtion	Checked And OK'd
Cabinet 7 Condtion	Checked And OK'd
Cabinet 8 Condtion	Checked And OK'd
Cabinet 9 Condtion	Checked And OK'd
Cabinet 10 Condtion	Checked And OK'd
RV - Interior Living Area (info)	
Living Area Location	Middle

 Motorhome Specific Checks	
RV - Interior Living Area (info)	
Living Area Shades / Curtain Types	Day / Night Pleated Shades
Number of Sofas	1
Sofa Material	Leather
Max Sleeping Count	2
Number of Convertible / Sofa Beds	1
RV - Interior Living Area - Inspection	
Live Area Shades Condition	Checked And OK'd
Sofa Condition	Checked And OK'd
Convertible Beds Condition	Checked And OK'd
Lighting Condition	Checked And OK'd
RV - Interior Electrical - Inspection	
Circuit Break Panel Box Condition	Checked And OK'd
All Light Switches Operational	Yes
All Lights Functioning	Yes
All Light Bulbs Present & Working	Yes
House Battery Disconnect Operational	Yes
House Battery System Charging	Yes
House Battery System Condition	Checked And OK'd
Generator Unit Powers All of House	Yes
Misc Wiring Exposed	No
Thermostat Operational	Yes
HVAC System Operational	Yes
AC Cools House - Under 10 Mins	Yes
RV - Interior Safety - Inspection	
Fire Extinguisher Present & Charged	No
Fire Alarm Self Test	Yes
Co2 Alarm Self Test	Yes
 Auxiliary Generator	
Auxiliary Generator	
Equipped	Yes
Fluid Level	Checked And OK'd
Starting Condition	Checked And OK'd
Idle Condition	Checked And OK'd
Noise Level Condition	Checked And OK'd
Power Supply Condition	Checked And OK'd
 HD Truck Wheels & Tires	
HDE Tires & Wheels	
LF Wheel & Hub Condition	Checked And OK'd
LF Tire Condition	Checked And OK'd
LF Tread Depth	14/32
RF Wheel & Hub Condition	Checked And OK'd
RF Tire Condition	Checked And OK'd
RF Tread Depth	12/32

HD Truck Wheels & Tires	
HDE Tires & Wheels	
LFO Wheel & Hub Condition	Checked And OK'd
LFO Tire Condition	Checked And OK'd
LFO Tread Depth	10/32
LFI Wheel & Hub Condition	Checked And OK'd
LFI Tire Condition	Checked And OK'd
LFI Tread Depth	10/32
RFO Wheel & Hub Condition	Checked And OK'd
RFO Tire Condition	Checked And OK'd
RFO Tread Depth	10/32
RFI Wheel & Hub Condition	Checked And OK'd
RFI Tire Condition	Checked And OK'd
RFI Tread Depth	10/32
All Studs Present	Yes
All Lug Nuts Present	Yes


HD Brake System	
ABS	
Type	4 Wheel ABS
ABS Fault Light On	No
Overall Condition	Checked And OK'd
ABS - Mechanical	
ABS Self System Check Performed (Bulb Working)	Yes
ABS Warning Light On	No
Hydraulic Brake System	
Type	Disc Front / Disc Rear (ABS)
Fluid Level	Checked And OK'd
Master Cylinder Condion	Checked And OK'd
Rubber Brake Line Condition	Checked And OK'd
Front Pad / Shoe Condition	Checked And OK'd
Front Caliper / Wheel Cyl Condition	Checked And OK'd
Front Disc / Drum Condition	Checked And OK'd
Rear Pad / Shoe Condition	Checked And OK'd
Rear Caliper / Wheel Cyl Condition	Checked And OK'd
Rear Disc / Drum Condition	Checked And OK'd
Brake Line Leaks	No

HD Engine & Exhaust	
Engine	
Type / Size	V6
Fuel Type	Road Diesel
Fuel / Air Delivery Type	Fuel Injection
Oil Leaks	No
Oil Condition	Checked And OK'd
Oil Lines Condition	Checked And OK'd
Oil Pan Damage	No

HD Engine & Exhaust	
Engine	
Air Filter Condition	Checked And OK'd
Coolant Leaks	No
Coolant Condition	Checked And OK'd
Coolant Hoses Condition	Checked And OK'd
Radiator Condition	Checked And OK'd
Vacuum Lines Condition	Checked And OK'd
Smoke From Tailpipe	No
Crackcase Noise	No
Valve Noise	No
Excessive Blow-By Present (exhaust / PVC)	No
Engine Idle	Checked And OK'd
Engine Mounts Condition	Checked And OK'd
Wiring Condition	Checked And OK'd
Engine Components	
Radiator Condition	Checked And OK'd
Air 2 Air Cooler Condition	Checked And OK'd
Major Hoses Condition	Checked And OK'd
Belts Condition	Checked And OK'd
Turbo Condition	Checked And OK'd
Starter Condition	Checked And OK'd
Alternator Condition	Checked And OK'd
Exhaust	
Muffler	Checked And OK'd
Catalytic Converter	Checked And OK'd
Piping	Checked And OK'd
Seals	Checked And OK'd
Hangers	Checked And OK'd
Clamps	Checked And OK'd
Tips	Checked And OK'd
HD Truck Drive Line	
Transmission	
Type / Size	Automatic 5 Speed
Shifter Type	Automatic - Floor Shifter
Shifter Condition	Checked And OK'd
Fluid Condition	Checked And OK'd
Fluid Level	Checked And OK'd
Fluid Leaks	No
Oil Pan Damage	No
Transmission Rear Seal Condition	Checked And OK'd
Driveline	
Drive-Shaft	Checked And OK'd
U-Joints	Checked And OK'd
Carrier Bearing	Checked And OK'd
Shaft Yokes	Checked And OK'd

HD Truck Drive Line	
Driveline	
Rear Axle Input Seal	Checked And OK'd
Rear Axle Wheel Seal	Checked And OK'd
Axle - Front	
Leaks Present	No
CV Shaft Boots Sealed	Yes
Axle - Intermediate	
Leaks Present	No
CV Shaft Boots Sealed	Yes
Axle - Rear	
Axle Type	Solid - Limited Slip
Fluid Level	Checked And OK'd
Fluid Condition	Checked And OK'd
Leaks Present	No
CV Shaft Boots Sealed	Yes
HD Truck Suspension	
HD Truck Suspension	
HD Truck Suspension Type	Full Spring Ride
Front Struts / Shocks Condition	Checked And OK'd
Front Ball Joints Condition	Checked And OK'd
Front Sway Bar Condition	Checked And OK'd
Front A-Arm Bushings Condition	Checked And OK'd
Front Sway Bar Bushings Condition	Checked And OK'd
Front Sway Bar Links Condition	Checked And OK'd
Front Springs Condition	Checked And OK'd
Rear Struts / Shocks Condition	Checked And OK'd
Rear Sway Bar Condition	Checked And OK'd
Rear Sway Bar Bushings Condition	Checked And OK'd
Rear Sway Bar Links Condition	Checked And OK'd
Rear Springs Condition	Checked And OK'd
HD Truck Frame / Structure	
Cross Members	
Original	Yes - Original
Signs of Corrosion	No
Bent	No
Cracked	No
Overall Condition	Checked And OK'd
Mounts	
Non-Factory Welds Present	No
Signs of Corrosion	No
Bent	No
Cracked	No
Overall Condition	Checked And OK'd

HD Truck Frame / Structure	
Brackets	
Signs of Corrosion	No
Non-Factory Welds Present	No
Bent	No
Cracked	No
Overall Condition	Checked And OK'd
Floor Pans	
Original	Yes - Original
Factory Welds	Yes
Signs of Corrosion	No
Bent	No
Cracked	No
Overall Condition	Checked And OK'd
HD Vehicle Test Drive	
RV / HD Truck Test Drive	
Test Drive Performed	Yes
Starting Mileage	35754
Ending Mileage	35765
Engine Idle	Checked And OK'd
RPM Performance	Checked And OK'd
PSI Hold Brake Applied	Yes
Acceleration From Stop	Checked And OK'd
Deacceleration From Coast	Checked And OK'd
Braking From 30 MPH	Checked And OK'd
Acceleration From 30 MPH	Checked And OK'd
Hard Left Turns	Checked And OK'd
Hard Right Turns	Checked And OK'd
Suspension Reaction	Checked And OK'd
Transmission Shifting	Checked And OK'd
Abnormal Noise During Drive	No
Shaking In Steering Wheel	No
Pulsing In Brake Pedal	No
Issues	Vehicle drove very nicely and performed very well
This Vehicle Was Inspected By	
Your Inspector's Information	
Inspectors Notes	This vehicle is in very good overall condition and has been very well maintained.
Inspector's Name	Steven S. Paul

This Vehicle Was Inspected By	
Your Inspector's Information	
Inspector's Signature	(See below)
	
Inspection Date	11/30/2016
Copyrighted by Test Drive Technologies - This report shall not be shared, altered or resold without written permission.	Yes