



WWW.
TESTDRIVETECH
VEHICLE INSPECTION SERVICES .COM

St Rose, Illinois 62230

WWW.TESTDRIVETECH.COM

PHONE: 636-388-8378

EMAIL: INFO@TESTDRIVETECH.COM

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 6/14/2017

VIN 242177P173182	Trim: 2 DR HARDTOP
Year: 1967	Vehicle Type: COUPE
Make: PONTIAC	Number of Doors: 2
Model: GTO	Engine Size: 8 CYL
Mileage: 70499	Transmission Type: MANUAL
Hours: NA	Driveline Type: RWD

How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

Left Front Fender	2.0
Left Windshield A-Pillar	2.0
Left Front Door	2.0
Left Center B-Pillar	NA
Left Rear Door	NA
Left C-Pillar	2.0
Left Quarter Panel	2.0

Right Front Fender	2.0
Right Windshield A-Pillar	2.0
Right Front Door	2.0
Right Center B-Pillar	NA
Right Rear Door	NA
Right C-Pillar	2.0
Right Quarter Panel	2.0

Section Condition Grade 2.0

Section Condition Grade 2.0

Section Notes: BODY HAS BEEN WELL RESTORED. PAINT LOOKS GOOD. IT DOES HAVE SOME MINOR IMPERFECTIONS IN THE SHADING BUT IS SMOOTH AND GLOSSY.

Front Body Condition

Hood	2.0
Front Bumper	2.0
Headlamps	2.0
Windshield Cowl	2.0
Front Roof Top	2.0
Section Condition Grade	2.0

Rear Body Condition

Trunk	4.0
Rear Bumper	2.0
Tail Lamps	3.0
Deck Cowl	2.0
Rear Roof Top	2.0
Section Condition Grade	2.6

Section Notes: LIGHT BUBBLING ON THE LEFT AND RIGHT CORNERS OF THE TRUNK LID. DOES NOT APPEAR TO BE SPREADING.

Front Interior Condition

Front Seat Type	BENCH
Dashboard Condition	2.0
Steering Wheel Condition	2.0
Driver Seat Condition	2.0
Passenger Seat Condition	2.0
Front Carpet Condition	2.0
Left Front Door Panel	2.0
Left Rear Door Panel	NA
Cargo Interior Sides	2.0
Section Condition Grade	2.0

Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	2.0
Rear Deck Condition	2.0
Rear Carpet Condition	2.0
3rd Seat Condition	NA
Right Front Door Panel	2.0
Right Rear Door Panel	NA
Cargo Floor & Roof	2.0
Section Condition Grade	2.0

Section Notes: INTERIOR IS IN GREAT CONDITION. IT HAS BEEN VERY WELL RESTORED.

Tire Condition

Front Tire Size	F70-14
Left Front Tire Tread	2.0
Right Front Tire Tread	2.0
Rear Tire Size	F70-14
Left Rear Tire Tread	2.0
Right Rear Tire Tread	2.0
Section Condition Grade	2.0

Wheel Condition

Wheel Type	STEEL WITH HUB CAPS
Left Front Wheel Condition	3.0
Right Front Wheel Condition	3.0
Left Rear Wheel Condition	3.0
Right Rear Wheel Condition	3.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	YES
Section Condition Grade	3.0

Section Notes: TIRES ARE IN VERY GOOD CONDITION. WHEELS HAVE SOME MINOR CHIPPING AROUND EDGES FROM MOUNTING TIRES.

Interior Option Operation

Left Front Seat Operation	2.0
Right Front Seat Operation	2.0
Rear Seat Operation	NA
3rd Seat Operation	NA
Stereo Operation	2.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	YES
Section Condition Grade	NA

Exterior Option Operation

Left Front Window Operation	2.0
Right Front Window Operation	2.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Cargo Door Operation	2.0
Door Locks Operation	2.0
Windshield Wiper Operation	2.0
Rear Defrost Operation	2.0
Section Condition Grade	2.0

Section Notes: ALL OPERATING AS DESIGNED. STEREO TUNES IN VERY WELL.

Interior Lighting Condition

Dash Lamps Operation	2.0
Interior Lighting Operation	2.0
Map Lights Operation	2.0
Dome Lights Operation	2.0
Hood Lamp Operation	NA
Seat Belt Light Operation	NA
Section Condition Grade	2.0

Exterior Lighting Condition

Low Beam Head Light Operation	2.0
High Beam Head Light Operation	2.0
Parking Lamp Operation	2.0
4-Way Flasher Operation	2.0
Left Turn Operation	2.0
Right Turn Operation	2.0
Section Condition Grade	2.0

Section Notes: ALL LIGHTS OPERATING AS DESIGNED EXCEPT FOR A BULB THAT IS BURNT OUT IN THE LEFT REAR.

Engine Mechanical Condition

Engine Block Condition	2.0
Engine Hoses Condition	2.0
Engine Oil Leaks	2.0
Fuel Leaks	2.0
Air Filter Condition	2.0
Radiator Condition	2.0
Section Condition Grade	2.0

Transmission Mechanical Condition

Trans Housing Condition	2.0
Tran Lines Condition	2.0
Trans Fluid Condition	2.0
Trans Fluid Leaks Condition	2.0
Trans Cooler Condition	2.0
Trans Shifter Condition	2.0
Section Condition Grade	2.0

Section Notes: ENGINE AND TRANSMISSION IN VERY GOOD CONDITION. THE TRANSMISSION AND REAR END HAVE BEEN CHANGED OUT AND ARE NOT ORIGINAL.

Brakes Mechanical Condition

Front Brake Material	2.0
Front Brake Rotors / Drums	2.0
Rear Brake Material	2.0
Rear Brake Rotors / Drums	2.0
Brake Lines Condition	2.0
Parking Brake Operation	2.0
Section Condition Grade	2.0

Steering Mechanical Condition

Rack-n-Pinion Condition	NA
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	2.0
Alignment Condition	2.0
Section Condition Grade	2.0

Section Notes: BRAKES ARE IN GOOD CONDITION. STEERING TIGHT AS DESIGNED.

Suspension Mechanical Condition

Front Shocks Condition	2.0
Rear Shocks Condition	2.0
Bushings Condition	2.0
Sway Bar Links Condition	2.0
Suspension Control Condition	2.0
Control Arms Condition	2.0
Section Condition Grade	2.0

Electrical Systems Condition

Diagnostic Trouble Codes Present	NO
Check Engine Light On / Off	OFF
Airbag Light On / Off	OFF
ABS Light On / Off	OFF
Wiring Condition	2.0
Battery Condition	2.0
Section Condition Grade	2.0

Section Notes: SUSPENSION AND ELECTRICAL SYSTEM IN GOOD CONDITION.

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	2.0
Firewall Repair / Condition	2.0
Floor Pans Repair / Condition	3.0
Apron Repair / Condition	2.0
Inner Quarter Repair / Condition	2.0
Frame Rail Repair / Condition	2.0
Rocker Panel Repair / Condition	2.0
Section Condition Grade	2.1

Conventional Frame Condition

Frame Rail Repair / Condition	2.0
Cross Member Repair / Condition	2.0
Radiator Core Repair / Condition	2.0
Trunk Pan Repair / Condition	2.0
Spring Pod Repair / Condition	2.0
Torque Box Repair / Condition	2.0
Wheel House Repair / Condition	2.0
Section Condition Grade	2.0

Section Notes: FLOOR PANS AND FRAME LOOK SOLID. IT DOES APPEAR SOME PATCHING HAS BEEN DONE ON THE FLOOR PANS AND HAS BEEN SMOOTHED OUT WITH SOME FILLER. NO CORROSION IS FOUND.

Test Drive Results

Acceleration	2.0
Shifting	2.0
Steering	2.0
Braking	2.0
Ride / Handling	NA
Rattles / Noises	NA
Warning Lights	NA

Section Condition Grade 2.0

Condition Summary

Body	2.3
Interior	2.0
Features / Options	2.0
Mechanical	2.0
Electrical	2.0
Structural	2.1
Test Drive	2.0

Overall Vehicle Grade 2.0

Section Notes: VEHICLE WAS NOT FULLY TEST DRIVEN DUE TO WEET ROAD CONDITIONS. IT WAS VERIFIED TO MOVE FORWARD AND BACKWARD AS WELL AS THE BRAKES HOLDING IN GEAR.

Inspectors Notes: THIS VEHICLE IS A GREAT OLDER RESTORATION. IT SHOWS AS A NEWER RESTORATION AND HAS BEEN EXTREMELY WELL KEPT OVER THE YEARS.