



WWW.
TESTDRIVETECH
VEHICLE INSPECTION SERVICES .COM

St Rose, Illinois 62230

www.TestDriveTech.com

Phone: 636-388-8378

Email: info@testdrivetech.com

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 7/5/2017

VIN: 27RA206073	Trim: DELUXE
Year: 1936	Vehicle Type: CABRIOLET
Make: FORD	Number of Doors: 2
Model: MODEL 68	Engine Size: 8 CYL
Mileage: 19490	Transmission Type: 3 SPEED
Hours: NA	Driveline Type: RWD

How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

Left Front Fender	4.0	Right Front Fender	3.0
Left Windshield A-Pillar	2.0	Right Windshield A-Pillar	2.0
Left Front Door	2.0	Right Front Door	2.0
Left Center B-Pillar	NA	Right Center B-Pillar	NA
Left Rear Door	NA	Right Rear Door	NA
Left C-Pillar	2.0	Right C-Pillar	2.0
Left Quarter Panel	4.0	Right Quarter Panel	2.0
Section Condition Grade	2.8	Section Condition Grade	2.2

Section Notes: FINISH IS GLOSSY AND BRIGHT. SOME DEEP SCRATCHING IN THE LF FENDER FROM HOOD LATCH HITTING. SOME MINOR CRACKING IN FIBERGLASS IN THE LEFT REAR NEAR THE BUMPER MOUNT AND SOME BLEMISH IN THE RIGHT FRONT FENDER WHERE IT LOOKS LIKE A REPAIR WAS DONE.

Front Body Condition

Hood	2.0
Front Bumper	2.0
Headlamps	2.0
Windshield Cowl	2.0
Front Roof Top	4.0
Section Condition Grade	2.4

Rear Body Condition

Trunk	2.0
Rear Bumper	2.0
Tail Lamps	2.0
Deck Cowl	2.0
Rear Roof Top	4.0
Section Condition Grade	2.4

Section Notes: BUMPERS ARE IN LIKE NEW CONDITION, WELL POLISHED AND MOUNTED CORRECTLY. SOME WEAR ON THE CONVERTIBLE TOP IN

Front Interior Condition

Front Seat Type	BENCH
Dashboard Condition	4.0
Steering Wheel Condition	3.0
Driver Seat Condition	2.0
Passenger Seat Condition	2.0
Front Carpet Condition	2.0
Left Front Door Panel	2.0
Left Rear Door Panel	NA
Cargo Interior Sides	2.0
Section Condition Grade	2.4

Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	2.0
Rear Deck Condition	2.0
Rear Carpet Condition	2.0
3rd Seat Condition	NA
Right Front Door Panel	2.0
Right Rear Door Panel	NA
Cargo Floor & Roof	2.0
Section Condition Grade	2.0

Section Notes: DASH HAS A SCRATCH JUST TO THE RIGHT OF STEERING WHEEL, STEERING WHEEL HAS SOME MINOR PITTING.

Tire Condition

Tire Brand	LETTER TIRE CO
Front Tire Size	6.00-18
Left Front Tire Condition	5.0
Right Front Tire Condition	4.0
Rear Tire Size	6.00-18
Left Rear Tire Condition	4.0
Right Rear Tire Condition	4.0
Section Condition Grade	4.3

Wheel Condition

Wheel Type	STEAL WITH TRIM RINGS
Left Front Wheel Condition	2.0
Right Front Wheel Condition	2.0
Left Rear Wheel Condition	2.0
Right Rear Wheel Condition	2.0
Spare Tire / Wheel Condition	4.0
Jack / Emergency Tools Present	YES
Section Condition Grade	2.4

Section Notes: LF TIRE SHOWS SOME CRACKING IN SIDEWALL FROM STORAGE, OTHER TIRES SHOW USE AND LOWER TREAD. REPLACEMENT RECOMMENDED. WHEELS LOOK GOOD, SOME SCRATCHING ON SPARE TIRE WHEEL.

Interior Option Operation

Left Front Seat Operation	NA
Right Front Seat Operation	NA
Rear Seat Operation	NA
3rd Seat Operation	NA
Stereo Operation	3.0
Navigation Operation	NA
Front Seat Belts Present	NA
Rear Seat Belts Present	NA
Section Condition Grade	3.0

Exterior Option Operation

Left Front Window Operation	3.0
Right Front Window Operation	3.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Cargo Door Operation	2.0
Door Locks Operation	2.0
Windshield Wiper Operation	2.0
Rear Defrost Operation	NA
Section Condition Grade	2.4

Section Notes: RADIO POWERS ON AFTER A FEW SECONDS OF WARM UP. DOES NOT TUNE CHANNEL. LIKELY NEEDS AN ANTENNA. WINDOWS, LOCKS AND WIPERS OPERATE AS DESIGNED BUT COULD BE A BIT SMOOTHER.

Interior Lighting Condition

Dash Lamps Operation	3.0
Interior Lighting Operation	2.0
Map Lights Operation	NA
Dome Lights Operation	NA
Hood Lamp Operation	NA
Seat Belt Light Operation	NA
Section Condition Grade	2.5

Exterior Lighting Condition

Low Beam Head Light Operation	2.0
High Beam Head Light Operation	NA
Parking Lamp Operation	2.0
4-Way Flasher Operation	2.0
Left Turn Operation	2.0
Right Turn Operation	4.0
Section Condition Grade	2.4

Section Notes: LF FOG LAMP DIM (LIKELY A GROUND ISSUE), RIGHT TURN INOP, BRAKES AND OTHER LIGHTS OPERATING AS DESIGNED. DASH LIGHTS BRIGHTER ON LEFT THAN RIGHT.

Engine Mechanical Condition

Engine Block Condition	3.0
Engine Hoses Condition	2.0
Engine Oil Leaks	2.0
Fuel Leaks	2.0
Air Filter Condition	2.0
Radiator Condition	2.0
Section Condition Grade	2.2

Transmission Mechanical Condition

Trans Housing Condition	2.0
Tran Lines Condition	2.0
Trans Fluid Condition	2.0
Trans Fluid Leaks Condition	2.0
Trans Cooler Condition	2.0
Trans Shifter Condition	2.0
Section Condition Grade	2.0

Section Notes: ENGINE AND TRANSMISSION ARE IN GOOD CONDITION. COMPRESSION CHECK WAS PERFORMED AS REQUESTED. 40 PSI IN RIGHT SIDE AND 60'S IN LEFT SIDE.

Engine Compression Test Results

Left Side (Driver)	Right Side (Passenger)		
Front	Front	After Oil	
62		39	39
61		40	40
62		50	50
52		39	39

Brakes Mechanical Condition

Front Brake Material	2.0
Front Brake Rotors / Drums	2.0
Rear Brake Material	2.0
Rear Brake Rotors / Drums	2.0
Brake Lines Condition	2.0
Parking Brake Operation	2.0
 Section Condition Grade	 2.0

Steering Mechanical Condition

Rack-n-Pinion Condition	NA
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	2.0
Alignment Condition	2.0
 Section Condition Grade	 2.0

Section Notes: BRAKES ARE IN GOOD CONDITION. STEERING TIGHT AS DESIGNED.

Suspension Mechanical Condition

Front Shocks Condition	2.0
Rear Shocks Condition	2.0
Bushings Condition	2.0
Sway Bar Links Condition	NA
Suspension Control Condition	NA
Control Arms Condition	2.0
 Section Condition Grade	 2.0

Electrical Systems Condition

Diagnostic Trouble Codes Present	NO
Check Engine Light On / Off	OFF
Airbag Light On / Off	OFF
ABS Light On / Off	OFF
Wiring Condition	2.0
Battery Condition	1.0
 Section Condition Grade	 1.5

Section Notes: SUSPENSION, STEERING IN GOOD CONDITION. NEW BATTERY, WIRING LOOKS PRETTY GOOD.

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	2.0
Firewall Repair / Condition	2.0
Floor Pans Repair / Condition	2.0
Apron Repair / Condition	2.0
Inner Quarter Repair / Condition	2.0
Frame Rail Repair / Condition	2.0
Rocker Panel Repair / Condition	2.0
 Section Condition Grade	 2.0

Conventional Frame Condition

Frame Rail Repair / Condition	2.0
Cross Member Repair / Condition	2.0
Radiator Core Repair / Condition	2.0
Trunk Pan Repair / Condition	2.0
Spring Pod Repair / Condition	2.0
Torque Box Repair / Condition	2.0
Wheel House Repair / Condition	2.0
 Section Condition Grade	 2.0

Section Notes: PILLARS, FLOORS, FIREWALL AND FRAME ALL APPEAR SOLID AND WELL RESTORED. UNDERCARRIAGE IS CLEAN AND WELL KEPT.

Test Drive Results

Acceleration	3.0
Shifting	2.0
Steering	2.0
Braking	3.0
Ride / Handling	2.0
Rattles / Noises	2.0
Warning Lights	2.0

Section Condition Grade 2.3

Condition Summary

Body	2.4
Interior	2.2
Features / Options	2.7
Mechanical	2.3
Electrical	2.5
Structural	2.0
Test Drive	2.3

Overall Vehicle Grade 2.3

Section Notes: VEHICLE NICE TO DRIVE. STARTS AND RUNS WELL. IT DID DIE ON ME WHEN RETURNING AND WAS A BIT TOUGH TO START BUT STARTED BACK UP AND RAN OK.

Inspectors Notes: THIS VEHICLE SHOWS AN OLDER RESTORATION BUT HAS BEEN WELL KEPT. IT DOES HAVE A LARGE VARIANCE IN COMPRESSION BETWEEN THE LEFT AND RIGHT HEAD WHICH COULD BE THE DIFFERENCE OF A HEAD GASKET OR FURTHER ISSUES. THE CAR SHOWS A FEW COSMETIC ISSUES AND SOME AREAS FOR IMPROVMENT WHICH COULD EASILY BRING IT UP TO A SOLID #2 CAR AND BE DEEMED IN EXCELLENT CONDITION.