



WWW.  
**TESTDRIVETECH**  
VEHICLE INSPECTION SERVICES .COM

St Rose, Illinois 62230

[www.TestDriveTech.com](http://www.TestDriveTech.com)

Phone: 636-388-8378

Email: [info@testdrivetech.com](mailto:info@testdrivetech.com)

# TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



## Vehicle Identification

Inspection Date: 7/18/2017

VIN AK664115  
Year: 1967  
Make: ALFA  
Model: ROMEO  
Mileage: 24  
Hours: NA

Trim: DUETTO  
Vehicle Type: CONVERTIBLE  
Number of Doors: 2  
Engine Size: 4 CYL  
Transmission Type: MANUAL  
Driveline Type: RWD

**Section Notes:** MILEAGE SHOWN IS NOT ACCURATE. ODOMETER IS WORKING AND VERIFIED DURING TEST DRIVE TO ROLL OVER 1 MILE ON THE ODOMETER. TRUE MILEAGE IS NOT KNOWN.

How Each  
Inspection Section Is  
Graded

*Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.*

## Left Side Body Condition

## Right Side Body Condition

Left Front Fender	3.0
Left Windshield A-Pillar	3.0
Left Front Door	3.0
Left Center B-Pillar	NA
Left Rear Door	NA
Left C-Pillar	3.0
Left Quarter Panel	3.0
<b>Section Condition Grade</b>	<b>3.0</b>

Right Front Fender	3.0
Right Windshield A-Pillar	3.0
Right Front Door	3.0
Right Center B-Pillar	NA
Right Rear Door	NA
Right C-Pillar	3.0
Right Quarter Panel	3.0
<b>Section Condition Grade</b>	<b>3.0</b>

**Section Notes:** BODY OF VEHICLE SHOWS TO BE DONE WELL BUT APPEARS TO BE AN OLDER RESPRAY THAT HAS BEEN DECENTLY KEPT.

### Front Body Condition

Hood	3.0
Front Bumper	3.0
Headlamps	3.0
Windshield Cowl	3.0
Front Roof Top	3.0
Section Condition Grade	3.0

### Rear Body Condition

Trunk	3.0
Rear Bumper	3.0
Tail Lamps	3.0
Deck Cowl	3.0
Rear Roof Top	3.0
Section Condition Grade	3.0

**Section Notes:** BODY OF VEHICLE SHOWS TO BE DONE WELL BUT APPEARS TO BE AN OLDER RESPRAY THAT HAS BEEN DECENTLY KEPT.

### Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	4.0
Steering Wheel Condition	3.0
Driver Seat Condition	3.0
Passenger Seat Condition	3.0
Front Carpet Condition	3.0
Left Front Door Panel	3.0
Left Rear Door Panel	NA
Cargo Interior Sides	3.0
Section Condition Grade	3.1

### Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	3.0
Rear Deck Condition	3.0
Rear Carpet Condition	3.0
3rd Seat Condition	NA
Right Front Door Panel	3.0
Right Rear Door Panel	NA
Cargo Floor & Roof	3.0
Section Condition Grade	3.0

**Section Notes:** INTERIOR IS IN FAIR CONDITION. THE LOWER DASHBOARD PAD IS CRACKED AND WHILE THE INTERIOR IS ORIGINAL IT DOES SHOW ITS AGE.

### Tire Condition

Tire Brand	MASTERCRAFT
Front Tire Size	185/65R15
Left Front Tire Tread	2.0
Right Front Tire Tread	2.0
Rear Tire Size	185/65R15
Left Rear Tire Tread	2.0
Right Rear Tire Tread	2.0
Section Condition Grade	2.0

### Wheel Condition

Wheel Type	STEAL WITH TRIM RINGS
Left Front Wheel Condition	3.0
Right Front Wheel Condition	3.0
Left Rear Wheel Condition	3.0
Right Rear Wheel Condition	3.0
Spare Tire / Wheel Present	NO
Jack / Emergency Tools Present	NO
Section Condition Grade	3.0

**Section Notes:** TIRES ARE IN GOOD CONDITION BUT ARE NOT PERIOD CORRECT. RIGHT FRONT TIRE BRAND DOES NOT MATCH OTHER 3. SPARE AND TOOLS NOT PRESENT.

**Interior Option Operation**

Left Front Seat Operation	3.0
Right Front Seat Operation	3.0
Rear Seat Operation	NA
3rd Seat Operation	NA
Stereo Operation	6.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	YES
Section Condition Grade	NA

**Exterior Option Operation**

Left Front Window Operation	3.0
Right Front Window Operation	3.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Cargo Door Operation	3.0
Door Locks Operation	3.0
Windshield Wiper Operation	3.0
Rear Defrost Operation	3.0
Section Condition Grade	3.0

Section Notes: STEREO WOULD NOT POWER ON, FACTORY RADIO IS IN TRUNK.  
STEERING WHEEL IS NICE, FACTORY WHEEL IN TRUNK.

**Interior Lighting Condition**

Dash Lamps Operation	3.0
Interior Lighting Operation	3.0
Map Lights Operation	3.0
Dome Lights Operation	NA
Hood Lamp Operation	3.0
Seat Belt Light Operation	NA
Section Condition Grade	3.0

**Exterior Lighting Condition**

Low Beam Head Light Operation	3.0
High Beam Head Light Operation	3.0
Parking Lamp Operation	5.0
4-Way Flasher Operation	3.0
Left Turn Operation	3.0
Right Turn Operation	3.0
Section Condition Grade	3.3

Section Notes: RR TAILLAMP INOPERABLE. ALL OTHERS OPERATING AS DESIGNED.

**Engine Mechanical Condition**

Engine Block Condition	3.0
Engine Hoses Condition	3.0
Engine Oil Leaks	3.0
Fuel Leaks	1.0
Air Filter Condition	3.0
Radiator Condition	4.0
Section Condition Grade	2.8

**Transmission Mechanical Condition**

Trans Housing Condition	3.0
Tran Lines Condition	3.0
Trans Fluid Condition	3.0
Trans Fluid Leaks Condition	1.0
Trans Cooler Condition	NA
Trans Shifter Condition	3.0
Section Condition Grade	2.6

Section Notes: POWERTRAIN IS IN GOOD CONDITION. ENGINE HAS A BIT OF HESITATION TO IT FROM SITTING AS THE CARB NEEDS A GOOD CLEAN OUT AND LIKELY SOME NEW PLUGS INSTALLED. RADIATOR HAS SOME BENT FINS ON THE FAN SIDE.

**Brakes Mechanical Condition**

Front Brake Material	3.0
Front Brake Rotors / Drums	3.0
Rear Brake Material	3.0
Rear Brake Rotors / Drums	3.0
Brake Lines Condition	3.0
Parking Brake Operation	6.0
Section Condition Grade	3.5

**Steering Mechanical Condition**

Rack-n-Pinion Condition	NA
Tie Rods Condition	3.0
Steering Linkage Condition	3.0
Steering Column Condition	3.0
Pump / Gearbox Condition	NA
Alignment Condition	3.0
Section Condition Grade	3.0

**Section Notes:** BRAKES ARE IN GOOD CONDITION. PARKING BRAKE IS NOT OPERABLE. STEERING IS NICE AND TIGHT.

**Suspension Mechanical Condition**

Front Shocks Condition	3.0
Rear Shocks Condition	3.0
Bushings Condition	3.0
Sway Bar Links Condition	3.0
Suspension Control Condition	3.0
Control Arms Condition	3.0
Section Condition Grade	3.0

**Electrical Systems Condition**

Diagnostic Trouble Codes Present	NO
Check Engine Light On / Off	OFF
Airbag Light On / Off	OFF
ABS Light On / Off	OFF
Wiring Condition	4.0
Battery Condition	3.0
Section Condition Grade	3.5

**Section Notes:** SUSPENSION AND ELECTRICAL SYSTEM IN GOOD CONDITION. WIRING COULD BE BETTER IN SEVERAL PLACES THROUGHOUT THE CAR BUT IS

**Unibody Frame Condition**

A,B,C,D Pillar Repair / Condition	3.0
Firewall Repair / Condition	3.0
Floor Pans Repair / Condition	6.0
Apron Repair / Condition	3.0
Inner Quarter Repair / Condition	3.0
Frame Rail Repair / Condition	3.0
Rocker Panel Repair / Condition	3.0
Section Condition Grade	3.4

**Conventional Frame Condition**

Frame Rail Repair / Condition	3.0
Cross Member Repair / Condition	3.0
Radiator Core Repair / Condition	3.0
Trunk Pan Repair / Condition	3.0
Spring Pod Repair / Condition	3.0
Torque Box Repair / Condition	6.0
Wheel House Repair / Condition	3.0
Section Condition Grade	3.4

**Section Notes:** UNDERCARRIAGE AROUND THE FRONT TORQUE BOXES HAVE SOFT SPOTS AS WELL AS SOME SEALANT STUFFED IN THE HOLES. LEFT SIDE REAR FLOOR HAS BEEN REPAIRED AND SHOWS SOME UNDERCOATING FLAKING.

## Test Drive Results

Acceleration	4.0
Shifting	3.0
Steering	3.0
Braking	3.0
Ride / Handling	3.0
Rattles / Noises	3.0
Warning Lights	1.0

Section Condition Grade 2.9

## Condition Summary

Body	3.0
Interior	3.1
Features / Options	4.0
Mechanical	3.0
Electrical	4.0
Structural	3.4
Test Drive	2.9

Overall Vehicle Grade 3.3

**Section Notes:** VEHICLE STUTTERS A BIT JUST OFF THROTTLE FROM SITTING FOR SOME TIME. NEEDS A GOOD TUNE-UP AND RAN FOR A WHILE.

**Inspectors Notes:** VEHICLE IS IN FAIR TO GOOD CONDITION. IT SHOWS TO HAVE BEEN MAINTAINED WELL BUT STILL HAS SEVERAL AREAS FOR IMPROVEMENT MAINLY THE UNDERCARRIAGE IN THE FRONT FLOORS AND TORQUE BOXES. SEVERAL ORIGINAL APPEARING ITEMS IN THE TRUNK ALONG WITH A FULL FOLDER OF PAPERWORK AND DOCUMENTATION.