



WWW.
TESTDRIVETECH
VEHICLE INSPECTION SERVICES .COM

St Rose, Illinois 62230

www.TestDriveTech.com

Phone: 636-388-8378

Email: info@testdrivetech.com

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 7/5/2017

VIN 242677k137481	Trim: CONVERTIBLE
Year: 1967	Vehicle Type: COUPE
Make: PONTIAC	Number of Doors: 2
Model: GTO	Engine Size: 8 CYL
Mileage: 81754	Transmission Type: AUTO
Hours: NA	Driveline Type: RWD

How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

Left Front Fender	3.0	Right Front Fender	3.0
Left Windshield A-Pillar	3.0	Right Windshield A-Pillar	3.0
Left Front Door	3.0	Right Front Door	3.0
Left Center B-Pillar	NA	Right Center B-Pillar	NA
Left Rear Door	NA	Right Rear Door	NA
Left C-Pillar	3.0	Right C-Pillar	3.0
Left Quarter Panel	3.0	Right Quarter Panel	3.0
Section Condition Grade	3.0	Section Condition Grade	3.0

Section Notes: PAINT IS GLOSSY HOWEVER IT SHOWS LARGE CHIPS AND SOME SANDING MARKS HERE AND THERE.

Front Body Condition

Hood	3.0
Front Bumper	4.0
Headlamps	2.0
Windshield Cowl	3.0
Front Roof Top	3.0
Section Condition Grade	3.0

Rear Body Condition

Trunk	4.0
Rear Bumper	4.0
Tail Lamps	3.0
Deck Cowl	4.0
Rear Roof Top	3.0
Section Condition Grade	3.6

Section Notes: BUMPERS HAVE BEEN RECHROMED HOWEVER IT IS PEELING OFF. REAR COWL HAS SANDING MARKS, HEAVY FILLER BEHIND BUMPERS IN

Front Interior Condition

Front Seat Type	BENCH
Dashboard Condition	4.0
Steering Wheel Condition	3.0
Driver Seat Condition	3.0
Passenger Seat Condition	3.0
Front Carpet Condition	3.0
Left Front Door Panel	3.0
Left Rear Door Panel	NA
Cargo Interior Sides	3.0
Section Condition Grade	3.1

Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	3.0
Rear Deck Condition	3.0
Rear Carpet Condition	3.0
3rd Seat Condition	NA
Right Front Door Panel	3.0
Right Rear Door Panel	NA
Cargo Floor & Roof	3.0
Section Condition Grade	3.0

Section Notes: INTERIOR IS IN FAIR CONDITION. THE DASHBOARD PAD IS CRACKED AND WHILE THE INTERIOR IS ORIGINAL IT DOES SHOW ITS AGE.

Tire Condition

Tire Brand	KUMHO
Front Tire Size	205/75R15
Left Front Tire Tread	2.0
Right Front Tire Tread	2.0
Rear Tire Size	205/75R15
Left Rear Tire Tread	2.0
Right Rear Tire Tread	2.0
Section Condition Grade	2.0

Wheel Condition

Wheel Type	STEAL WITH TRIM RINGS
Left Front Wheel Condition	4.0
Right Front Wheel Condition	4.0
Left Rear Wheel Condition	4.0
Right Rear Wheel Condition	4.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	YES
Section Condition Grade	4.0

Section Notes: TIRES ARE IN GOOD CONDITION HOWEVER ARE NOT PERIOD CORRECT. WHEELS HAVE BEEN REPAINTED AND THE COATING IS FLAKING OFF AND SHOWING RED BEHIND IT.

Interior Option Operation

Left Front Seat Operation	2.0
Right Front Seat Operation	2.0
Rear Seat Operation	NA
3rd Seat Operation	NA
Stereo Operation	2.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	YES
Section Condition Grade	NA

Exterior Option Operation

Left Front Window Operation	3.0
Right Front Window Operation	3.0
Left Rear Window Operation	3.0
Right Rear Window Operation	3.0
Cargo Door Operation	3.0
Door Locks Operation	3.0
Windshield Wiper Operation	3.0
Rear Defrost Operation	3.0
Section Condition Grade	3.0

Section Notes: EVERYTHING IS WORKING HOWEVER WINDOWS ARE HARD TO ROLL UP AND DOWN. NEED TRACKS ADJUSTED.

Interior Lighting Condition

Dash Lamps Operation	2.0
Interior Lighting Operation	2.0
Map Lights Operation	2.0
Dome Lights Operation	2.0
Hood Lamp Operation	NA
Seat Belt Light Operation	NA
Section Condition Grade	2.0

Exterior Lighting Condition

Low Beam Head Light Operation	2.0
High Beam Head Light Operation	2.0
Parking Lamp Operation	2.0
4-Way Flasher Operation	2.0
Left Turn Operation	2.0
Right Turn Operation	2.0
Section Condition Grade	2.0

Section Notes: ALL LIGHTS OPERATING AS DESIGNED. HEADLAMP BULBS ARE NOT PERIOD CORRECT AND DO NOT MATCH BRANDS OR POWER

Engine Mechanical Condition

Engine Block Condition	2.0
Engine Hoses Condition	2.0
Engine Oil Leaks	2.0
Fuel Leaks	2.0
Air Filter Condition	2.0
Radiator Condition	2.0
Section Condition Grade	2.0

Transmission Mechanical Condition

Trans Housing Condition	2.0
Tran Lines Condition	2.0
Trans Fluid Condition	2.0
Trans Fluid Leaks Condition	2.0
Trans Cooler Condition	2.0
Trans Shifter Condition	2.0
Section Condition Grade	2.0

Section Notes: ENGINE AND TRANSMISSION IN VERY GOOD CONDITION. THE ENGINE AND TRANSMISSION SERIAL NUMBERS MATCH THE VEHICLE BUILD INFORMATION.

Brakes Mechanical Condition

Front Brake Material	2.0
Front Brake Rotors / Drums	2.0
Rear Brake Material	2.0
Rear Brake Rotors / Drums	2.0
Brake Lines Condition	2.0
Parking Brake Operation	2.0
Section Condition Grade	2.0

Steering Mechanical Condition

Rack-n-Pinion Condition	NA
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	2.0
Alignment Condition	2.0
Section Condition Grade	2.0

Section Notes: BRAKES ARE IN GOOD CONDITION. STEERING TIGHT AS DESIGNED.

Suspension Mechanical Condition

Front Shocks Condition	3.0
Rear Shocks Condition	3.0
Bushings Condition	3.0
Sway Bar Links Condition	3.0
Suspension Control Condition	3.0
Control Arms Condition	3.0
Section Condition Grade	3.0

Electrical Systems Condition

Diagnostic Trouble Codes Present	NO
Check Engine Light On / Off	OFF
Airbag Light On / Off	OFF
ABS Light On / Off	OFF
Wiring Condition	4.0
Battery Condition	3.0
Section Condition Grade	3.5

Section Notes: SUSPENSION AND ELECTRICAL SYSTEM IN GOOD CONDITION. WIRING COULD BE BETTER IN SEVERAL PLACES THROUGHOUT THE CAR

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	2.0
Firewall Repair / Condition	5.0
Floor Pans Repair / Condition	6.0
Apron Repair / Condition	2.0
Inner Quarter Repair / Condition	6.0
Frame Rail Repair / Condition	3.0
Rocker Panel Repair / Condition	4.0
Section Condition Grade	4.0

Conventional Frame Condition

Frame Rail Repair / Condition	2.0
Cross Member Repair / Condition	3.0
Radiator Core Repair / Condition	2.0
Trunk Pan Repair / Condition	6.0
Spring Pod Repair / Condition	2.0
Torque Box Repair / Condition	2.0
Wheel House Repair / Condition	2.0
Section Condition Grade	2.7

Section Notes: LARGE SECTIONS CUT OUT AND SHEET METAL APPLIED OVER HOLES IN FLOOR AND TRUNK PANS. WELDS ARE NOT VERY GOOD HOWEVER SEEM TO HOLD. FIREWALL HAS HAD SOME REPAIRS TO LOWER SIDE AS

Test Drive Results

Acceleration	3.0
Shifting	3.0
Steering	3.0
Braking	3.0
Ride / Handling	NA
Rattles / Noises	NA
Warning Lights	NA

Section Condition Grade 3.0

Condition Summary

Body	3.3
Interior	3.1
Features / Options	2.0
Mechanical	2.0
Electrical	2.0
Structural	3.4
Test Drive	3.0

Overall Vehicle Grade 2.7

Section Notes: VEHICLE WAS NOT TEST DRIVEN DUE TO DEALER REPRESENTATIVE BEING IN A LONG MEETING. VEHICLE WAS MOVED FORWARD AND BACKWARD AND WATCHED IN THE PARKING LOT.

Inspectors Notes: THIS VEHICLE IS NOT A RESTORED VEHICLE. IT SHOWS MANY AREAS FOR IMPROVEMENT AND SEVERAL NON-PROFESSIONAL REPAIRS. THIS IS A CANDIDATE FOR A FRAME OFF REQUIRING A LOT OF WORK.