



WWW.  
**TESTDRIVETECH**  
VEHICLE INSPECTION SERVICES .COM

St Rose, Illinois 62230

[www.TestDriveTech.com](http://www.TestDriveTech.com)

Phone: 636-388-8378

Email: [info@testdrivetech.com](mailto:info@testdrivetech.com)

# TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



## Vehicle Identification

Inspection Date: 7/18/2017

VIN 124378N458509	Trim: SS 350
Year: 1968	Vehicle Type: COUPE
Make: CHEVROLET	Number of Doors: 2
Model: CAMARO	Engine Size: 350 CID
Mileage: 5879	Transmission Type: 3 SPEED AUTO
Hours: NA	Driveline Type: RWD

**Section Notes:** MILEAGE TAKEN FROM ODOMETER - WE CAN NOT GUARANTEE TRUE MILEAGE.

How Each  
Inspection Section Is  
Graded

*Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.*

## Left Side Body Condition

## Right Side Body Condition

Left Front Fender	2.0	Right Front Fender	2.0
Left Windshield A-Pillar	3.0	Right Windshield A-Pillar	3.0
Left Front Door	2.0	Right Front Door	2.0
Left Center B-Pillar	NA	Right Center B-Pillar	NA
Left Rear Door	NA	Right Rear Door	NA
Left C-Pillar	2.0	Right C-Pillar	2.0
Left Quarter Panel	2.0	Right Quarter Panel	2.0
<b>Section Condition Grade</b>	<b>2.2</b>	<b>Section Condition Grade</b>	<b>2.2</b>

**Section Notes:** BODY HAS BEEN WELL RESTORED. NEW QUARTERS, NEW FENDERS, NEW OUTER ROCKERS, GOOD SHUTTINGS AND PANEL ALIGNMENTS. A BIT OF SANDING MARKS IN FRONT AND REAR GLASS PILLARS AND ROOF BUT HARDLY NOTICEABLE UNLESS YOU ARE UP ON IT.

### Front Body Condition

Hood	2.0
Front Bumper	3.0
Headlamps	2.0
Windshield Cowl	2.0
Front Roof Top	3.0
Section Condition Grade	2.4

### Rear Body Condition

Trunk	3.0
Rear Bumper	2.0
Tail Lamps	2.0
Deck Cowl	2.0
Rear Roof Top	3.0
Section Condition Grade	2.4

**Section Notes:** BODY HAS BEEN WELL RESTORED. NEW QUARTERS, NEW FENDERS, NEW OUTER ROCKERS, GOOD SHUTTINGS AND PANEL ALIGNMENTS. A BIT OF SANDING MARKS IN FRONT AND REAR GLASS PILLARS AND ROOF BUT HARDLY NOTICEABLE UNLESS YOU ARE UP ON IT.

### Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	3.0
Steering Wheel Condition	2.0
Driver Seat Condition	2.0
Passenger Seat Condition	2.0
Front Carpet Condition	2.0
Left Front Door Panel	2.0
Left Rear Door Panel	NA
Cargo Interior Sides	2.0
Section Condition Grade	2.1

### Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	2.0
Rear Deck Condition	2.0
Rear Carpet Condition	2.0
3rd Seat Condition	NA
Right Front Door Panel	2.0
Right Rear Door Panel	NA
Cargo Floor & Roof	2.0
Section Condition Grade	2.0

**Section Notes:** DASH PAD COULD BE WRAPPED BETTER BUT IT IS OK. INTERIOR IS IN VERY GOOD CONDITION. ADDITIONAL GAUGES INSTALLED NEAR CENTER CONSOLE. SUN VISORS ARE IN REAR FLOOR NOT INSTALLED.

### Tire Condition

Tire Brand	HERCULES
Front Tire Size	215/65R15
Left Front Tire Tread	2.0
Right Front Tire Tread	2.0
Rear Tire Size	235/60R15
Left Rear Tire Tread	2.0
Right Rear Tire Tread	2.0
Section Condition Grade	2.0

### Wheel Condition

Wheel Type	STEAL WITH TRIM RINGS
Left Front Wheel Condition	3.0
Right Front Wheel Condition	3.0
Left Rear Wheel Condition	3.0
Right Rear Wheel Condition	3.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	NO
Section Condition Grade	3.0

**Section Notes:** TIRES ARE IN GOOD CONDITION. WHEELS LOOK GOOD. BEAUTY RINGS SHOW SOME LIGHT SCRATCHES AND COULD USE SOME POLISHING.

**Interior Option Operation**

Left Front Seat Operation	2.0
Right Front Seat Operation	2.0
Rear Seat Operation	NA
3rd Seat Operation	NA
Stereo Operation	2.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	YES
Section Condition Grade	NA

**Exterior Option Operation**

Left Front Window Operation	2.0
Right Front Window Operation	2.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Cargo Door Operation	2.0
Door Locks Operation	2.0
Windshield Wiper Operation	2.0
Rear Defrost Operation	NA
Section Condition Grade	2.0

Section Notes: FACTORY RADIO REPLACED WITH AFTERMARKET AS WELL AS SPEAKERS.  
AFTERMARKET VINTAGE AC INSTALLED AND WORKS WELL.

**Interior Lighting Condition**

Dash Lamps Operation	2.0
Interior Lighting Operation	2.0
Map Lights Operation	2.0
Dome Lights Operation	2.0
Hood Lamp Operation	NA
Seat Belt Light Operation	NA
Section Condition Grade	2.0

**Exterior Lighting Condition**

Low Beam Head Light Operation	2.0
High Beam Head Light Operation	2.0
Parking Lamp Operation	2.0
4-Way Flasher Operation	2.0
Left Turn Operation	2.0
Right Turn Operation	2.0
Section Condition Grade	2.0

Section Notes: LIGHTS WORKING WELL. WIRING IN GOOD CONDITION.

**Engine Mechanical Condition**

Engine Block Condition	2.0
Engine Hoses Condition	2.0
Engine Oil Leaks	2.0
Fuel Leaks	1.0
Air Filter Condition	2.0
Radiator Condition	2.0
Section Condition Grade	1.8

**Transmission Mechanical Condition**

Trans Housing Condition	2.0
Tran Lines Condition	2.0
Trans Fluid Condition	2.0
Trans Fluid Leaks Condition	1.0
Trans Cooler Condition	2.0
Trans Shifter Condition	2.0
Section Condition Grade	1.8

Section Notes: ENGINE AND TRANSMISSION ARE IN GOOD CONDITION. GOOD  
POWER, SOLID SHIFTS, GOOD OIL PRESSURE AND STEADY TEMP.

**Brakes Mechanical Condition**

Front Brake Material	2.0
Front Brake Rotors / Drums	2.0
Rear Brake Material	2.0
Rear Brake Rotors / Drums	2.0
Brake Lines Condition	2.0
Parking Brake Operation	2.0
Section Condition Grade	2.0

**Steering Mechanical Condition**

Rack-n-Pinion Condition	NA
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	2.0
Alignment Condition	2.0
Section Condition Grade	2.0

**Section Notes:** BRAKES STOP WELL WITHOUT PULLING. STEERING FEELS TIGHT AND SOLID NO PULLING.

**Suspension Mechanical Condition**

Front Shocks Condition	2.0
Rear Shocks Condition	2.0
Bushings Condition	2.0
Sway Bar Links Condition	2.0
Suspension Control Condition	2.0
Control Arms Condition	2.0
Section Condition Grade	2.0

**Electrical Systems Condition**

Diagnostic Trouble Codes Present	NO
Check Engine Light On / Off	OFF
Airbag Light On / Off	OFF
ABS Light On / Off	OFF
Wiring Condition	2.0
Battery Condition	2.0
Section Condition Grade	2.0

**Section Notes:** SUSPENSION AND ELECTRICAL SYSTEM IN GOOD CONDITION.

**Unibody Frame Condition**

A,B,C,D Pillar Repair / Condition	2.0
Firewall Repair / Condition	2.0
Floor Pans Repair / Condition	3.0
Apron Repair / Condition	3.0
Inner Quarter Repair / Condition	3.0
Frame Rail Repair / Condition	3.0
Rocker Panel Repair / Condition	3.0
Section Condition Grade	2.7

**Conventional Frame Condition**

Frame Rail Repair / Condition	3.0
Cross Member Repair / Condition	3.0
Radiator Core Repair / Condition	3.0
Trunk Pan Repair / Condition	2.0
Spring Pod Repair / Condition	3.0
Torque Box Repair / Condition	6.0
Wheel House Repair / Condition	3.0
Section Condition Grade	3.3

**Section Notes:** UNDERCARRIAGE IS IN GOOD CONDITION. IT HAS BEEN WELL RESTORED IN THE LAST SEVERAL YEARS. TRUNK PAN WAS REPLACED AND SHOWS QUALITY SEAMS. FLOORS ARE SOLID AND FRAME RAILS ARE GOOD.

## Test Drive Results

Acceleration	2.0
Shifting	2.0
Steering	2.0
Braking	2.0
Ride / Handling	2.0
Rattles / Noises	2.0
Warning Lights	1.0
<b>Section Condition Grade</b>	<b>1.9</b>

## Condition Summary

Body	2.4
Interior	2.1
Features / Options	2.0
Mechanical	2.0
Electrical	2.0
Structural	3.0
Test Drive	1.9
<b>Overall Vehicle Grade</b>	<b>2.2</b>

**Section Notes:** GOOD POWER, SOLID SHIFTS, STEERS WELL AND STOPS WELL.

**Inspectors Notes:** VEHICLE SHOWS A PROFESSIONAL RESTORATION AND BODY WORK AND TO BE A NICE SOLID CAR. IT HAS BEEN WELL MAINTAINED AND COULD USE A FEW AREAS FRESHENED UP FOR ADDITIONAL POINTS BUT OVERALL A VERY NICE CLEAN SOLID CAR.