



17715 St Rose Road  
St Rose, Illinois 62230  
[www.TestDriveTech.com](http://www.TestDriveTech.com)  
Phone: 636-388-8378  
Email: [info@testdrivetech.com](mailto:info@testdrivetech.com)

# TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



**Inspection Date:** 7/20/2017

## Vehicle Identification

**VIN:** 18XF4CC24X1172082  
**Year:** 1999  
**Make:** WESTERN  
**Model:** ALPINE  
**Mileage:** 108720  
**Gen Hours:** 270  
**Trim:** AMS 36' FDS  
**Vehicle Type:** MOTORHOME  
**Number of Doors:** 1  
**Engine Size:** ISC-330E RV  
**Transmission Type:** AUTO  
**Driveline Type:** RWD

## Condition Summary

Chassis Body	2.9
Chassis Electrical	2.7
Chassis Mechanical	2.9
Coach Structural	3.0
Coach Body / Interior	2.2
Coach Electrical	2.5
Coach HVAC / Plumbing	2.6
Coach Appliances / Options	3.0
Test Drive	2.7
<b>Overall Vehicle Grade</b>	<b>2.7</b>

### How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

## Class A RV Chassis Inspection

### What We Are Inspecting In This Section.

"Chassis" in this section refers to what powers and moves your coach. The Chassis is the workhorse of your RV which includes the engine, transmission and other mechanicals as well as basic structure and body of your motorhome.

### Left Side Body Condition

Left Front	3.0
Left Side	3.0
Left Storage Doors	4.0
Left Windows	3.0
Left Roof	3.0
Left Slide	3.0
Left Rear	3.0

**Section Condition Grade** 3.1

### Right Side Body Condition

Right Front	3.0
Right Side	3.0
Right Storage Doors	4.0
Right Windows	3.0
Right Roof	3.0
Right Slide	NA
Right Rear	3.0

**Section Condition Grade** 3.2

**Section Notes:** SOME AREAS AROUND BUMPERS HAVE SLIGHT CRACKS IN THEM. THE STORAGE DOORS NEED ADJUSTED AND LIKELY A COUPLE NEW LATCHES

**Front Body Condition**

Generator Door	3.0
Front Bumper	3.0
Headlamp Lens	2.0
Front Body Panel	3.0
Front Roof Top	3.0
Section Condition Grade	2.8

**Rear Body Condition**

Cargo Doors	4.0
Rear Bumper	3.0
Tail Lamp Lens	3.0
Rear Body Panel	3.0
Rear Roof Top	3.0
Section Condition Grade	3.2

Section Notes: GENERATOR SLIDE DOOR STICKS SLIGHTLY ON PASS SIDE BUT WORKS OK. CARGO DOORS ARE LOOSE BUT HOLD OPEN WELL.

**Front Interior Condition**

Front Seat Type	CAPTAINS
Dashboard Condition	3.0
Steering Wheel Condition	3.0
Driver Seat Condition	3.0
Passenger Seat Condition	3.0
Front Carpet Condition	3.0
Section Condition Grade	3.0

**Rear Interior Condition**

Rear Seat Type	NA
3rd Seat Present	NA
Rear Seat Condition	NA
Rear Deck Condition	NA
Rear Carpet Condition	NA
3rd Seat Condition	NA
Section Condition Grade	NA

Section Notes: CLEAN AND WELL CARED FOR HOWEVER CARPET AND TRIM SHOW ITS AGE

**Tire Condition**

Tire Manufacture	GOODYEAR
Tire Manufacture Date	30TH DAY OF 2010
Front Tire Size	295/75R22.5
Left Steer Tire Tread	3.0
Right Steer Tire Tread	3.0
Rear Tire Size	3.0
LRI Tire Tread	3.0
LRO Tire Tread	3.0
LI Tag Axle Tire Tread	NA
LO Tag Axle Tire Tread	NA
RFI Tire Tread	3.0
RFO Tire Tread	3.0
RI Tag Axle Tire Tread	NA
RO Tag Axle Tire Tread	NA
Section Condition Grade	3.0

**Wheel Condition**

Wheel Type	ALUMINUM
Left Steer Wheel Condition	2.0
Right Steer Wheel Condition	2.0
LRI Wheel Condition	2.0
LRO Wheel Condition	2.0
LI Tag Wheel Condition	NA
LO Tag Wheel Condition	NA
RRI Wheel Condition	2.0
RRO Wheel Condition	2.0
RI Tag Wheel Condition	NA
RO Tag Wheel Condition	NA
Cracks or Welds in Wheels	NO
All Studs & Lug Nuts Present	YES
Section Condition Grade	2.0

Section Notes: TIRES HAVE GOOD TREAD ON THEM. THEY DO SHOW DATE CODES FROM 30TH DAY IN 2010 MAKING THEM OVER 7 YEARS OLD. REPLACEMENT RECOMMENDED AT 5-6 YEARS - TIRES ARE SEMI TRUCK TIRES

### Interior Option Operation

Left Front Seat Operation	3.0
Right Front Seat Operation	3.0
Rear Seat Operation	NA
Stereo Operation	3.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	NA
Fire Extinguisher Present	YES
Section Condition Grade	3.0

### Exterior Option Operation

Left Front Window Operation	3.0
Right Front Window Operation	3.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Generator Door Operation	3.0
Door Locks Operation	3.0
Windshield Wiper Operation	3.0
Rear Wiper Operation	NA
Section Condition Grade	3.0

Section Notes: SEATS, LOCKS AND WINDOWS OPERATING AS DESIGNED. GENERATOR DOOR STICKS SLIGHTLY

### Interior Lighting Condition

Dash Lamps Operation	2.0
Interior Lighting Operation	2.0
Map Lights Operation	2.0
Dome Lights Operation	2.0
Cargo Lamp Operation	2.0
Seat Belt Light Operation	NA
Section Condition Grade	2.0

### Exterior Lighting Condition

Low Beam Head Light Operation	2.0
High Beam Head Light Operation	2.0
Parking Lamp Operation	5.0
4-Way Flasher Operation	2.0
Left Turn Operation	2.0
Right Turn Operation	2.0
Section Condition Grade	2.5

Section Notes: REAR UPPER MARKER LAMPS INOP AND DAMAGED NEED REPAIRED. RR TAIL LAMP HOUSING LOOSE IN BODY BUT HOLDING.

### Engine Mechanical Condition

Engine Block Condition	3.0
Engine Hoses Condition	3.0
Engine Oil Condition	3.0
Oil Leaks Condition	4.0
Air Filter Condition	3.0
Radiator Condition	3.0
Section Condition Grade	3.2

### Transmission Mechanical Condition

Trans Housing Condition	3.0
Tran Lines Condition	3.0
Trans Fluid Condition	3.0
Trans Fluid Leaks Condition	1.0
Trans Cooler Condition	3.0
Power Take Off (PTO) Condition	NA
Section Condition Grade	2.6

Section Notes: ENGINE AND TRANSMISSION AREA ARE IN GOOD CONDITION. RUNS STRONG, SMOOTH AND SHIFTS WELL. FLUIDS CLEAN. LEAK AT EXHAUST MANIFOLD AND TURBO (NEEDS GASKET REPLACED)

**Brakes Mechanical Condition**

Front Brake Material	3.0
Front Brake Rotors / Drums	3.0
Rear Brake Material	3.0
Rear Brake Rotors / Drums	3.0
Brake Lines Condition	3.0
Parking Brake Operation	2.0
Section Condition Grade	2.8

**Air Brakes Condition**

Front Brake Chambers	3.0
Intermediate Brake Chambers	3.0
Rear Brake Chambers	3.0
Governor Operation	3.0
Purge Valve Operation	3.0
Air Compressor Operation	3.0
Section Condition Grade	3.0

Section Notes: BRAKES ARE IN GOOD CONDITION AS WELL AS THE AIR SYSTEM.

**Suspension Mechanical Condition**

Front Shocks Condition	3.0
Rear Shocks Condition	3.0
Bushings Condition	3.0
Track Bar Links Condition	3.0
Suspension Control Condition	3.0
Kingpins Condition	3.0
Section Condition Grade	3.0

**Air Suspension Systems Condition**

Leveling Valve Condition	3.0
Air Dump Valve Operation	3.0
Front Air Bags Condition	3.0
Rear / Tag Air Bags Condition	NA
Air Lines Condition	3.0
Repairs / Splices in Lines	YES
Section Condition Grade	3.0

Section Notes: MECHANICAL SUSPENSION AND AIR RIDE ARE IN GOOD CONDITON

**Steering Mechanical Condition**

Rack-n-Pinion Condition	NA
Tie Rods Condition	3.0
Steering Linkage Condition	3.0
Steering Column Condition	3.0
Pump / Gearbox Condition	3.0
Alignment Condition	2.0
Section Condition Grade	2.8

**Electrical Systems Condition**

Diagnostic Trouble Codes Present	NO
Check Engine Light On / Off	OFF
Airbag Light On / Off	NA
ABS Light On / Off	OFF
Wiring Condition	3.0
Misc. Wires in Fuse Box Y/N	NO
Section Condition Grade	3.0

Section Notes: STEERING SEEMS A BIT TIGHT ABOUT 50% OF TURN BUT ONCE MOVING IS EASIER (LIKELY FROM LACK OF USE) AND ELECTRICAL SYSTEM IN GOOD CONDITION

### Conventional Frame Condition

Frame Rails Condition	3.0
Front Cross Member	3.0
Engine Cross Member	3.0
Transmission Cross Member	3.0
Cab Cross Member	3.0
Intermediate Cross Member	3.0
Rear Cross Member	3.0
Section Condition Grade	3.0

### Conventional Frame Condition

Welds on Frame Rails	NO
Cuts on Frame Rails	NO
Missing Bolts on Frame Rails	NO
Corrosion on Frame Rails	NO
Damaged Cross Members	NO
Corrosion on Cross Members	NO
Proper Fasteners on Cross Members	YES
Section Condition Grade	NA

Section Notes: FRAME IN GOOD CONDITION

## Class A RV Coach Inspection

What We Are  
Inspecting In This  
Section.

"Coach" in this section refers to what is often called the "House" of your motorhome. This is where you mostly live in your RV when you are not driving it. This section covers the living area, kitchen, appliances, body of the motorhome and the major plumbing and electrical systems.

### Interior Coach Condition

Counter Condition	3.0
Flooring Condition	3.0
Doors / Walls Condition	4.0
Trim / Drapery Condition	3.0
Upholstery / Seating Condition	3.0
Cabinetry Condition	3.0
Section Condition Grade	3.2

### Coach Exterior

Roof Condition	3.0
Roof Seals / Sealant Condition	3.0
Left Side Coach Body	3.0
Windows Condition	3.0
Storage Doors Condition	4.0
Entry Door Condition	3.0
Section Condition Grade	3.2

Section Notes: INTERIOR SHOWS AGE AS EXPECTED. COACH EXTERIOR SHOWS AGE, ROOF HAS SOME REPAIRS AND LOOKS MAINTAINED BUT SOME SEALANT COULD USE REPLACEMENT.

### Coach Lighting Condition

12 Volt Lighting Condition	3.0
110 Volt Lighting Condition	3.0
Switches Condition	3.0
Accessory Lighting Condition	3.0
Awning Light Condition	3.0
Storage Lighting Condition	3.0
Section Condition Grade	3.0

### Appliances Condition

Heater Condition	3.0
Air Conditioning Condition	3.0
Stove / Oven Condition	3.0
Microwave Condition	5.0
Refrigerator Condition	2.0
TV / Stereo Condition	3.0
Section Condition Grade	3.2

Section Notes: APPLIANCES OPERATE AS DESIGNED, MICROWAVE FACE BROKEN. SOME 12V LIGHTS NEED NEW BULBS AS THE FILIMENTS ARE GOING BAD.

**Generator Condition**

Visible Leaks Present	<b>NO</b>
Run for 30 Minutes	<b>YES</b>
Oil Level Condition	<b>2.0</b>
Oil Condition	<b>2.0</b>
Starting Condition	<b>3.0</b>
Shutdown Condition	<b>3.0</b>

Section Condition Grade **2.5**

**Plumbing Condition**

Visible Leaks Present	<b>YES</b>
12 Volt Pump Operation	<b>2.0</b>
Holding Tank Gauge Operation	<b>2.0</b>
Sinks / Shower / Toilet Condition	<b>2.0</b>
Grey / Black Water Valve Condition	<b>2.0</b>
Fresh Water Inlets Condition	<b>2.0</b>

Section Condition Grade **2.0**

**Section Notes:** GENERATOR STARTED EASY. POWERED ALL OF HOUSE. PLUMBING IN GOOD CONDITION. WATER PUMP HOWEVER DOES NOT HAVE MUCH PRESSURE.

**Slides / Awning Condition**

Number of Slideouts	<b>1</b>
Number of Awnings	<b>2</b>
Slide Outs Operation	<b>3.0</b>
Slide Out Seals Condition	<b>3.0</b>
Awning Operation	<b>3.0</b>
Awning Condition	<b>1.0</b>

Section Condition Grade **2.5**

**Coach Electrical Condition**

House Batteries Condition	<b>2.0</b>
Voltage Gauge Operation	<b>2.0</b>
Shore Power Condition	<b>NA</b>
Power Cords Condition	<b>2.0</b>
Generator Operation	<b>2.0</b>
Inverter Operation	<b>2.0</b>

Section Condition Grade **2.0**

SLIDEOUT COVER IS SHOWING AGE AND CRACKING. SLIDE SEALS ARE

**Section Notes:** SHOWING AGE AND WILL NEED REPLACED IN A YEAR OR SO. HOUSE BATTERIES SHOW 12.6 VOLTS TOTAL AND CHASSIS SHOW 13.4 VOLTS

**Coach Safety Condition**

Any Smell of Exhaust in Cabin	<b>NO</b>
Fire Extinguisher Condition	<b>1.0</b>
Gas Monitor Condition	<b>1.0</b>
Carbon Monoxide Alarm Condition	<b>1.0</b>
Smoke Detector Condition	<b>1.0</b>
Lock-Outs Operation	<b>1.0</b>

Section Condition Grade **1.0**

**Leveling System Condition**

System Type	<b>JACKS</b>
Hydraulic Fluid Level	<b>3.0</b>
Hydraulic Fluid Condition	<b>3.0</b>
Self Leveling Operation	<b>3.0</b>
Jacks Operation	<b>3.0</b>
Control Panel Operation	<b>3.0</b>

Section Condition Grade **3.0**

**Section Notes:** SAFETY DEVICES CHECKED AND OK. LEVELING SYSTEM WORKING AS DESIGNED BUT A BIT SLOW TO GO INTO TRAVEL MODE (BE PATIENT)

**Test Drive Results**

Acceleration	3.0
Shifting	3.0
Steering	3.0
Braking	3.0
Ride / Handling	3.0
Rattles / Noises	3.0
Warning Lights	1.0

**Section Condition Grade**                      **2.7**

**Inspectors Notes:**

VEHICLE HAS BEEN WELL CARED FOR. CLEAN.  
RUNS WELL. APPLIACNES ARE WORKING AS  
DESIGNED. OVERALL A VERY GOOD COACH  
JUST NEEDS SOME TLC AND SIMPLE REPAIRS.

**Section Notes:** VEHICLE TEST DROVE NICELY. GOOD POWER, SMOOTH SHIFTS. GOOD  
HANDLING. STEERING IS GOOD. BRAKING IS GOOD.