



www.
TESTDRIVETECH
VEHICLE INSPECTION SERVICES .COM

St Rose, Illinois 62230

www.TestDriveTech.com

Phone: 636-388-8378

Email: info@testdrivetech.com

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 7/5/2017

VIN: JHMCN36485C009947	Trim: HYBRID
Year: 2005	Vehicle Type: SEDAN
Make: HONDA	Number of Doors: 4
Model: ACCORD	Engine Size: 4 CYL
Mileage: 141491	Transmission Type: AUTO
Hours: NA	Driveline Type: FWD

How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

Left Front Fender	4.0	Right Front Fender	4.0
Left Windshield A-Pillar	4.0	Right Windshield A-Pillar	4.0
Left Front Door	4.0	Right Front Door	4.0
Left Center B-Pillar	4.0	Right Center B-Pillar	4.0
Left Rear Door	4.0	Right Rear Door	4.0
Left C-Pillar	4.0	Right C-Pillar	4.0
Left Quarter Panel	4.0	Right Quarter Panel	4.0
Section Condition Grade	4.0	Section Condition Grade	4.0

Section Notes: PAINT AND BODY OF VEHICLE ARE IN MOSTLY GOOD CONDITION BUT SHOW MILEAGE AND AGE.

Front Body Condition

Hood	4.0
Front Bumper	4.0
Headlamps	4.0
Windshield Cowl	4.0
Front Roof Top	4.0
Section Condition Grade	4.0

Rear Body Condition

Trunk	4.0
Rear Bumper	4.0
Tail Lamps	4.0
Deck Cowl	4.0
Rear Roof Top	4.0
Section Condition Grade	4.0

Section Notes: PAINT AND BODY OF VEHICLE ARE IN GOOD CONDITION BUT SHOW MILEAGE AND AGE. HEADLAMPS ARE FADED AND NEED RESTORED.

Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	4.0
Steering Wheel Condition	4.0
Driver Seat Condition	4.0
Passenger Seat Condition	4.0
Front Carpet Condition	4.0
Section Condition Grade	4.0

Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	4.0
Rear Deck Condition	4.0
Rear Carpet Condition	4.0
3rd Seat Condition	NA
Section Condition Grade	4.0

Section Notes: INTERIOR IS IN FAIR CONDITION. HAS SMOKE ODOR TO IT. SHOWS AGE AND LACK OF DETAILING

Tire Condition

Tire Manufacture	MICHELIN
Front Tire Size	215/60R16
Left Front Tire Tread	3.0
Right Front Tire Tread	3.0
Rear Tire Size	215/60R16
Left Rear Tire Tread	3.0
Right Rear Tire Tread	3.0
Section Condition Grade	3.0

Wheel Condition

Wheel Type	ALLOY
Left Front Wheel Condition	4.0
Right Front Wheel Condition	4.0
Left Rear Wheel Condition	4.0
Right Rear Wheel Condition	4.0
Spare Tire / Wheel Present	NA
Jack / Emergency Tools Present	YES
Section Condition Grade	4.0

Section Notes: TIRES HAVE ABOUT 50%. WHEELS ARE SCRATCHED AND SCUFFED.

Interior Option Operation

Left Front Seat Operation	3.0
Right Front Seat Operation	3.0
Rear Seat Operation	3.0
3rd Seat Operation	NA
Stereo Operation	3.0
Navigation Operation	NA
Front Seat Belts Present	3.0
Rear Seat Belts Present	3.0
Section Condition Grade	3.0

Exterior Option Operation

Left Front Window Operation	3.0
Right Front Window Operation	3.0
Left Rear Window Operation	3.0
Right Rear Window Operation	3.0
Cargo Door Operation	3.0
Door Locks Operation	3.0
Windshield Wiper Operation	3.0
Rear Wiper Operation	NA
Section Condition Grade	3.0

Section Notes: ALL FEATURES AND OPTIONS WORKING. SHOW AGE AND USE.

Interior Lighting Condition

Dash Lamps Operation	1.0
Interior Lighting Operation	1.0
Map Lights Operation	1.0
Dome Lights Operation	1.0
Cargo Lamp Operation	NA
Seat Belt Light Operation	1.0
Section Condition Grade	1.0

Exterior Lighting Condition

Low Beam Head Light Operation	1.0
High Beam Head Light Operation	1.0
Parking Lamp Operation	1.0
4-Way Flasher Operation	1.0
Left Turn Operation	1.0
Right Turn Operation	1.0
Section Condition Grade	1.0

Section Notes: ALL LIGHTS WORKING. DASH SELF TEST LIGHTS WORKING AS WELL.

Engine Mechanical Condition

Engine Block Condition	3.0
Engine Hoses Condition	3.0
Engine Oil Condition	3.0
Oil Leaks Condition	3.0
Air Filter Condition	4.0
Radiator / Coolant Condition	3.0
Section Condition Grade	3.2

Transmission Mechanical Condition

Trans Housing Condition	3.0
Tran Lines Condition	3.0
Trans Fluid Condition	3.0
Trans Fluid Leaks Condition	3.0
Trans Cooler Condition	3.0
Trans Shifter Condition	3.0
Section Condition Grade	3.0

Section Notes: ENGINE AND TRANSMISSION ARE IN GOOD CONDITION, HYBRID SYSTEM IS WORKING HOWEVER THE VEHICLE SHOWS SIGNS OF THE ANC MALFUNCTIONING CAUSING A LOUD RUMBLE IN THE COCKPIT.

Brakes Mechanical Condition

Front Brake Material	3.0
Front Brake Rotors / Drums	3.0
Rear Brake Material	3.0
Rear Brake Rotors / Drums	3.0
Brake Lines Condition	3.0
Parking Brake Operation	3.0
Section Condition Grade	3.0

Steering Mechanical Condition

Rack-n-Pinion Condition	3.0
Tie Rods Condition	3.0
Steering Linkage Condition	3.0
Steering Column Condition	3.0
Pump / Gearbox Condition	3.0
Alignment Condition	3.0
Section Condition Grade	3.0

Section Notes: BRAKES HAVE ABOUT 50% LIFE. STEERING OK

Suspension Mechanical Condition

Front Shocks Condition	3.0
Rear Shocks Condition	3.0
Bushings Condition	3.0
Sway Bar Links Condition	3.0
Suspension Control Condition	3.0
Control Arms Condition	3.0
Section Condition Grade	3.0

Electrical Systems Condition

I= OFF / NO 6= YES / ON

Diagnostic Trouble Codes Present	6.0
Check Engine Light On / Off	1.0
Airbag Light On / Off	1.0
ABS Light On / Off	1.0
Wiring Condition	1.0
Misc. Wires in Fuse Box Y/N	1.0
Section Condition Grade	1.8

Section Notes: SUSPENSION LOOKS IN GOOD CONDITION. AVERAGE FOR THE MILEAGE ON VEHICLE. NO WARNING LIGHTS ON BUT CODES PRESENT BOTH MISFIRE AND BATTERY CODES PRESENT

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	3.0
Firewall Repair / Condition	3.0
Floor Pan Repair / Condition	3.0
Apron Repair / Condition	3.0
Inner Quarter Repair / Condition	3.0
Frame Rail Repair / Damage	3.0
Rocker Panel Repair / Condition	3.0
Section Condition Grade	3.0

Conventional Frame Condition

Frame Rail Repair / Condition	3.0
Cross Member Repair / Condition	3.0
Radiator Core Repair / Condition	3.0
Trunk Pan Repair / Condition	3.0
Spring Pod Repair / Condition	3.0
Torque Box Repair / Condition	3.0
Wheel House Repair / Condition	3.0
Section Condition Grade	3.0

Section Notes: STRUCTURE SOLID. NO REPAIRS FOUND.

Test Drive Results

Acceleration	3.0
Shifting	3.0
Steering	3.0
Braking	3.0
Ride / Handling	3.0
Rattles / Noises	6.0
Warning Lights	6.0
Section Condition Grade	3.9

Condition Summary

Body	4.0
Interior	4.0
Features / Options	3.0
Mechanical	2.6
Electrical	1.3
Structural	3.0
Test Drive	3.9
Overall Vehicle Grade	3.1

Section Notes: NOISE FROM HYBRID SYSTEM, DRIVES AS DESIGNED. SHOWS AGE AND MILEAGE.

Inspectors Notes: CAR SHOWS ITS AGE AND MILEAGE AND LIKELY NEEDS ROUTINE MAINTENANCE AND FRESHING OF VEHICLE. HEAVY DETAIL NEEDED.