



17715 St Rose Road
St Rose, Illinois 62230
www.TestDriveTech.com
Phone: 636-388-8378
Email: info@testdrivetech.com

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 8/22/2017

VIN: 3035201
Year: 1963
Make: FORD
Model: ROADSTER
Mileage: 37187 (TMU)
Hours: NA

Trim: CONVERTIBLE
Vehicle Type: STREET ROD
Number of Doors: 2
Engine Size: V8
Transmission Type: 3 SPEED W/OD
Driveline Type: RWD

VIN / SERIAL NUMBER NOT AFFIXED TO VEHICLE. VIN WAS OBTAINED FROM PAPERWORK FOUND IN VEHICLE. TRUE MILEAGE UNKNOWN

How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Left Front Fender	3.0
Left Windshield A-Pillar	3.0
Left Front Door	3.0
Left Center B-Pillar	3.0
Left Rear Door	NA
Left C-Pillar	NA
Left Quarter Panel	4.0
Section Condition Grade	3.2

Right Side Body Condition

Right Front Fender	4.0
Right Windshield A-Pillar	3.0
Right Front Door	4.0
Right Center B-Pillar	3.0
Right Rear Door	NA
Right C-Pillar	NA
Right Quarter Panel	4.0
Section Condition Grade	3.6

Section Notes: HEAVY FILLER FOUND THROUGHOUT BODY OF THE VEHICLE. FINISH IS SMOOTH AND STRAIGHT HOWEVER A MAGNETIC RULER WOULD NOT STICK ON THE MAJORITY OF THE BODY PANELS. MUCH OF THE PAINT IS THICK THUS CAUSING IT TO CRACK IN SEVERAL PLACES SHOWN IN PHOTOS.

Front Body Condition

Hood	4.0
Front Bumper	2.0
Headlamps	2.0
Windshield Cowl	2.0
Front Roof Top	2.0
Section Condition Grade	2.4

Rear Body Condition

Trunk	4.0
Rear Bumper	2.0
Tail Lamps	2.0
Deck Cowl	3.0
Rear Roof Top	2.0
Section Condition Grade	2.6

Section Notes: BUMPERS, LAMP HOUSINGS AND MOST OF THE TRIM HAVE BEEN REPLACED WITH AFTERMARKET PIECES. SOME ORIGINAL TRIM STILL REMAINS SUCH AS THE MIRROR BRACKETS, HINGES AND DOOR HANDLES. HOOD HAS CRACKED AND CHIPPED PAINT IN CENTER, REAR DECK (RUMBLE SEAT HATCH) HAS HEAVY PAINT IN CORNERS FLAKING OFF

Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	2.0
Steering Wheel Condition	2.0
Driver Seat Condition	2.0
Passenger Seat Condition	2.0
Front Carpet Condition	2.0
Left Front Door Panel	2.0
Left Rear Door Panel	NA
Cargo Interior Sides	2.0
Section Condition Grade	2.0

Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	2.0
Rear Deck Condition	NA
Rear Carpet Condition	2.0
3rd Seat Condition	NA
Right Front Door Panel	2.0
Right Rear Door Panel	NA
Cargo Floor & Roof	NA
Section Condition Grade	2.0

Section Notes: INTERIOR HAS BEEN WELL DONE. THE CENTER CONSOLE NEEDS SOME ADJUSTMENT AND REMOUNTING BUT THE SEATS LOOK NICE AND ARE MOUNTED GOOD. DASH IS WELL DONE.

Tire Condition

Tire Brand	BF GOODRICH
Front Tire Size	245/45R16
Left Front Tire Tread	5.0
Right Front Tire Tread	5.0
Rear Tire Size	255/50R16
Left Rear Tire Tread	5.0
Right Rear Tire Tread	5.0
Section Condition Grade	5.0

Wheel Condition

Wheel Type	CHROME ALLOY
Left Front Wheel Condition	2.0
Right Front Wheel Condition	2.0
Left Rear Wheel Condition	2.0
Right Rear Wheel Condition	2.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	NO
Section Condition Grade	2.0

Section Notes: TIRES NEED REPLACED. FRONT TIRES SHOW UNEVEN WEAR. REAR TIRES LOW ON TREAD. WHEELS LOOK GOOD AND CLEAN. SPARE TIRE IS OEM AND WILL NOT FIT CURRENT AXLE SETUP.

Interior Option Operation

Left Front Seat Operation	2.0
Right Front Seat Operation	2.0
Rear Seat Operation	NA
3rd Seat Operation	NA
Stereo Operation	6.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	YES

Section Condition Grade 3.3

Exterior Option Operation

Left Front Window Operation	NA
Right Front Window Operation	NA
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Rear Hatch Operation	2.0
Door Locks Operation	NA
Windshield Wiper Operation	3.0
Rear Defrost Operation	NA

Section Condition Grade 2.5

Section Notes: RADIO INOP. DOES NOT POWER ON.

Interior Lighting Condition

Dash Lamps Operation	2.0
Interior Lighting Operation	NA
Map Lights Operation	NA
Dome Lights Operation	NA
Hood Lamp Operation	NA
Seat Belt Light Operation	NA

Section Condition Grade 2.0

Exterior Lighting Condition

Low Beam Head Light Operation	2.0
High Beam Head Light Operation	2.0
Parking Lamp Operation	2.0
4-Way Flasher Operation	3.0
Left Turn Operation	3.0
Right Turn Operation	3.0

Section Condition Grade 2.5

Section Notes: LF MARKER / TURN LAMP NOT MOUNTED PROPERLY. RR TAILLAMP / TURN NOT OPERATING AT ALL. 4 WAY FLASHERS DO NOT OPERATE WITH PARKING LAMPS ON.

Engine Mechanical Condition

Engine Block Condition	2.0
Engine Hoses Condition	2.0
Engine Oil Leaks	3.0
Fuel Leaks	1.0
Air Filter Condition	2.0
Radiator Condition	2.0

Section Condition Grade 2.0

Transmission Mechanical Condition

Trans Housing Condition	2.0
Tran Lines Condition	2.0
Trans Fluid Condition	1.0
Trans Fluid Leaks Condition	2.0
Trans Cooler Condition	2.0
Trans Shifter Condition	2.0

Section Condition Grade 1.8

Section Notes: ENGINE IN TRANSMISISON IN GOOD CONDITION. ENGINE HAS LEAKING PASSENGER SIDE VALVE COVER IN THE REAR. IT IS DRIPPING DOWN PASSENGER SIDE OF BELLHOUSING.

Brakes Mechanical Condition

Front Brake Material	3.0
Front Brake Rotors / Drums	3.0
Rear Brake Material	3.0
Rear Brake Rotors / Drums	3.0
Brake Lines Condition	3.0
Parking Brake Operation	6.0
Section Condition Grade	3.5

Steering Mechanical Condition

Rack-n-Pinion Condition	3.0
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	2.0
Alignment Condition	3.0
Section Condition Grade	2.3

Section Notes: PARKING BRAKE CABLE NOT CONNECTED IN CENTER OF VEHICLE.
RACK-N-PINION HAS A SLIGHT LEAK ON THE INNER TIE ROD BOOT.
TIRES SHOW AN ALIGNMENT IS NEEDED BUT THE CAR STEERS STRAIGHT.

Suspension Mechanical Condition

Front Shocks Condition	2.0
Rear Shocks Condition	2.0
Bushings Condition	3.0
Sway Bar Links Condition	3.0
Suspension Control Condition	NA
Control Arms Condition	2.0
Section Condition Grade	2.4

Electrical Systems Condition

Diagnostic Trouble Codes Present	NA
Check Engine Light On / Off	OFF
Airbag Light On / Off	NA
ABS Light On / Off	ON
Wiring Condition	2.0
Battery Condition	2.0
Section Condition Grade	2.0

Section Notes: SOME WEAR AND AGE ON THE BUSHINGS BUT ALL STILL SOLID. ABS
WARNING LAMP ON BECAUSE THERE IS NO ABS SENSORS INSTALLED.

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	2.0
Firewall Repair / Condition	2.0
Floor Pans Repair / Condition	2.0
Apron Repair / Condition	2.0
Inner Quarter Repair / Condition	2.0
Frame Rail Repair / Condition	2.0
Rocker Panel Repair / Condition	2.0
Section Condition Grade	2.0

Conventional Frame Condition

Frame Rail Repair / Condition	2.0
Cross Member Repair / Condition	2.0
Radiator Core Repair / Condition	2.0
Trunk Pan Repair / Condition	2.0
Spring Pod Repair / Condition	2.0
Torque Box Repair / Condition	2.0
Wheel House Repair / Condition	2.0
Section Condition Grade	2.0

Section Notes: VEHICLE UNDERCARRIAGE HAS BEEN VERY WELL BUILT. FRAME IS WELL
BOXED, WELDS ARE VERY SOUND AND THE TUBULAR CROSSMEMBERS
AND SUPPORTS ARE WELL DESIGNED. THE UNDERSIDE OF THE BODY
HAS BEEN REPLACED WITH SOME CUSTOM PANELS AS WELL AS A REAR
ACCESS PANEL POINT FOR THE REAR END WHICH IS IN THE TRUNK PAN.

Test Drive Results

Acceleration	2.0
Shifting	2.0
Steering	2.0
Braking	2.0
Ride / Handling	3.0
Rattles / Noises	3.0
Warning Lights	5.0
Section Condition Grade	2.7

Condition Summary

Body	2.6
Interior	2.0
Features / Options	3.0
Mechanical	2.3
Electrical	3.0
Structural	2.0
Test Drive	2.7
Overall Vehicle Grade	2.5

Section Notes: VEHICLE DROVE AND PERFORMED WELL. LARGE VIBRATION IN TIRES FROM SITTING FOR A LONG PERIOD. NO PULLING, GOOD BRAKING, EASY SHIFTS AND GOOD POWER.

Inspectors Notes: VEHICLE IS IN GOOD CONDITION. IT IS A SOLID #3 CAR AND COULD BE A #2 IF SOME BODY AND PAINT WORK WERE PUT INTO IT.