



St Rose, Illinois 62230

[www.TestDriveTech.com](http://www.TestDriveTech.com)

Phone: 636-388-8378

Email: [info@testdrivetech.com](mailto:info@testdrivetech.com)

# TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



## Vehicle Identification

VIN: BN4L-0-31926  
Year: 1957  
Make: AUSTIN HEALEY  
Model: 100-6  
Mileage: 95558  
Hours: NA

## Inspection Date: 8/3/2017

Trim: NA  
Vehicle Type: COUPE  
Number of Doors: 2  
Engine Size: INLINE 6  
Transmission Type: 4 SPEED W/OD  
Driveline Type: RWD

### How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

## Left Side Body Condition

Left Front Fender	4.0
Left Windshield A-Pillar	4.0
Left Front Door	5.0
Left Center B-Pillar	3.0
Left Rear Door	NA
Left C-Pillar	NA
Left Quarter Panel	3.0
Section Condition Grade	3.8

## Right Side Body Condition

Right Front Fender	4.0
Right Windshield A-Pillar	3.0
Right Front Door	3.0
Right Center B-Pillar	3.0
Right Rear Door	NA
Right C-Pillar	NA
Right Quarter Panel	3.0
Section Condition Grade	3.2

**Section Notes:** HEAVY PRIMER FILLER FOUND THROUGHOUT THE MAJORITY OF THE CAR. A FEW DEEP SCRATCHES WHICH WILL NEED REPAINTED. LF DOOR HAS CRACKED PAINT UNDER DOOR HANDLE FROM THICK PAINT AND FILLER. PANELS LOOK STRAIGHT HOWEVER DOORS NEED ALIGNMENT AND ADJUSTED AS THEY ARE HITTING THE B-PILLAR.

### Front Body Condition

Hood	3.0
Front Bumper	4.0
Headlamps	3.0
Windshield Cowl	3.0
Front Roof Top	6.0
Section Condition Grade	3.8

### Rear Body Condition

Trunk	4.0
Rear Bumper	4.0
Tail Lamps	3.0
Deck Cowl	3.0
Rear Roof Top	6.0
Section Condition Grade	4.0

**Section Notes:** BUMPERS HAVE BEEN RECHROMED AND LOOK OK HOWEVER IT IS EASY TO SPOT SOME REWELDING ON THE BACK SIDE OF THEM. TRUNK PANEL SEEMS DO NOT LINE UP CORRECTLY BUT STILL CLOSES AND ROOF ASSEMBLY IS MISSING.

### Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	3.0
Steering Wheel Condition	6.0
Driver Seat Condition	3.0
Passenger Seat Condition	3.0
Front Carpet Condition	3.0
Left Front Door Panel	3.0
Left Rear Door Panel	NA
Cargo Interior Sides	3.0
Section Condition Grade	3.4

### Rear Interior Condition

Rear Seat Type	NA
3rd Seat Present	NA
Rear Seat Condition	4.0
Rear Deck Condition	NA
Rear Carpet Condition	3.0
3rd Seat Condition	NA
Right Front Door Panel	3.0
Right Rear Door Panel	NA
Cargo Floor & Roof	3.0
Section Condition Grade	3.3

**Section Notes:** INTERIOR SHOWS SOME AGE BUT IS STILL IN GOOD CONDITION. STEERING WHEEL IS CRACKED IN SEVERAL PLACES. REAR SEAT DOES NOT SECURELY LATCH IN PLACE.

### Tire Condition

Tire Brand	MICHELIN
Front Tire Size	175R15
Left Front Tire Tread	3.0
Right Front Tire Tread	3.0
Rear Tire Size	175R15
Left Rear Tire Tread	3.0
Right Rear Tire Tread	3.0
Section Condition Grade	3.0

### Wheel Condition

Wheel Type	CHROME SPOKES
Left Front Wheel Condition	3.0
Right Front Wheel Condition	3.0
Left Rear Wheel Condition	3.0
Right Rear Wheel Condition	3.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	YES
Section Condition Grade	3.0

**Section Notes:** TIRES IN AVERAGE CONDITION AND SHOW ABOUT 50% LIFE REMAINING. PROPER WEAR PATTERN. WHEELS IN GOOD CONDITION.

### Interior Option Operation

Left Front Seat Operation	3.0
Right Front Seat Operation	3.0
Rear Seat Operation	NA
3rd Seat Operation	NA
Stereo Operation	NA
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	YES
Section Condition Grade	3.0

### Exterior Option Operation

Left Front Window Operation	3.0
Right Front Window Operation	3.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Cargo Door Operation	4.0
Door Locks Operation	NA
Windshield Wiper Operation	3.0
Rear Defrost Operation	NA
Section Condition Grade	3.3

Section Notes: ALL FEATURES AND OPTIONS WORKING AS DESIGNED.

### Interior Lighting Condition

Dash Lamps Operation	3.0
Interior Lighting Operation	3.0
Map Lights Operation	NA
Dome Lights Operation	NA
Hood Lamp Operation	NA
Seat Belt Light Operation	NA
Section Condition Grade	3.0

### Exterior Lighting Condition

Low Beam Head Light Operation	3.0
High Beam Head Light Operation	3.0
Parking Lamp Operation	3.0
4-Way Flasher Operation	3.0
Left Turn Operation	3.0
Right Turn Operation	3.0
Section Condition Grade	3.0

Section Notes: ALL LIGHTS OPERATING AS DESIGNED.

### Engine Mechanical Condition

Engine Block Condition	4.0
Engine Hoses Condition	2.0
Engine Oil Leaks	3.0
Fuel Leaks	1.0
Air Filter Condition	2.0
Radiator Condition	2.0
Section Condition Grade	2.3

### Transmission Mechanical Condition

Trans Housing Condition	2.0
Tran Lines Condition	2.0
Trans Fluid Condition	1.0
Trans Fluid Leaks Condition	2.0
Trans Cooler Condition	NA
Trans Shifter Condition	2.0
Section Condition Grade	1.8

Section Notes: ENGINE IN TRANSMISISON IN GOOD CONDITION. ENGINE OIL PAN IS LARGELY DENTED ON BOTTOM BUT STILL SEALING. SLIGHT LEAKS FROM ENGINE AND TRANSMISSION AS EXPECTED FROM ERA OF VEHICLE.

### **Brakes Mechanical Condition**

Front Brake Material	3.0
Front Brake Rotors / Drums	3.0
Rear Brake Material	3.0
Rear Brake Rotors / Drums	3.0
Brake Lines Condition	3.0
Parking Brake Operation	3.0
Section Condition Grade	3.0

### **Steering Mechanical Condition**

Rack-n-Pinion Condition	NA
Tie Rods Condition	3.0
Steering Linkage Condition	3.0
Steering Column Condition	3.0
Pump / Gearbox Condition	NA
Alignment Condition	2.0
Section Condition Grade	2.8

**Section Notes:** VEHICLE HAS DISC IN FRONT AND DRUMS IN REAR. STOPS AND STEERS WELL. MAJORITY OF STEERING AND FRONT SUSPENSION HAS BEEN REPLACED.

### **Suspension Mechanical Condition**

Front Shocks Condition	2.0
Rear Shocks Condition	4.0
Bushings Condition	4.0
Sway Bar Links Condition	4.0
Suspension Control Condition	NA
Control Arms Condition	3.0
Section Condition Grade	3.4

### **Electrical Systems Condition**

Diagnostic Trouble Codes Present	NA
Check Engine Light On / Off	NA
Airbag Light On / Off	NA
ABS Light On / Off	NA
Wiring Condition	2.0
Battery Condition	2.0
Section Condition Grade	2.0

**Section Notes:** SOME OF REAR BUSHINGS SHOW AGE AND ARE DRY. ELECTRICAL SYSTEM IN GOOD CONDITION. WIRING LOOKS GOOD.

### **Unibody Frame Condition**

A,B,C,D Pillar Repair / Condition	5.0
Firewall Repair / Condition	3.0
Floor Pans Repair / Condition	3.0
Apron Repair / Condition	3.0
Inner Quarter Repair / Condition	3.0
Frame Rail Repair / Condition	3.0
Rocker Panel Repair / Condition	3.0
Section Condition Grade	3.3

### **Conventional Frame Condition**

Frame Rail Repair / Condition	3.0
Cross Member Repair / Condition	5.0
Radiator Core Repair / Condition	3.0
Trunk Pan Repair / Condition	3.0
Spring Pod Repair / Condition	3.0
Torque Box Repair / Condition	3.0
Wheel House Repair / Condition	3.0
Section Condition Grade	3.3

**Section Notes:** LEFT FRONT A-PILLAR (DOOR JAM HING AREA) NEAR BOTTOM SHOWS CORROSION IN LOWER CORNER. FRONT CROSS MEMBER TO FRAME RAILS WELDS ARE SPOTTY AND COULD HAVE BEEN REPAIRED BETTER AS WELL AS DENTING IN CROSS MEMBER.

### Test Drive Results

Acceleration	2.0
Shifting	3.0
Steering	2.0
Braking	2.0
Ride / Handling	3.0
Rattles / Noises	4.0
Warning Lights	NA
Section Condition Grade	2.7

### Condition Summary

Body	3.8
Interior	3.3
Features / Options	3.0
Mechanical	2.7
Electrical	3.0
Structural	3.3
Test Drive	2.7
Overall Vehicle Grade	3.1

**Section Notes:** VEHICLE DROVE AS DESIGNED. REAR SUSPENSION IS A BIT SOFT AND BOUNCY BUT STILL SOLID ENOUGH. VEHICLE BRAKES WELL AND HAS GOOD ACCLERATION.

**Inspectors Notes:** VEHICLE IS IN AVERGE CONDITION. SHOWS TO HAVE SOME THICK PRIMER FILLER AND BODY FILLER IN SEVERAL PANELS. UNDERCARRIAGE IS IN GOOD CONDITION BUT SOME REPAIRS COULD HAVE BEEN DONE BETTER. IT RUNS AND DRIVES WELL AND APPEARS TO HAVE THE CORRECT BADGING AND OPTIONS FOR THE ERA.