



St Rose, Illinois 62230  
 www.TestDriveTech.com  
 Phone: 636-388-8378  
 Email: info@testdrivetech.com

# TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



## Vehicle Identification

Inspection Date: 8/3/2017

VIN: JN1CZ24D0TX580361	Trim: ZX
Year: 1996	Vehicle Type: COUPE
Make: NISSAN	Number of Doors: 2
Model: 300	Engine Size: V6
Mileage: 60344	Transmission Type: AUTO
Hours: NA	Driveline Type: RWD

### How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

### Left Side Body Condition

### Right Side Body Condition

Left Front Fender	2.0
Left Windshield A-Pillar	2.0
Left Front Door	2.0
Left Center B-Pillar	NA
Left Rear Door	NA
Left C-Pillar	2.0
Left Quarter Panel	2.0

Right Front Fender	2.0
Right Windshield A-Pillar	2.0
Right Front Door	2.0
Right Center B-Pillar	NA
Right Rear Door	NA
Right C-Pillar	2.0
Right Quarter Panel	2.0

Section Condition Grade 2.0

Section Condition Grade 2.0

**Section Notes:** PAINT IS IN GOOD CONDITION. DOES NEED A GOOD DETAIL AND POLISH TO BRING OUT THE GLOSS AND SHINE.

### Front Body Condition

Hood	3.0
Front Bumper	3.0
Headlamps	2.0
Windshield Cowl	2.0
Front Roof Top	2.0
Section Condition Grade	2.4

### Rear Body Condition

Trunk	2.0
Rear Bumper	2.0
Tail Lamps	2.0
Deck Cowl	2.0
Rear Roof Top	2.0
Section Condition Grade	2.0

**Section Notes:** FRONT BUMPER AND PARTIAL HOOD SHOWS THAT IT WAS PROTECTED FROM A BRA HOWEVER IT NOW SHOWS THE REST OF THE CAR AS FADED. POLISHING SHOULD BE ABLE TO BRING OUT THE REMAINING

### Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	2.0
Steering Wheel Condition	2.0
Driver Seat Condition	2.0
Passenger Seat Condition	2.0
Front Carpet Condition	2.0
Left Front Door Panel	2.0
Left Rear Door Panel	NA
Cargo Interior Sides	2.0
Section Condition Grade	2.0

### Rear Interior Condition

Rear Seat Type	NA
3rd Seat Present	NA
Rear Seat Condition	NA
Rear Deck Condition	2.0
Rear Carpet Condition	2.0
3rd Seat Condition	NA
Right Front Door Panel	2.0
Right Rear Door Panel	NA
Cargo Floor & Roof	2.0
Section Condition Grade	2.0

**Section Notes:** INTERIOR IS IN NEAR NEW CONDITION. CLEAN AND WELL MAINTAINED.

### Tire Condition

Tire Brand	FUZION
Front Tire Size	225/50/R16
Left Front Tire Tread	3.0
Right Front Tire Tread	3.0
Rear Tire Size	245/45R16
Left Rear Tire Tread	3.0
Right Rear Tire Tread	3.0
Section Condition Grade	3.0

### Wheel Condition

Wheel Type	CHROME ALLOY
Left Front Wheel Condition	3.0
Right Front Wheel Condition	3.0
Left Rear Wheel Condition	3.0
Right Rear Wheel Condition	3.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	YES
Section Condition Grade	3.0

**Section Notes:** TIRES ARE IN GOOD CONDITION, SHOW SOME WEAR. WHEELS ARE IN GOOD CONDITION AND SHOW SOME LIGHT PITTING AND WEAR BUT OK.

**Interior Option Operation**

Left Front Seat Operation	2.0
Right Front Seat Operation	2.0
Rear Seat Operation	NA
3rd Seat Operation	NA
Stereo Operation	2.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	NA
Section Condition Grade	NA

**Exterior Option Operation**

Left Front Window Operation	2.0
Right Front Window Operation	2.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Cargo Door Operation	2.0
Door Locks Operation	2.0
Windshield Wiper Operation	3.0
Rear Defrost Operation	2.0
Section Condition Grade	2.2

**Section Notes:** ALL FEATURES AND OPTIONS ARE OPERATING HOWEVER, THE WINDSHIELD WASHER NOZZLE ON THE DRIVER SIDE IS NOT SPRAYING CORRECTLY.

**Interior Lighting Condition**

Dash Lamps Operation	2.0
Interior Lighting Operation	2.0
Map Lights Operation	2.0
Dome Lights Operation	2.0
Hood Lamp Operation	NA
Seat Belt Light Operation	2.0
Section Condition Grade	2.0

**Exterior Lighting Condition**

Low Beam Head Light Operation	2.0
High Beam Head Light Operation	2.0
Parking Lamp Operation	2.0
4-Way Flasher Operation	2.0
Left Turn Operation	2.0
Right Turn Operation	2.0
Section Condition Grade	2.0

**Section Notes:** ALL LIGHTS OPERATING AS DESIGNED.

**Engine Mechanical Condition**

Engine Block Condition	2.0
Engine Hoses Condition	2.0
Engine Oil Leaks	1.0
Fuel Leaks	1.0
Air Filter Condition	2.0
Radiator Condition	2.0
Section Condition Grade	1.7

**Transmission Mechanical Condition**

Trans Housing Condition	2.0
Tran Lines Condition	2.0
Trans Fluid Condition	1.0
Trans Fluid Leaks Condition	1.0
Trans Cooler Condition	2.0
Trans Shifter Condition	2.0
Section Condition Grade	1.7

**Section Notes:** ENGINE AND TRANSMISSION IN VERY GOOD CONDITION. ENGINE SOUNDS GOOD AND TRANSMISSION SHIFTS SMOOTHLY AS DESIGNED.

**Brakes Mechanical Condition**

Front Brake Material	3.0
Front Brake Rotors / Drums	3.0
Rear Brake Material	3.0
Rear Brake Rotors / Drums	3.0
Brake Lines Condition	2.0
Parking Brake Operation	2.0
Section Condition Grade	2.7

**Steering Mechanical Condition**

Rack-n-Pinion Condition	2.0
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	2.0
Alignment Condition	2.0
Section Condition Grade	2.0

Section Notes: BRAKES SHOW NORMAL WEAR AND WILL LIKELY NEED CHANGED IN NEAR FUTURE.

**Suspension Mechanical Condition**

Front Shocks Condition	3.0
Rear Shocks Condition	3.0
Bushings Condition	2.0
Sway Bar Links Condition	3.0
Suspension Control Condition	3.0
Control Arms Condition	3.0
Section Condition Grade	2.8

**Electrical Systems Condition**

Diagnostic Trouble Codes Present	NO
Check Engine Light On / Off	OFF
Airbag Light On / Off	OFF
ABS Light On / Off	OFF
Wiring Condition	2.0
Battery Condition	2.0
Section Condition Grade	2.0

Section Notes: SUSPENSION AND ELECTRICAL SYSTEM IN GOOD CONDITION. WIRING LOOKS GOOD.

**Unibody Frame Condition**

A,B,C,D Pillar Repair / Condition	2.0
Firewall Repair / Condition	2.0
Floor Pans Repair / Condition	2.0
Apron Repair / Condition	2.0
Inner Quarter Repair / Condition	2.0
Frame Rail Repair / Condition	2.0
Rocker Panel Repair / Condition	2.0
Section Condition Grade	2.0

**Conventional Frame Condition**

Frame Rail Repair / Condition	4.0
Cross Member Repair / Condition	2.0
Radiator Core Repair / Condition	2.0
Trunk Pan Repair / Condition	2.0
Spring Pod Repair / Condition	2.0
Torque Box Repair / Condition	2.0
Wheel House Repair / Condition	2.0
Section Condition Grade	2.3

Section Notes: VEHICLE IS STRUCTURALLY SOUND AND NO REPAIRS FOUND. AREA ON RAIL OF ROCKER PANELS SHOWS TO HAVE HIT A CURB OR OBJECT ON BOTH SIDES.

## Test Drive Results

Acceleration	3.0
Shifting	3.0
Steering	3.0
Braking	3.0
Ride / Handling	3.0
Rattles / Noises	3.0
Warning Lights	1.0
<b>Section Condition Grade</b>	<b>2.7</b>

## Condition Summary

Body	2.2
Interior	2.0
Features / Options	2.0
Mechanical	2.1
Electrical	2.0
Structural	2.1
Test Drive	2.7
<b>Overall Vehicle Grade</b>	<b>2.2</b>

**Section Notes:** VEHICLE DROVE WELL AS DESIGNED.

**Inspectors Notes:** VEHICLE IS IN GOOD CONDITION. SHOWS ITS AGE FROM SUN FADING. POWERTRAIN FEELS STRONG AND SOUND. NO RUST OR CORROSION FOUND ON CAR. PAINT IS IN GOOD CONDITION, INTERIOR IS IN GOOD CONDITION.