



**17715 St Rose Road**  
**St Rose, Illinois 62230**  
**www.TestDriveTech.com**  
**Phone: 636-388-8378**  
**Email: info@testdrivetech.com**

# TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



## Inspection Date:

## Vehicle Identification

**VIN: WDXPF445X89371015**  
**Year: 2010**  
**Make: WINNEBAGO**  
**Model: ITASCA**  
**Mileage: 53092**  
**Hours: NA**  
**Coach / Body SN: F70540L241919**  
**Vehicle Type: CLASS C MOTORHOME**  
**Number of Doors 3**  
**Engine Size: 6**  
**Transmission Type: AUTO**  
**Driveline Type: 2WD**

## What We Are Inspecting In This Section.

"Chassis" in this section refers to the basic structure which your motorhome is built upon such as a Ford F350 and its working & driving components. This section will include the basic body, operators seating, engine, driveline, steering and suspension systems as well as the braking system.

## Condition Summary

Chassis Body	2.6
Chassis Electrical	2.1
Chassis Mechanical	2.1
Coach Structural	2.0
Coach Body / Interior	2.7
Coach Electrical	1.4
Coach HVAC / Plumbing	1.6
Coach Appliances / Options	1.9
Test Drive	2.9
<b>Overall Vehicle Grade</b>	<b>2.1</b>

## Left Body

Left Front Fender	3.0
Left Windshield A-Pillar	3.0
Left Front Door	3.0
Left Center B-Pillar	3.0
Left Rocker Panel	3.0
Front Bumper	3.0
Cab Roof	3.0
<b>Section Condition Grade</b>	<b>3.0</b>

## Right Body

Right Front Fender	3.0
Right Windshield A-Pillar	3.0
Right Front Door	3.0
Right Center B-Pillar	3.0
Right Rocker Panel	3.0
Rear Bumper	3.0
Hood	3.0
<b>Section Condition Grade</b>	<b>3.0</b>

**Section Notes: BODY IS IN GOOD AVERAGE CONDITION. SHOWS AGE BUT IS WELL MAINTAINED AND FREE OF MAJOR DAMAGE OR REPAIRS.**

**Glass Condition**

Windshield Condition	3.0
Left Front Door Glass	3.0
Right Front Door Glass	3.0
Left House Windows	3.0
Right House Windows	3.0
Rear House Windows	3.0

Section Condition Grade 3.0

**Exterior Lights Condition**

High / Low Beam Operation	2.0
Tail Light Operation	2.0
Clearance Lights Operation	4.0
Left Turn Signal Operation	2.0
Right Turn Signal Operation	2.0
4-Way Flasher Operation	2.0

Section Condition Grade 2.3

Section Notes: REAR LEFT UPPER CLEARANCE LAMP IS INOPERATIVE. ALL OTHER LIGHTS WORKING AS DESIGNED. LIKELY JUST NEEDS A BULB.

**Left Side Wheels Condition**

Welds or Cracks in Wheels	NO
LF Steer Wheel	2.0
LFI Drive Wheel	2.0
LFO Drive Wheel	2.0
LRI Drive Wheel	2.0
LRO Drive Wheel	2.0

Section Condition Grade 2.0

**Right Side Wheels Condition**

Studs & Lug Nuts Present	YES
RF Steer Wheel	2.0
RFI Drive Wheel	2.0
RFO Drive Wheel	2.0
RRI Drive Wheel	2.0
RRO Drive Wheel	2.0

Section Condition Grade 2.0

Section Notes: WHEELS IN GOOD CONDITION. RR CHROME BEAUTY RING HUBCAP MISSING.

**Left Side Tires Condition**

Tire Size	LT 215/85R16
LF Steer Tire	2.0
LFI Drive Tire	2.0
LFO Drive Tire	2.0
LRI Drive Tire	2.0
LRO Drive Tire	2.0

Section Condition Grade 2.0

**Right Side Tires Condition**

DOT Date	2/1/2015
RF Steer Tire	2.0
RFI Drive Tire	2.0
RFO Drive Tire	2.0
RRI Drive Tire	2.0
RRO Drive Tire	2.0

Section Condition Grade 2.0

Section Notes: TIRES MANUFACTURED IN FEB OF 2015. SHOWS TO BE IN VERY GOOD TO BRAND NEW CONDITION.

**Interior Options**

Driver / Passenger Seat Type	MANUAL
Seat Covering Type	CLOTH
Driver / Pass Window Type	POWER
Stereo Type	AM / FM / CD
HVAC Type	MANUAL SELECTION
Flooring Type	CARPET / VINYL

**Interior Condition**

Seat Operation	2.0
Window Operation	2.0
Stereo Operation	2.0
Heater / AC Operation	2.0
Seat Condition	2.0
Flooring Condition	4.0

Section Condition Grade 2.3

Section Notes: INTERIOR IN GOOD CONDITION. HOUSE FLOOR SHOWS A CRACK IN THE VINYL FLOOR NEAR THE SINK.

**Engine Mechanical Condition**

Engine Block Condition	2.0
Engine Oil Level	2.0
Engine Oil Condition	2.0
Air Filter Condition	2.0
Engine Hoses / Lines Condition	2.0
Turbo & Piping Condition	2.0

Section Condition Grade 2.0

**Transmission Mechanical Condition**

Transmission Housing Condition	2.0
Transmission Fluid Level	2.0
Transmission Fluid Condition	2.0
Transmission Hoses / Lines Condition	2.0
Transmission Seals Condition	2.0
Shifter Operation	2.0

Section Condition Grade 2.0

Section Notes: ENGINE AND TRANSMISSION BOTH CHECK OUT IN GOOD CONDITION. OBID II SYSTEM SHOWS STORED CODES FOR #2 GLOW PLUG FAULT WHICH NEEDS FURTHER TROUBLESHOOTING TO BE SURE OF CAUSE.

**Driveline Mechanical Condition**

Driveshaft Condition	2.0
U-Joints Condition	2.0
Transmission Yoke Condition	2.0
Axle Yoke Condition	2.0
Carrier Bearing Condition	2.0

Section Condition Grade 2.0

**Suspension Mechanical Condition**

Shocks Condition	2.0
Springs Condition	2.0
Air Bags Condition	NA
Swab Bar Bushings Condition	2.0
Trailing Arms Condition	2.0

Section Condition Grade 2.0

Section Notes: DRIVELINE AND SUSPENSION BOTH IN GOOD CONDITION AND FREE OF ISSUES.

**Steering Mechanical Condition**

Steering Linkage Condition	2.0
Tie Rods Condition	2.0
Steering Column Condition	2.0
Ball Joints Kingpins Condition	2.0
Pump / Gearbox Condition	2.0
Steering Hoses / Lines Condition	2.0

Section Condition Grade 3.0

**Brake System Mechanical Condition**

Front Disc / Drums Condition	3.0
Front Pads / Shoes Condition	3.0
Rear Disc / Drums Condition	3.0
Rear Pads / Shoes Condition	3.0
Master Cylinder / Lines Condition	2.0
Brake Fluid Level / Condition	2.0

Section Condition Grade 2.7

Section Notes: STEERING TIGHT AS DESIGNED, GOOD ALIGNMENT. BRAKES SHOW NORMAL WEAR FOR MILEAGE. PARKING BRAKE STICKS AND NEEDS LUBED AND ADJUSTED.

**Exhaust Mechanical Condition**

Exhaust Manifold Condition	2.0
Piping Condition	2.0
Muffler Condition	2.0
Catalytic Converter Condition	2.0
Seals / Gaskets Condition	2.0
Hangers / Mounts Condition	2.0

Section Condition Grade 2.0

**Structural / Frame Condition**

Frame Rails Condition	2.0
Front Cross Member	2.0
Engine Cross Member	2.0
Transmission Cross Member	2.0
Cab Cross Member	2.0
Intermediate Cross Member	2.0
Rear Cross Member	2.0

Section Condition Grade 2.0

Section Notes: EXHAUST AND FRAME OF VEHICLE ARE SOLID AND SECURE AS DESIGNED.

### Electrical System Condition

Gauges Operation	1.0
Warning Lights Self Check	1.0
Warning Lights On?	6.0
Wiring Condition	3.0
Fuse Box / Panel Condition	3.0
Trailer Lighting Condition	2.0
Section Condition Grade	2.7

### Features / Options Condition

Window Operation	1.0
Seat Operation	1.0
Stereo Operation	1.0
Mirror Operation	1.0
Locks Operation	1.0
Wipers Operation	1.0
Section Condition Grade	1.0

Section Notes: CHECK ENGINE LAMP CODE STORED FOR #2 GLOW PLUG. MISC. WIRES FOUND IN FUSE BOX.

### Interior Lighting Condition

Dash Lamps Operation	2.0
Interior Lighting Operation	2.0
Map Lights Operation	2.0
Dome Lights Operation	2.0
Cargo Lamp Operation	2.0
Seat Belt Light Operation	2.0
Section Condition Grade	2.0

### Exterior Lighting Condition

Low Beam Head Light Operation	2.0
High Beam Head Light Operation	2.0
Parking Lamp Operation	2.0
4-Way Flasher Operation	2.0
Left Turn Operation	2.0
Right Turn Operation	2.0
Section Condition Grade	2.0

Section Notes: ALL LIGHTS EXCEPT UPPER LEFT REAR CLEARANCE LAMP ARE WORKING.

## Class C RV Coach Inspection

What We Are  
Inspecting In This  
Section.

"Coach" in this section refers to what is often called the "House" of your motorhome. This is where you mostly live in your RV when you are not driving it. This section covers the living area, kitchen, appliances, body of the motorhome and the major plumbing and electrical systems.

### Interior Coach Condition

Counter Condition	2.0
Flooring Condition	6.0
Doors / Walls Condition	2.0
Trim / Drapery Condition	2.0
Upholstery / Seating Condition	2.0
Cabinetry Condition	4.0
Section Condition Grade	3.0

### Coach Exterior

Roof Condition	2.0
Roof Seals / Sealant Condition	2.0
Left Side Coach Body	2.0
Windows Condition	2.0
Storage Doors Condition	4.0
Entry Door Condition	2.0
Section Condition Grade	2.3

Section Notes: FLOOR SHOWS CRACK NEAR KITCHEN AREA. SEVERAL CABINETS HAVE BEEN "CUSTOMIZED" OR HAVE HAD ITEMS ADDED TO THEM. A COUPLE OF EXTERIOR STORAGE DOORS DO NOT SECURELY LATCH AND NEED FURTHER TROUBLESHOOTING & ADJUSTMENT.

**Coach Lighting Condition**

12 Volt Lighting Condition	2.0
110 Volt Lighting Condition	2.0
Switches Condition	2.0
Accessory Lighting Condition	2.0
Awning Light Condition	2.0
Storage Lighting Condition	2.0
Section Condition Grade	2.0

**Appliances Condition**

Heater Condition	2.0
Air Conditioning Condition	2.0
Stove / Oven Condition	3.0
Microwave Condition	2.0
Refrigerator Condition	2.0
TV / Stereo Condition	2.0
Section Condition Grade	2.2

Section Notes: MAIN AC WORKS WELL. HEATER WORKS WELL ON BOTH ELEC AND LP. STOVE LIGHTS WORKS HOWEVER, METAL GRATE IS SECURED TO ADDITIONAL COUNTER TOP.

**Generator Condition**

Visible Leaks Present	NO
Run for 30 Minutes	YES
Oil Level Condition	1.0
Oil Condition	1.0
Starting Condition	1.0
Shutdown Condition	1.0
Section Condition Grade	1.0

**Plumbing Condition**

Visible Leaks Present	YES
12 Volt Pump Operation	YES
Holding Tank Gauge Operation	1.0
Sinks / Shower / Toilet Condition	1.0
Grey / Black Water Valve Condition	1.0
Fresh Water Inlets Condition	1.0
Section Condition Grade	1.0

Section Notes: WHILE PROVIDING CITY WATER SERVICE CONNECTION WATER BEGAN TO LEAK FROM HOT WATER HEATER. UNABLE TO DIAGNOSIS LEAK DUE TO LACK OF ACCESS. LIKELY AN OPEN VALVE OR LINE AS THE UNIT WAS WINTERIZED PRIOR TO INSPECTION.

**Slides / Awning Condition**

Number of Slideouts	1
Number of Awnings	2.0
Slide Outs Operation	3.0
Slide Out Seals Condition	2.0
Awning Operation	1.0
Awning Condition	1.0
Section Condition Grade	1.8

**Coach Electrical Condition**

House Batteries Condition	3.0
Voltage Gauge Operation	1.0
Shore Power Condition	1.0
Power Cords Condition	1.0
Generator Operation	1.0
Inverter Operation	1.0
Section Condition Grade	1.3

Section Notes: SLIDEOUT NEEDS LUBE HOWEVER STILL WORKS AS DESIGNED. HOUSE BATTERIES DRAIN DOWN A BIT FAST HOWEVER RECOVER OK.

**Coach Safety Condition**

Any Smell of Exhaust in Cabin	NO
Fire Extinguisher Condition	2.0
Gas Monitor Condition	2.0
CO Alarm Condition	2.0
Smoke Detector Condition	2.0
Lock-Outs Operation	1.0
Section Condition Grade	1.8

Section Notes:

**Test Drive Results**

Acceleration	2.0
Shifting	2.0
Steering	2.0
Braking	3.0
Ride / Handling	2.0
Rattles / Noises	3.0
Warning Lights	6.0
Section Condition Grade	2.9

Section Notes: VEHICLE TEST DROVE WELL AT BOTH HIGHWAY AND CITY SPEEDS. IT STOPS AS DESIGNED, DOES NOT PULL AND FEEL SOLID AND SECURE ON THE

**Leveling System Condition**

System Type	RAMPS / JACKS
Hydraulic Fluid Level	NA
Hydraulic Fluid Condition	NA
Self Leveling Operation	NA
Jacks Operation	2.0
Control Panel Operation	NA
Section Condition Grade	2.0

**Inspectors Notes:**

VEHICLE WAS MADE READY FOR INSPECTION. IT WAS WINTERIZED UPON ARRIVAL, SHORE POWER (30 AMP 110 VOLTS AC) WAS PROVIDED AND RAN COACH. CITY WATER CONNECTION WAS PROVIDED.