



WWW.  
**TESTDRIVETECH**  
Vehicle Inspection Services .COM

St Rose, Illinois 62230

WWW.TESTDRIVETECH.COM

PHONE: 636-388-8378

EMAIL: INFO@TESTDRIVETECH.COM

# TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



## Vehicle Identification

Inspection Date: 7/19/2017

VIN WDDLJ9BB0EA097740	Trim: 550
Year: 2014	Vehicle Type: SEDAN
Make: MERCEDES-BENZ	Number of Doors: 4
Model: CLS	Engine Size: V8
Mileage: 39158	Transmission Type: AUTO
Hours: NA	Driveline Type: AWD

Section Notes: VIN VERIFIED BY TAG AND ECM

### How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

### Left Side Body Condition

### Right Side Body Condition

Left Front Fender	2.0	Right Front Fender	2.0
Left Windshield A-Pillar	2.0	Right Windshield A-Pillar	2.0
Left Front Door	2.0	Right Front Door	2.0
Left Center B-Pillar	2.0	Right Center B-Pillar	2.0
Left Rear Door	2.0	Right Rear Door	2.0
Left C-Pillar	2.0	Right C-Pillar	2.0
Left Quarter Panel	2.0	Right Quarter Panel	2.0
Left Rocker Panel	2.0	Right Rocker Panel	2.0
Section Condition Grade	2.0	Section Condition Grade	2.0

Section Notes: BODY PANELS SHOW TO BE IN GOOD CONDITION WITH A FEW CHIPS WHICH APPEAR TO HAVE BEEN TOUCHED UP WITH A PAINT PEN. NO PRIOR REPAIRS FOUND.

### Front Body Condition

Hood	3.0
Front Bumper	3.0
Headlamps	2.0
Windshield Cowl	2.0
Front Roof Top	2.0
Section Condition Grade	2.4

### Rear Body Condition

Trunk	2.0
Rear Bumper	2.0
Tail Lamps	2.0
Deck Cowl	2.0
Rear Roof Top	2.0
Section Condition Grade	2.0

**Section Notes:** HOOD AND BUMPER SHOW TO HAVE A FEW PAINT CHIPS THAT HAVE BEEN TOUCHED UP WITH A PAINT PEN. OVERALL IN GOOD CONDITION AND CLEAN. NO PRIOR REPAIRS FOUND.

### Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	2.0
Steering Wheel Condition	2.0
Driver Seat Condition	2.0
Passenger Seat Condition	2.0
Front Carpet Condition	2.0
Left Front Door Panel	2.0
Left Rear Door Panel	2.0
Cargo Interior Sides	2.0
Front Center Console / Arm Rest	2.0
Section Condition Grade	2.0

### Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	2.0
Rear Deck Condition	2.0
Rear Carpet Condition	2.0
3rd Seat Condition	NA
Right Front Door Panel	2.0
Right Rear Door Panel	2.0
Cargo Floor & Roof	6.0
Rear Center Console / Arm Rest	2.0
Section Condition Grade	2.7

**Section Notes:** INTERIOR OF VEHICLE IN VERY GOOD CONDITION. GREASE-LIKE SUBSTANCE FOUND IN TRUNK PAN FLOOR AND UNDER SPARE TIRE. UNKNOWN CAUSE. COMFORT BOX (CONVIENCE BOX) IS MISSING FROM CARGO AREA.

### Tire Condition

Front Tire Size	19 INCH
Left Front Tire Tread	1.0
Right Front Tire Tread	1.0
Rear Tire Size	19 INCH
Left Rear Tire Tread	1.0
Right Rear Tire Tread	1.0
Valve Caps Present	YES
Section Condition Grade	1.0

### Wheel Condition

Wheel Type	ALLOY
Left Front Wheel Condition	2.0
Right Front Wheel Condition	2.0
Left Rear Wheel Condition	2.0
Right Rear Wheel Condition	2.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	YES
Section Condition Grade	2.0

**Section Notes:** TIRES ARE NEW AND SHOW NO WEAR. WHEELS IN VERY GOOD CONDITION AND ONLY SHOW MINOR WEAR AROUND EDGES.

**Interior Option Operation**

Left Front Seat Operation	1.0
Right Front Seat Operation	1.0
Rear Seat Operation	NA
3rd Seat Operation	NA
Stereo Operation	1.0
Navigation Operation	1.0
Front Seat Belts Present	YES
Rear Seat Belts Present	YES
Section Condition Grade	1.0

**Exterior Option Operation**

Left Front Window Operation	1.0
Right Front Window Operation	1.0
Left Rear Window Operation	1.0
Right Rear Window Operation	1.0
Cargo Door Operation	1.0
Door Locks Operation	1.0
Windshield Wiper Operation	1.0
Rear Defrost Operation	1.0
Section Condition Grade	1.0

Section Notes: INTERIOR OPTIONS AND FEATURES OPERATING AS DESIGNED.  
COMFORT BOX MISSING FROM CARGO AREA.

**Interior Lighting Condition**

Dash Lamps Operation	1.0
Interior Lighting Operation	1.0
Map Lights Operation	1.0
Dome Lights Operation	1.0
Hood Lamp Operation	1.0
Seat Belt Light Operation	1.0
Section Condition Grade	1.0

**Exterior Lighting Condition**

Low Beam Head Light Operation	1.0
High Beam Head Light Operation	1.0
Parking Lamp Operation	1.0
4-Way Flasher Operation	1.0
Left Turn Operation	1.0
Right Turn Operation	1.0
Section Condition Grade	1.0

Section Notes: LIGHTS WORKING WELL. WIRING IN GOOD CONDITION.

**Engine Mechanical Condition**

Engine Block Condition	1.0
Engine Hoses Condition	1.0
Engine Oil Leaks	1.0
Fuel Leaks	1.0
Air Filter Condition	1.0
Radiator Condition	3.0
Section Condition Grade	1.3

**Transmission Mechanical Condition**

Trans Housing Condition	1.0
Tran Lines Condition	1.0
Trans Fluid Condition	1.0
Trans Fluid Leaks Condition	1.0
Trans Cooler Condition	1.0
Trans Shifter Condition	1.0
Section Condition Grade	1.0

Section Notes: LOWER AREA OF RADIATOR SHOWS BUILT UP ROAD DEBRIS AND SHOULD BE CLEANED. AIR INTAKE GASKET SEALS ARE NOT INSTALLED PROPERLY. (DRIVER SIDE IS BACKWARDS)

**Brakes Mechanical Condition**

Front Brake Material	1.0
Front Brake Rotors / Drums	1.0
Rear Brake Material	1.0
Rear Brake Rotors / Drums	3.0
Brake Lines Condition	1.0
Parking Brake Operation	1.0
Section Condition Grade	1.3

**Steering Mechanical Condition**

Rack-n-Pinion Condition	1.0
Tie Rods Condition	1.0
Steering Linkage Condition	1.0
Steering Column Condition	1.0
Pump / Gearbox Condition	1.0
Alignment Condition	1.0
Section Condition Grade	1.0

**Section Notes:** FRONT AND REAR BRAKE PADS ARE NEW, FRONT ROTORS ARE NEW. REARS ARE ORIGINAL AND SHOW SLIGHT WEAR.

**Suspension Mechanical Condition**

Front Shocks Condition	2.0
Rear Shocks Condition	2.0
Bushings Condition	2.0
Sway Bar Links Condition	2.0
Suspension Control Condition	1.0
Control Arms Condition	2.0
Section Condition Grade	1.8

**Electrical Systems Condition**

Diagnostic Trouble Codes Present	NO
Check Engine Light On / Off	OFF
Airbag Light On / Off	OFF
ABS Light On / Off	OFF
Wiring Condition	1.0
Battery Condition	1.0
Section Condition Grade	1.0

**Section Notes:** SUSPENSION PERFORMS AS DESIGNED. WIRING IN GOOD CONDITION. MAIN BATTERY TEST AT 12.37 WITH KEY OFF 12.03 WITH KEY ON. ACCESSORY BATTERY TEST AT 13.03 KEY OFF, 12.07 KEY ON AND 11.99 AFTER RELAY W KEY ON. ALL WITHIN OPERATING SPECS.

**Unibody Frame Condition**

A,B,C,D Pillar Repair / Condition	1.0
Firewall Repair / Condition	1.0
Floor Pans Repair / Condition	1.0
Apron Repair / Condition	1.0
Inner Quarter Repair / Condition	1.0
Frame Rail Repair / Condition	1.0
Rocker Panel Repair / Condition	1.0
Section Condition Grade	1.0

**Conventional Frame Condition**

Frame Rail Repair / Condition	1.0
Cross Member Repair / Condition	1.0
Radiator Core Repair / Condition	1.0
Trunk Pan Repair / Condition	1.0
Spring Pod Repair / Condition	1.0
Torque Box Repair / Condition	1.0
Wheel House Repair / Condition	1.0
Section Condition Grade	1.0

**Section Notes:** VEHICLE STRUCTURE IS IN VERY GOOD CONDITION AND FREE OF ANY CORROSION OR PREVIOUS REPAIR.

## Test Drive Results

Acceleration	1.0
Shifting	1.0
Steering	1.0
Braking	1.0
Ride / Handling	1.0
Rattles / Noises	1.0
Warning Lights	1.0

Section Condition Grade 1.0

## Condition Summary

Body	2.2
Interior	2.3
Features / Options	3.0
Mechanical	2.5
Electrical	3.0
Structural	1.0
Test Drive	1.0

Overall Vehicle Grade 2.1

**Section Notes:** GOOD POWER, GOOD SHIFTS, STEERS AND BRAKES AS DESIGNED.

**Inspectors Notes:** VEHICLE IS IN VERY GOOD CONDITION. IT IS MISSING THE COMFORT BOX IN THE CARGO AREA, SHOWS TO HAVE AN GREESE-LIKE SUSSTANCE IN THE TRUNK PAN, DRIVES VERY WELL AND PEFORMS AS DESIGNED. LOWER RADIATOR NEEDS CLEANED, DRIVER SIDE INTAKE GASKET IN FRONT NEEDS REINSTALLED CORRECTLY.