



WWW.
TESTDRIVETECH
VEHICLE INSPECTION SERVICES .COM

St Rose, Illinois 62230

WWW.TESTDRIVETECH.COM

PHONE: 636-388-8378

EMAIL: INFO@TESTDRIVETECH.COM

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 9/28/2017

VIN 223379L101692	Trim: TRANS AM CLONE
Year: 1969	Vehicle Type: COUPE
Make: PONTIAC	Number of Doors: 2
Model: FIREBIRD	Engine Size: V8
Mileage: 41084	Transmission Type: AUTO 3 SPEED
Hours: NA	Driveline Type: RWD

Section Notes: VIN VERIFIED BY VIN TAG AND PANEL VIN TAGS

How Each
Inspection Section Is
Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

Left Front Fender	4.0	Right Front Fender	4.0
Left Hood Cowl	4.0	Right Hood Cowl	4.0
Left Front Door	4.0	Right Front Door	4.0
Left Center B-Pillar	4.0	Right Center B-Pillar	4.0
Left Rear Door	NA	Right Rear Door	NA
Left C-Pillar	4.0	Right C-Pillar	4.0
Left Quarter Panel	4.0	Right Quarter Panel	4.0
Left Rocker Panel	4.0	Right Rocker Panel	4.0
Section Condition Grade	4.0	Section Condition Grade	4.0

Section Notes: BODY PANELS SHOW TO BE REPAINTED, PAINT LINES VERY VISIBLE. RUNS IN CLEAR COAT IN MANY PLACES. MANY LOOSE PIECES OF TRIM MISSING MOUNTING SCREWS ETC.

Front Body Condition

Hood	4.0
Front Bumper	4.0
Headlamps	4.0
Windshield Cowl	4.0
Front Roof Top	4.0
Section Condition Grade	4.0

Rear Body Condition

Trunk	4.0
Rear Bumper	4.0
Tail Lamps	4.0
Deck Cowl	4.0
Rear Roof Top	4.0
Section Condition Grade	4.0

Section Notes: HOOD, TRUNK, COWL, ROOF TOP, REAR PANELS ALL HAVE BEEN REPAINTED AND SHOW HIGHLY VISIBLE PAINT LINES. RUNS IN CLEAR COAT, FILLER IN ROOF, LACK OF SEAM SEALER IN DRIP RAILS, CRACKS IN REAR SPOILER AND FRONT NOSE CLIP.

Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	4.0
Steering Wheel Condition	3.0
Driver Seat Condition	3.0
Passenger Seat Condition	3.0
Front Carpet Condition	3.0
Left Front Door Panel	3.0
Left Rear Door Panel	NA
Cargo Interior Sides	3.0
Front Center Console / Arm Rest	4.0
Section Condition Grade	3.3

Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	3.0
Rear Deck Condition	3.0
Rear Carpet Condition	3.0
3rd Seat Condition	NA
Right Front Door Panel	3.0
Right Rear Door Panel	3.0
Cargo Floor & Roof	3.0
Rear Center Console / Arm Rest	NA
Section Condition Grade	3.0

Section Notes: DASH PAD IS IN GOOD CONDITION. SEATS ARE IN GOOD CONDITION. DOOR PANELS ARE IN GOOD CONDITION AND ARE SECURED. GLOVE BOX DOOR LATCH DOES NOT WORK AS DESIGNED, RADIO TRIM IS CUT ROUGHLY AND STEREO IS NOT INSTALLED CORRECTLY. CRACKS AND SCRATCHES IN CENTER CONSOLE.

Tire Condition

Front Tire Size	235/60R14
Left Front Tire Tread	3.0
Right Front Tire Tread	3.0
Rear Tire Size	235/60R14
Left Rear Tire Tread	3.0
Right Rear Tire Tread	3.0
Valve Caps Present	YES
Section Condition Grade	3.0

Wheel Condition

Wheel Type	ALLOY
Left Front Wheel Condition	2.0
Right Front Wheel Condition	2.0
Left Rear Wheel Condition	2.0
Right Rear Wheel Condition	2.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	YES
Section Condition Grade	2.0

Section Notes: TIRES AVERAGE, WHEELS GOOD CONDITION. SPARE IS DRY CRACKED

Interior Option Operation

Left Front Seat Operation	1.0
Right Front Seat Operation	NA
Rear Seat Operation	NA
Heater / Fan	4.0
Stereo Operation	6.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	YES
Section Condition Grade	3.7

Exterior Option Operation

Left Front Window Operation	3.0
Right Front Window Operation	3.0
Left Rear Window Operation	3.0
Right Rear Window Operation	3.0
Cargo Door Operation	1.0
Door Locks Operation	3.0
Windshield Wiper Operation	4.0
Rear Defrost Operation	NA
Section Condition Grade	2.9

Section Notes: BLOWER FAN WORKS HOWEVER DOES NOT CHANGE VENTS. WIPERS WORK HOWEVER WASHER DOES NOT. WINDOWS OK BUT STIFF, LOCKS OK BUT STIFF.

Interior Lighting Condition

Dash Lamps Operation	6.0
Interior Lighting Operation	6.0
Map Lights Operation	NA
Dome Lights Operation	1.0
Hood Lamp Operation	NA
Seat Belt Light Operation	6.0
Section Condition Grade	4.8

Exterior Lighting Condition

Low Beam Head Light Operation	1.0
High Beam Head Light Operation	1.0
Parking Lamp Operation	1.0
4-Way Flasher Operation	1.0
Left Turn Operation	5.0
Right Turn Operation	5.0
Section Condition Grade	2.3

Section Notes: GAUGE LAMPS INOP, DASH LAMPS INOP, SEAT BELT LAMP INOP, TURN SIGNALS WORK OPPOSITE WHEN LIGHTS ARE ON.

Engine Mechanical Condition

Engine Block Condition	2.0
Engine Hoses Condition	2.0
Engine Oil Leaks	3.0
Fuel Leaks	1.0
Air Filter Condition	1.0
Radiator Condition	1.0
Section Condition Grade	1.7

Transmission Mechanical Condition

Trans Housing Condition	2.0
Tran Lines Condition	2.0
Trans Fluid Condition	2.0
Trans Fluid Leaks Condition	3.0
Trans Cooler Condition	1.0
Trans Shifter Condition	4.0
Section Condition Grade	2.3

Section Notes: ENGINE IS GOOD. STARTS EASY AND HAS GOOD POWER. SLIGHT LEAKS AROUND OIL PAN. TRANS SHIFTS GOOD. SHIFTER NOT CORRECTLY ADJUSTED FOR SELECTIONS. SLIGHT LEAKING AROUND TRANS PAN. OIL FILTER VERY CLOSE TO HEADERS AND WILL LIKELY HEAT OIL TO UNSAFE TEMPS

Brakes Mechanical Condition

Front Brake Material	3.0
Front Brake Rotors / Drums	3.0
Rear Brake Material	3.0
Rear Brake Rotors / Drums	3.0
Brake Lines Condition	3.0
Parking Brake Operation	3.0
Section Condition Grade	3.0

Steering Mechanical Condition

Rack-n-Pinion Condition	NA
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	2.0
Alignment Condition	2.0
Section Condition Grade	2.0

Section Notes: DRUM BRAKES ALL AROUND. FADED QUICKLY AFTER A FEW HARD STOPS BUT STOPPED EVENLY. STEERING MECHANISM VERY CLOSE TO HEADERS ON PASSENGER SIDE.

Suspension Mechanical Condition

Front Shocks Condition	3.0
Rear Shocks Condition	3.0
Bushings Condition	3.0
Sway Bar Links Condition	2.0
Suspension Control Condition	2.0
Control Arms Condition	3.0
Section Condition Grade	2.7

Electrical Systems Condition

Diagnostic Trouble Codes Present	NO
Check Engine Light On / Off	OFF
Airbag Light On / Off	OFF
ABS Light On / Off	OFF
Wiring Condition	4.0
Battery Condition	4.0
Section Condition Grade	4.0

Section Notes: SOME BUSHINGS HAVE BEEN CHANGED OUT SOME ARE STILL FACTORY OEM AND ARE DRY CRACKED. WIRING HAS MANY UNPROFESSIONAL REPAIRS THROUGHOUT VEHICLE. BATTERY IS NOT SECURELY MOUNTED.

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	3.0
Firewall Repair / Condition	3.0
Floor Pans Repair / Condition	3.0
Apron Repair / Condition	3.0
Inner Quarter Repair / Condition	3.0
Frame Rail Repair / Condition	3.0
Rocker Panel Repair / Condition	3.0
Section Condition Grade	3.0

Conventional Frame Condition

Frame Rail Repair / Condition	3.0
Cross Member Repair / Condition	3.0
Radiator Core Repair / Condition	3.0
Trunk Pan Repair / Condition	3.0
Spring Pod Repair / Condition	3.0
Torque Box Repair / Condition	3.0
Wheel House Repair / Condition	3.0
Section Condition Grade	3.0

Section Notes: VEHICLE STRUCTURE IS SOLID. APPEARS A RESTORATION WAS DONE MANY YEARS BACK AND HAS BEEN WELL KEPT SINCE. NO EVIDENCE OF CORROSION IN USUAL PLACES. PANS AND MOUNTS LOOK SOLID. SOME REPAIRS DONE TO THE LOWER QUARTERS BUT IT LOOKS OK AND IS SOLID.

Test Drive Results

Acceleration	1.0
Shifting	2.0
Steering	2.0
Braking	3.0
Ride / Handling	2.0
Rattles / Noises	5.0
Warning Lights	6.0

Section Condition Grade 3.0

Condition Summary

Body	4.0
Interior	3.1
Features / Options	4.0
Mechanical	3.0
Electrical	4.0
Structural	3.0
Test Drive	3.0

Overall Vehicle Grade 3.4

Section Notes: GOOD POWER, GOOD SHIFTS. STEERS OK. BRAKES SEEM TO FADE QUICKLY BUT STOP EVENLY. LOTS OF RATTLES DUE TO LOOSE TRIM. WARNING LIGHTS DO NOT WORK BUT GAUGES OPERATE.

Inspectors Notes: VEHICLE HAS HAD A PRIOR DEEP BODY OFF RESTORATION BUT NOT A FRAME OFF. THERE IS VERY VISIBLE EVIDENCE OF A RECENT RESPRAY BECAUSE OF THE UNPROFESSIONAL TAPE LINES WHICH REALLY TAKE AWAY FROM THE BEAUTY OF THE CAR OVERALL. LOOSE TRIM IS EVERYWHERE ON THE VEHICLE FROM THE NOSE TO THE TAIL. MANY OF THE TRIM PIECES ARE HARDLY EVEN MOUNTED OR ARE JUST PUSHED INTO THE DRILLED BODY HOLES WITHOUT THE NUTS ON THE BACKS. ELECTRICAL NEEDS FURTHER CHECKED AS THE LIGHTS ARE NOT OPERATING CORRECTLY. OVERALL THE CAR IS DECENT BUT NEEDS A LOT OF LITTLE THINGS TO BE MUCH BETTER. A NUMBER 1 CAR IS THE BEST AND A 6 THE WORST. THIS CAR IS A GOOD 3.4 BUT COULD BE A SOLID 3 WITH MUCH MORE WORK.