



St Rose, Illinois 62230  
 www.TestDriveTech.com  
 Phone: 636-388-8378  
 Email: info@testdrivetech.com

# TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



## Vehicle Identification

Inspection Date: 10/11/2017

VIN 151769  
 Year: 1959  
 Make: PORSCHE  
 Model: 356  
 Mileage: 94074  
 Hours: NA

Trim: A  
 Vehicle Type: CABRIOLET  
 Number of Doors: 2  
 Engine Size: 1600CC  
 Transmission Type: MANUAL 4 SPEED  
 Driveline Type: RWD

Section Notes: VIN VERIFIED BY VIN TAG ON A-PILLAR.

How Each  
 Inspection Section Is  
 Graded

*Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.*

## Left Side Body Condition

## Right Side Body Condition

Left Front Fender	2.0
Left Hood Cowl	2.0
Left Front Door	2.0
Left Center B-Pillar	2.0
Left Rear Door	NA
Left C-Pillar	NA
Left Quarter Panel	2.0
Left Rocker Panel	2.0

Right Front Fender	2.0
Right Hood Cowl	2.0
Right Front Door	4.0
Right Center B-Pillar	2.0
Right Rear Door	NA
Right C-Pillar	NA
Right Quarter Panel	2.0
Right Rocker Panel	2.0

Section Condition Grade 2.0

Section Condition Grade 2.3

Section Notes: VEHICLE SHOWS TO HAVE A VERY NICE BODY, STRAIGHT AND SMOOTH PAINT WITH A HIGH GLOSS. RIGHT FRONT DOOR DOES NOT LATCH CLOSED. SELLER TO REPAIR IT, LIKELY A LOOSE CLIP ON INSIDE DOOR.

**Front Body Condition**

Hood	2.0
Front Bumper	2.0
Headlamps	2.0
Windshield Cowl	2.0
Front Roof Top	2.0
Section Condition Grade	2.0

**Rear Body Condition**

Trunk	2.0
Rear Bumper	2.0
Tail Lamps	2.0
Deck Cowl	2.0
Rear Roof Top	2.0
Section Condition Grade	2.0

TRUNK AND ENGINE COVER IN VERY GOOD CONDITION. BUMPERS ARE IN GOOD CONDITION. WINDSCREEN COWL AND ROOF ARE ALSO IN VERY GOOD CONDITION.

**Front Interior Condition**

Front Seat Type	BUCKETS
Dashboard Condition	2.0
Steering Wheel Condition	2.0
Driver Seat Condition	2.0
Passenger Seat Condition	2.0
Front Carpet Condition	2.0
Left Front Door Panel	2.0
Left Rear Door Panel	NA
Cargo Interior Sides	2.0
Front Center Console / Arm Rest	NA
Section Condition Grade	2.0

**Rear Interior Condition**

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	2.0
Rear Deck Condition	2.0
Rear Carpet Condition	2.0
3rd Seat Condition	NA
Right Front Door Panel	2.0
Right Rear Door Panel	NA
Trunk Area	2.0
Rear Center Console / Arm Rest	NA
Section Condition Grade	2.0

Section Notes: INTERIOR IS NICELY RESTORED. LEATHER IS SOFT, WELL DONE. ALL FASTENERS APPEAR CORRECT AND IN PLACE.

**Tire Condition**

Front Tire Size	165/80R15
Left Front Tire Tread	1.0
Right Front Tire Tread	1.0
Rear Tire Size	165/80R15
Left Rear Tire Tread	1.0
Right Rear Tire Tread	1.0
Valve Caps Present	YES
Section Condition Grade	1.0

**Wheel Condition**

Wheel Type	STEEL W CAPS
Left Front Wheel Condition	1.0
Right Front Wheel Condition	1.0
Left Rear Wheel Condition	1.0
Right Rear Wheel Condition	1.0
Spare Tire / Wheel Present	YES BUT FLAT
Jack / Emergency Tools Present	YES
Section Condition Grade	1.0

TIRES ARE BRANDNEW, WHEELS AND HUBCAPS IN GREAT CONDITION. SPARE TIRE IS FLAT AND NEEDS AIR.

**Interior Option Operation**

Left Front Seat Operation	2.0
Right Front Seat Operation	2.0
Rear Seat Operation	NA
Heater / Fan	2.0
Stereo Operation	5.0
Navigation Operation	NA
Front Seat Belts Present	NO
Rear Seat Belts Present	NO

Section Condition Grade 2.8

**Exterior Option Operation**

Left Front Window Operation	2.0
Right Front Window Operation	2.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Cargo Door Operation	2.0
Door Locks Operation	2.0
Windshield Wiper Operation	2.0
Rear Defrost Operation	NA

Section Condition Grade 2.0

Section Notes: SEATS SLIDE AS DESIGNED. WINDOWS ROLL UP AND DOWN SMOOTHLY, WING WINDOWS MOVE FREELY AND LOCK. HEATER PRODUCES HEAT. STEREO DOES NOT POWER ON. WIPERS ARE WORKING. VEHICLE NOT EQUIPPED WITH SEATBELTS

**Interior Lighting Condition**

Dash Lamps Operation	1.0
Interior Lighting Operation	1.0
Map Lights Operation	NA
Dome Lights Operation	NA
Hood Lamp Operation	NA
Seat Belt Light Operation	NA

Section Condition Grade 1.0

**Exterior Lighting Condition**

Low Beam Head Light Operation	1.0
High Beam Head Light Operation	1.0
Parking Lamp Operation	1.0
4-Way Flasher Operation	NA
Left Turn Operation	5.0
Right Turn Operation	1.0

Section Condition Grade 1.8

Section Notes: ALL LIGHTS ARE OPERATING EXCEPT LEFT TURN SIGNAL. WHEN SWITCH IS IN DOWN POSITION THE RELAY IS NOT ACTIVATED HOWEVER IS WHEN IN UP POSITION.

**Engine Mechanical Condition**

Engine Block Condition	2.0
Engine Hoses Condition	2.0
Engine Oil Leaks	2.0
Fuel Leaks	1.0
Air Filter Condition	1.0
Radiator Condition	NA

Section Condition Grade 1.6

**Transmission Mechanical Condition**

Trans Housing Condition	2.0
Tran Lines Condition	2.0
Trans Fluid Condition	2.0
Trans Fluid Leaks Condition	2.0
Trans Cooler Condition	NA
Trans Shifter Condition	2.0

Section Condition Grade 2.0

Section Notes: ENGINE AND TRANSMISISON ARE IN GOOD CONDITION. SLIDE LEAK FROM CENTER SEAL ON ENGINE BUT VERY COMMON FOR THIS VEHICLE. TRANSMISISON HAS A SLIGHT DRIP FROM DRAIN PLUG.

**Brakes Mechanical Condition**

Front Brake Material	2.0
Front Brake Rotors / Drums	2.0
Rear Brake Material	2.0
Rear Brake Rotors / Drums	2.0
Brake Lines Condition	2.0
Parking Brake Operation	2.0

Section Condition Grade 2.0

**Steering Mechanical Condition**

Rack-n-Pinion Condition	2.0
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	2.0
Alignment Condition	2.0

Section Condition Grade 2.0

VEHICLE HAS UNDERWENT A VERY THOROUGH MECHANICAL RECONDITIONING. MANY OF THE PARTS ARE NEW OR IN LIKE-NEW CONDITION. ENGINE HAS GOOD POWER, CLUTCH IS STRONG AND TRANSMISSION IS SMOOTH SHIFTING AND HOLDS GEARS.

Section Notes:

**Suspension Mechanical Condition**

Front Shocks Condition	1.0
Rear Shocks Condition	1.0
Bushings Condition	2.0
Sway Bar Links Condition	NA
Suspension Control Condition	NA
Control Arms Condition	2.0

Section Condition Grade 1.5

**Electrical Systems Condition**

Diagnostic Trouble Codes Present	NA
Check Engine Light On / Off	NA
Airbag Light On / Off	NA
ABS Light On / Off	NA
Wiring Condition	2.0
Battery Condition	1.0

Section Condition Grade 1.5

SUSPENSION IN VERY GOOD CONDITION. PROVIDES A SMOOTH RIDE AND HANDLES WELL. WIRING AND BATTERY IN GOOD CONDITION.

Section Notes:

**Unibody Frame Condition**

A,B,C,D Pillar Repair / Condition	3.0
Firewall Repair / Condition	3.0
Floor Pans Repair / Condition	3.0
Apron Repair / Condition	3.0
Inner Quarter Repair / Condition	3.0
Frame Rail Repair / Condition	3.0
Rocker Panel Repair / Condition	3.0

Section Condition Grade 3.0

**Conventional Frame Condition**

Frame Rail Repair / Condition	3.0
Cross Member Repair / Condition	NA
Radiator Core Repair / Condition	NA
Trunk Pan Repair / Condition	3.0
Spring Pod Repair / Condition	3.0
Torque Box Repair / Condition	3.0
Wheel House Repair / Condition	3.0

Section Condition Grade 3.0

Section Notes: VEHICLE HAS HAD SOME MODERATE REPAIRS DONE TO THE UNDERCARRIAGE HOWEVER STILL RETAINS THE MAJORITY OF THE ORIGINAL FLOOR PANS. THERE IS EVIDENCE OF REWELDS BUT THEY LOOK WELL DONE. EASIEST WAY TO EXPLAIN THE REPAIRS IS DONE WELL BUT NOT OVERLY DONE. APPEARS TO BE SOLID AND WELL COATED.

## Test Drive Results

Acceleration	2.0
Shifting	2.0
Steering	2.0
Braking	3.0
Ride / Handling	2.0
Rattles / Noises	2.0
Warning Lights	1.0

Section Condition Grade 2.0

## Condition Summary

Body	2.0
Interior	2.0
Features / Options	2.0
Mechanical	2.0
Electrical	2.0
Structural	3.0
Test Drive	2.0

Overall Vehicle Grade 2.1

**Section Notes:** VEHICLE DROVE AND PERFORMED WELL. GOOD STRONG ENGINE AND TRANSMISSION, HANDLING IS GOOD. BRAKES ARE A BIT WEAK HOWEVER, BEING JUST A STEP ABOVE MANUAL BRAKES THEY DO

**Inspectors Notes:** VEHICLE OVERALL HAS HAD A VERY GOOD RESTORATION IN THE RECENT PAST. THE BODY IS IN VERY GOOD CONDITION, THE INTERIOR IS WELL DONE. THE UNDERCARRIAGE IS IN GOOD CONDITION. THE VEHICLE DRIVES AND PERFORMS WELL. THIS IS A WELL RESTORED CAR BUT NOT OVERLY RESTORED.