

Front Body Condition

Hood	4.0
Front Bumper	5.0
Headlamps	4.0
Windshield Cowl	4.0
Front Roof Top	4.0

Section Condition Grade 4.2

Rear Body Condition

Trunk	4.0
Rear Bumper	4.0
Tail Lamps	4.0
Deck Cowl	4.0
Rear Roof Top	4.0

Section Condition Grade 4.0

Section Notes: HOOD HAS A FEW AREAS THAT HAVE BEEN TOUCHED UP WITH A BRUSH AND ARE ROUGH. BUMPER HAS A COUPLE OF DENTS IN IT. LAMP LENSES ARE DISCOLORED AND HOW THEIR AGE. FILLER FOUND IN SEVERAL PANELS ON THE REAR AND ROOF.

Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	3.0
Steering Wheel Condition	2.0
Driver Seat Condition	2.0
Passenger Seat Condition	2.0
Front Carpet Condition	3.0
Left Front Door Panel	3.0
Left Rear Door Panel	NA
Cargo Interior Sides	3.0
Front Center Console / Arm Rest	3.0
Section Condition Grade	2.6

Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	3.0
Rear Deck Condition	3.0
Rear Carpet Condition	3.0
3rd Seat Condition	NA
Right Front Door Panel	3.0
Right Rear Door Panel	NA
Cargo Floor & Roof	3.0
Rear Center Console / Arm Rest	NA
Section Condition Grade	3.0

Section Notes: DASH PANEL SHOWS IT AGE BUT IS STILL IN GOOD CONDITION. AFTERMARKET STEERING WHEEL. AFTERMARKET GAUGES, CENTER CONSOLE AND SHIFTER FROM ANOTHER VEHICLE. SHIFTER NOT MARKED. SEATS IN GOOD CONDITION.

Tire Condition

Front Tire Size	215/65R16
Left Front Tire Tread	2.0
Right Front Tire Tread	2.0
Rear Tire Size	215/65R16
Left Rear Tire Tread	2.0
Right Rear Tire Tread	2.0
Valve Caps Present	YES

Section Condition Grade 2.0

Wheel Condition

Wheel Type	CHROME ALLOY
Left Front Wheel Condition	2.0
Right Front Wheel Condition	2.0
Left Rear Wheel Condition	2.0
Right Rear Wheel Condition	2.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	YES

Section Condition Grade 2.0

TIRES AVERAGE, WHEELS GOOD CONDITION. FACTORY SPARE TIRE /

Section Notes: WHEEL IS PRESENT, SPARE IS DRY CRACKED

Interior Option Operation

Left Front Seat Operation	3.0
Right Front Seat Operation	3.0
Rear Seat Operation	NA
Heater / Fan	3.0
Stereo Operation	2.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	NO
 Section Condition Grade	 2.8

Exterior Option Operation

Left Front Window Operation	2.0
Right Front Window Operation	2.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Cargo Door Operation	1.0
Door Locks Operation	2.0
Windshield Wiper Operation	2.0
Rear Defrost Operation	NA
 Section Condition Grade	 1.8

Section Notes: FEATURES AND OPTIONS WORKING AS EXPECTED.

Interior Lighting Condition

Dash Lamps Operation	3.0
Interior Lighting Operation	NA
Map Lights Operation	NA
Dome Lights Operation	NA
Hood Lamp Operation	NA
Seat Belt Light Operation	NA
 Section Condition Grade	 3.0

Exterior Lighting Condition

Low Beam Head Light Operation	1.0
High Beam Head Light Operation	1.0
Parking Lamp Operation	1.0
4-Way Flasher Operation	NA
Left Turn Operation	1.0
Right Turn Operation	1.0
 Section Condition Grade	 1.0

Section Notes: LIGHTS AND GAUGES WORKING AS DESIGNED.

Engine Mechanical Condition

Engine Block Condition	2.0
Engine Hoses Condition	2.0
Engine Oil Leaks	2.0
Fuel Leaks	1.0
Air Filter Condition	1.0
Radiator Condition	1.0
 Section Condition Grade	 1.5

Transmission Mechanical Condition

Trans Housing Condition	2.0
Tran Lines Condition	2.0
Trans Fluid Condition	2.0
Trans Fluid Leaks Condition	3.0
Trans Cooler Condition	1.0
Trans Shifter Condition	4.0
 Section Condition Grade	 2.3

Section Notes: ENGINE STARTS EASY, IDLES AND RUNS GOOD THROUGH RPM RANGES.
TRANSMISSION SHIFTS EASY HOWEVER THERE IS NO MARKINGS ON SHIFTER CONSOLE. SLIGHT LEAK COMING FROM SPEEDO CABLE ON TRANSMISSION HOUSING (SELLER HAS REPLACEMENT PART)

Test Drive Results

Acceleration	3.0
Shifting	3.0
Steering	3.0
Braking	4.0
Ride / Handling	3.0
Rattles / Noises	5.0
Warning Lights	1.0

Section Condition Grade 3.1

Condition Summary

Body	4.1
Interior	2.8
Features / Options	3.5
Mechanical	3.5
Electrical	3.5
Structural	3.7
Test Drive	3.1

Overall Vehicle Grade 3.5

Section Notes: GOOD POWER, RUNS WELL AND DRIVES WELL. BRAKES FAIR FOR DRUM BRAKES. EXHAUST RATTLES UNDER FLOORS.

Inspectors Notes: OVERALL THE CAR SHOWS IT AGE. THE BODY WORK IS SUB PAR AND COULD BE MUCH NICER INCLUDING THE BODY FILLER AND PAINT. THE INTERIOR IS NICELY DONE AS WELL AS THE ENGINE COMPARTMENT. THIS WOULD MAKE A GOOD PROJECT CAR OR DAILY DRIVER HOWEVER WILL NEED SOME BODY WORK AND UNDERCARRIAGE WORK TO BE MUCH NICER IN THE FUTURE.