



St Rose, Illinois 62230
 www.TestDriveTech.com
 Phone: 636-388-8378
 Email: info@testdrivetech.com

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 10/26/2017

VIN 233203989	Trim: POP UP CAMPER
Year: 1973	Vehicle Type: CAMPER
Make: VOLKSWAGEN	Number of Doors: 2
Model: CAMPER BUS	Engine Size: 4 CLY
Mileage: 21046 (TMU)	Transmission Type: MANUAL
Hours: NA	Driveline Type: RWD

Section Notes: VIN VERIFIED WINDSHIELD TAG AND BY DOOR JAM TAG.

How Each
 Inspection Section Is
 Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

Left Front Fender	2.0	Right Front Fender	2.0
Left Hood Cowl	2.0	Right Hood Cowl	2.0
Left Front Door	2.0	Right Front Door	2.0
Left Center B-Pillar	NA	Right Center B-Pillar	NA
Left Rear Door	NA	Right Rear Door	NA
Left C-Pillar	2.0	Right C-Pillar	2.0
Left Quarter Panel	2.0	Right Quarter Panel	2.0
Left Rocker Panel	3.0	Right Rocker Panel	3.0

Section Condition Grade	2.2	Section Condition Grade	2.2
-------------------------	-----	-------------------------	-----

Section Notes: BODY PANELS ARE IN GOOD CONDITION. FILLER IN SEVERAL PANELS BUT MOST OF THE BODY IS SOLID. FOUND LARGER AMOUNTS OF FILLER IN LOWER SIDE PANELS (ROCKERS). FINISH IS GOOD AND BODY LINES ARE GOOD.

Front Body Condition

Hood	2.0
Front Bumper	2.0
Headlamps	2.0
Windshield Cowl	2.0
Front Roof Top	2.0
Section Condition Grade	2.0

Rear Body Condition

Trunk	NA
Rear Bumper	2.0
Tail Lamps	2.0
Deck Cowl	2.0
Rear Roof Top	2.0
Section Condition Grade	2.0

VEHICLE BODY IS IN GOOD CONDITION. REPAIRS HAVE BEEN DONE.

Section Notes: SOME FILLER FOUND THROUGHOUT BUT HELPS MAKE THE BODY STRAIGHT AND SOUND.

Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	2.0
Steering Wheel Condition	5.0
Driver Seat Condition	2.0
Passenger Seat Condition	2.0
Front Carpet Condition	2.0
Left Front Door Panel	2.0
Left Rear Door Panel	NA
Cargo Interior Sides	2.0
Front Center Console / Arm Rest	NA
Section Condition Grade	2.4

Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	2.0
Rear Deck Condition	NA
Rear Carpet Condition	NA
3rd Seat Condition	NA
Right Front Door Panel	2.0
Right Rear Door Panel	2.0
Cargo Floor & Roof	2.0
Rear Center Console / Arm Rest	NA
Section Condition Grade	2.0

Section Notes: STEERING WHEEL AREA AROUND HORN IS CRACKED. INTERIOR IS IN GOOD CONDITION. REAR FLOOR HAS BEEN REDONE WITH LAMINATE FLOORING. SUGGEST PUTTING CAP EDGING ON FLOOR NEAR SIDE DOOR FOR PROTECTION.

Tire Condition

Front Tire Size	14 INCH
Left Front Tire Tread	2.0
Right Front Tire Tread	2.0
Rear Tire Size	14 INCH
Left Rear Tire Tread	2.0
Right Rear Tire Tread	2.0
Valve Caps Present	YES
Section Condition Grade	2.0

Wheel Condition

Wheel Type	STEEL W CAPS
Left Front Wheel Condition	2.0
Right Front Wheel Condition	2.0
Left Rear Wheel Condition	2.0
Right Rear Wheel Condition	2.0
Spare Tire / Wheel Present	NO
Jack / Emergency Tools Present	NO
Section Condition Grade	2.0

TIRES AND WHEELS IN GOOD CONDITION. NO SPARE OR TOOLS WITH

Section Notes: VEHICLE

Interior Option Operation

Left Front Seat Operation	3.0
Right Front Seat Operation	3.0
Rear Seat Operation	NA
Heater / Fan	3.0
Stereo Operation	6.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	NO

Section Condition Grade 3.8

Exterior Option Operation

Left Front Window Operation	2.0
Right Front Window Operation	2.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Cargo Door Operation	2.0
Door Locks Operation	2.0
Windshield Wiper Operation	5.0
Rear Defrost Operation	NA

Section Condition Grade 2.6

SEATS, LOCKS AND WINDOWS ALL MANUAL. THEY ALL WORK OK

Section Notes: HOWEVER SEAT TRACKES NEED LUBED. STEREO IS INOPERABLE. STEREO LACKS SPEAKERS. WIPERS DO NOT WORK FULLY. HORN IS INOPERABLE.

Interior Lighting Condition

Dash Lamps Operation	3.0
Interior Lighting Operation	3.0
Map Lights Operation	NA
Dome Lights Operation	3.0
Hood Lamp Operation	NA
Seat Belt Light Operation	NA

Section Condition Grade 3.0

Exterior Lighting Condition

Low Beam Head Light Operation	2.0
High Beam Head Light Operation	2.0
Parking Lamp Operation	2.0
4-Way Flasher Operation	2.0
Left Turn Operation	2.0
Right Turn Operation	2.0

Section Condition Grade 2.0

Section Notes: LIGHTS ALL WORK WELL. 3 OF THE 4 SIDE LENS NEED REPLACED BECAUSE THEY ARE FADED TO CLEAR.

Engine Mechanical Condition

Engine Block Condition	2.0
Engine Hoses Condition	2.0
Engine Oil Leaks	1.0
Fuel Leaks	1.0
Air Filter Condition	2.0
Radiator Condition	NA

Section Condition Grade 1.6

Transmission Mechanical Condition

Trans Housing Condition	2.0
Tran Lines Condition	2.0
Trans Fluid Condition	2.0
Trans Fluid Leaks Condition	1.0
Trans Cooler Condition	NA
Trans Shifter Condition	2.0

Section Condition Grade 1.8

Section Notes: ENGINE, TRANSMISSION IN VERY GOOD CONDITION. ALL FACTORY PARTS PRESENT. SOME WIRING IN ENGINE BAY COULD BE BETTER BUT IS OK.

Brakes Mechanical Condition

Front Brake Material	3.0
Front Brake Rotors / Drums	3.0
Rear Brake Material	3.0
Rear Brake Rotors / Drums	3.0
Brake Lines Condition	3.0
Parking Brake Operation	1.0
Section Condition Grade	2.7

Steering Mechanical Condition

Rack-n-Pinion Condition	NA
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	2.0
Alignment Condition	2.0
Section Condition Grade	2.0

Section Notes: VEHICLE STOPS WELL AND STRAIGHT. STEERING IN GOOD CONDITION. NO CATCHING NO PULLING.

Suspension Mechanical Condition

Front Shocks Condition	2.0
Rear Shocks Condition	2.0
Bushings Condition	3.0
Sway Bar Links Condition	NA
Suspension Control Condition	NA
Control Arms Condition	3.0
Section Condition Grade	2.5

Electrical Systems Condition

Diagnostic Trouble Codes Present	NA
Check Engine Light On / Off	NA
Airbag Light On / Off	NA
ABS Light On / Off	NA
Wiring Condition	3.0
Battery Condition	3.0
Section Condition Grade	3.0

SUSPENSION IN GOOD CONDITION. BUSHINGS AND RUBBERS SHOW

Section Notes: THEIR AGE BUT STILL OK. WIRING IN SOME AREAS NEEDS CLEANED UP BUT STILL OK. BATTERY FOR CAMPER IS MISSING. VEHICLE STARTS EASILY.

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	3.0
Firewall Repair / Condition	3.0
Floor Pans Repair / Condition	3.0
Apron Repair / Condition	3.0
Inner Quarter Repair / Condition	5.0
Frame Rail Repair / Condition	3.0
Rocker Panel Repair / Condition	3.0
Section Condition Grade	3.3

Conventional Frame Condition

Frame Rail Repair / Condition	3.0
Cross Member Repair / Condition	3.0
Radiator Core Repair / Condition	NA
Trunk Pan Repair / Condition	NA
Spring Pod Repair / Condition	3.0
Torque Box Repair / Condition	NA
Wheel House Repair / Condition	5.0
Section Condition Grade	3.5

Section Notes: UNDERCARRIAGE SHOWS AGE HOWEVER, IS VERY SOLID, RUST AND CORROSION FREE IN MOST AREAS EXPECT FOR UNDERNEATH BATTERY TRAY WHICH SHOWS TO HAVE RUSTED THROUGH.

Test Drive Results

Acceleration	2.0
Shifting	2.0
Steering	2.0
Braking	2.0
Ride / Handling	2.0
Rattles / Noises	2.0
Warning Lights	1.0

Section Condition Grade 1.9

Condition Summary

Body	2.2
Interior	2.5
Features / Options	4.0
Mechanical	2.0
Electrical	2.0
Structural	3.5
Test Drive	1.9

Overall Vehicle Grade 2.6

Section Notes: VEHICLE STARTS UP EASY. VEHICLE RUNS WELL. STEERS EASY, STOPS SMOOTH, SHIFTS SMOOTH, RIDES WELL AND RUNS GOOD.

Inspectors Notes: OVERALL THIS IS CAMPER BUS IS IN GOOD CONDITION. IT DOES NEED SOME TLC AND SOME MINOR REPAIRS SUCH AS THE HORN, WIPERS, SCREEN ON PASSENGER SIDE REAR WINDOW, RUST HOLE IN RR UNDER BATTERY, NEW SIDE LAMP LENSES, SPEAKERS FOR RADIO AND A BATTERY FOR THE CAMPER. COULD ALSO USE SOME TIDYING OF THE WIRING BUT OVERALL A GOOD CAMPER VAN.