



St Rose, Illinois 62230

www.TestDriveTech.com

Phone: 636-388-8378

Email: info@testdrivetech.com

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 10/23/2017

VIN WBACK73431LJ15316
Year: 2001
Make: BMW
Model: Z3
Mileage: 66361
Hours: NA

Trim: 3.0i
Vehicle Type: COUPE
Number of Doors: 2
Engine Size: 3.0 L
Transmission Type: MANUAL 5 SPEED
Driveline Type: RWD

Section Notes: VIN VERIFIED BY DOOR TAG AND WINDSHIELD TAG

How Each
Inspection Section Is
Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

| | |
|--------------------------|-----|
| Left Front Fender | 2.0 |
| Left Windshield A-Pillar | 2.0 |
| Left Front Door | 2.0 |
| Left Center B-Pillar | NA |
| Left Rear Door | NA |
| Left C-Pillar | 2.0 |
| Left Quarter Panel | 3.0 |
| Left Rocker Panel | 2.0 |

| | |
|---------------------------|-----|
| Right Front Fender | 2.0 |
| Right Windshield A-Pillar | 2.0 |
| Right Front Door | 3.0 |
| Right Center B-Pillar | NA |
| Right Rear Door | NA |
| Right C-Pillar | 2.0 |
| Right Quarter Panel | 3.0 |
| Right Rocker Panel | 2.0 |

Section Condition Grade 2.2

Section Condition Grade 2.3

Section Notes: VEHICLE FINISH IS IN GOOD CONDITION. SHOWS A REPAINT OF THE LEFT REAR QUARTER PANEL, REAR BUMPER AND RIGHT REAR QUARTER PANEL.

Front Body Condition

| | |
|-------------------------|-----|
| Hood | 3.0 |
| Front Bumper | 4.0 |
| Headlamps | 3.0 |
| Windshield Cowl | 2.0 |
| Front Roof Top | 2.0 |
| Section Condition Grade | 2.8 |

Rear Body Condition

| | |
|-------------------------|-----|
| Trunk | 2.0 |
| Rear Bumper | 3.0 |
| Tail Lamps | 2.0 |
| Deck Cowl | 2.0 |
| Rear Roof Top | 2.0 |
| Section Condition Grade | 2.2 |

Section Notes: VEHICLE FINISH IS IN GOOD CONDITION. SHOWS A REPAINT OF THE LEFT REAR QUARTER PANEL, REAR BUMPER AND RIGHT REAR QUARTER PANEL AS WELL AS SOME TOUCHUPS ON THE HOOD. FRONT BUMPER DENTED FROM LOW CLEARANCE TO GROUND ISSUES.

Front Interior Condition

| | |
|---------------------------------|---------|
| Front Seat Type | BUCKETS |
| Dashboard Condition | 2.0 |
| Steering Wheel Condition | 2.0 |
| Driver Seat Condition | 4.0 |
| Passenger Seat Condition | 2.0 |
| Front Carpet Condition | 2.0 |
| Left Front Door Panel | 2.0 |
| Left Rear Door Panel | NA |
| Cargo Interior Sides | 2.0 |
| Front Center Console / Arm Rest | 2.0 |
| Section Condition Grade | 2.3 |

Rear Interior Condition

| | |
|--------------------------------|-----|
| Rear Seat Type | NA |
| 3rd Seat Present | NA |
| Rear Seat Condition | NA |
| Rear Deck Condition | NA |
| Rear Carpet Condition | 2.0 |
| 3rd Seat Condition | NA |
| Right Front Door Panel | 2.0 |
| Right Rear Door Panel | NA |
| Cargo Floor & Roof | 2.0 |
| Rear Center Console / Arm Rest | NA |
| Section Condition Grade | 2.0 |

Section Notes: INTERIOR IS NICE AND CLEAN, FREE OF ODORS. DRIVER SEAT TRACK HAS SLIGHT PLAY BUT NOT EXCESSIVE. DRIVER SEAT SHOWS WEAR AND TEAR.

Tire Condition

| | |
|-------------------------|-----------|
| Tire Brand | TOYO |
| Front Tire Size | 225/45R17 |
| Left Front Tire Tread | 3.0 |
| Right Front Tire Tread | 3.0 |
| Rear Tire Size | 245/40R17 |
| Left Rear Tire Tread | 3.0 |
| Right Rear Tire Tread | 3.0 |
| Section Condition Grade | 3.0 |

Wheel Condition

| | |
|--------------------------------|-------|
| Wheel Type | ALLOY |
| Left Front Wheel Condition | 2.0 |
| Right Front Wheel Condition | 2.0 |
| Left Rear Wheel Condition | 2.0 |
| Right Rear Wheel Condition | 2.0 |
| Spare Tire / Wheel Present | YES |
| Jack / Emergency Tools Present | YES |
| Section Condition Grade | 2.0 |

Section Notes: TIRES SHOW TO HAVE ABOUT 60% TREAD REMAINING. SIZES ARE CORRECT AND WHEELS ARE IN GOOD CONDITION.

Interior Option Operation

| | |
|----------------------------|-----|
| Left Front Seat Operation | 3.0 |
| Right Front Seat Operation | 2.0 |
| Rear Seat Operation | NA |
| 3rd Seat Operation | NA |
| Stereo Operation | 2.0 |
| Navigation Operation | NA |
| Front Seat Belts Present | YES |
| Rear Seat Belts Present | NA |
| Section Condition Grade | 2.3 |

Exterior Option Operation

| | |
|------------------------------|-----|
| Left Front Window Operation | 2.0 |
| Right Front Window Operation | 2.0 |
| Left Rear Window Operation | 2.0 |
| Right Rear Window Operation | 2.0 |
| Cargo Door Operation | 2.0 |
| Door Locks Operation | 2.0 |
| Windshield Wiper Operation | 2.0 |
| Rear Defrost Operation | 2.0 |
| Section Condition Grade | 2.0 |

Section Notes: DRIVER SEAT HAS SLIGHT PLAY IN TRACK FORWARD AND AFT.

Interior Lighting Condition

| | |
|-----------------------------|-----|
| Dash Lamps Operation | 1.0 |
| Interior Lighting Operation | 1.0 |
| Map Lights Operation | 1.0 |
| Dome Lights Operation | 1.0 |
| Hood Lamp Operation | 1.0 |
| Seat Belt Light Operation | 1.0 |
| Section Condition Grade | 1.0 |

Exterior Lighting Condition

| | |
|--------------------------------|-----|
| Low Beam Head Light Operation | 1.0 |
| High Beam Head Light Operation | 1.0 |
| Parking Lamp Operation | 1.0 |
| 4-Way Flasher Operation | 1.0 |
| Left Turn Operation | 1.0 |
| Right Turn Operation | 1.0 |
| Section Condition Grade | 1.0 |

Section Notes: LIGHTS WORKING WELL. WIRING IN GOOD CONDITION.

Engine Mechanical Condition

| | |
|-------------------------|-----|
| Engine Block Condition | 2.0 |
| Engine Hoses Condition | 2.0 |
| Engine Oil Leaks | 2.0 |
| Fuel Leaks | 1.0 |
| Air Filter Condition | 1.0 |
| Radiator Condition | 1.0 |
| Section Condition Grade | 1.5 |

Transmission Mechanical Condition

| | |
|-----------------------------|-----|
| Trans Housing Condition | 2.0 |
| Tran Lines Condition | 2.0 |
| Trans Fluid Condition | 2.0 |
| Trans Fluid Leaks Condition | 1.0 |
| Trans Cooler Condition | 2.0 |
| Trans Shifter Condition | 2.0 |
| Section Condition Grade | 1.8 |

Section Notes: POWERTRAIN APPEAR TO BE IN GOOD CONDITION. ENGINE UNDER COVER IS DRY. NO LEAKS OR ISSUES FOUND. BELTS ARE IN GOOD CONDITION AS WELL AS WIRING. ALL FLUIDS FULL. HEAT SHEILD NEAR PASSENGER SIDE MANIFOLD IS VIBRATING WHEN AC COMPRESSOR IS ON OR AT SLIGHT REV.

Brakes Mechanical Condition

| | |
|----------------------------|-----|
| Front Brake Material | 3.0 |
| Front Brake Rotors / Drums | 3.0 |
| Rear Brake Material | 3.0 |
| Rear Brake Rotors / Drums | 3.0 |
| Brake Lines Condition | 3.0 |
| Parking Brake Operation | 3.0 |
| Section Condition Grade | 3.0 |

Steering Mechanical Condition

| | |
|----------------------------|-----|
| Rack-n-Pinion Condition | 2.0 |
| Tie Rods Condition | 2.0 |
| Steering Linkage Condition | 2.0 |
| Steering Column Condition | 2.0 |
| Pump / Gearbox Condition | 2.0 |
| Alignment Condition | 1.0 |
| Section Condition Grade | 1.8 |

Section Notes: FRONT AND REAR BRAKE PADS HAVE ABOUT 50% LIFE. ROTORS ARE ORIGINAL AND NOT MACHINED OR TURNED. NO PULLING OR

Suspension Mechanical Condition

| | |
|------------------------------|-----|
| Front Shocks Condition | 3.0 |
| Rear Shocks Condition | 1.0 |
| Bushings Condition | 3.0 |
| Sway Bar Links Condition | 1.0 |
| Suspension Control Condition | NA |
| Control Arms Condition | 2.0 |
| Section Condition Grade | 2.0 |

Electrical Systems Condition

| | |
|----------------------------------|-----|
| Diagnostic Trouble Codes Present | NO |
| Check Engine Light On / Off | OFF |
| Airbag Light On / Off | OFF |
| ABS Light On / Off | OFF |
| Wiring Condition | 2.0 |
| Battery Condition | 2.0 |
| Section Condition Grade | 2.0 |

Section Notes: SUSPENSION IN GOOD CONDITION. REAR SWAY BAR LINK BUSHINGS SHOW WEAR BUT ARE STILL OK. FRONT SWAY BAR LINKS ARE NEW, REAR SHOCKS ARE NEW. ELECTRICAL IS IN GOOD CONDITION NO ISSUES TO REPORT. OBD II SYSTEM SCAN CLEAR, ALL SYSTEM

Unibody Frame Condition

| | |
|-----------------------------------|-----|
| A,B,C,D Pillar Repair / Condition | 2.0 |
| Firewall Repair / Condition | 2.0 |
| Floor Pans Repair / Condition | 4.0 |
| Apron Repair / Condition | 2.0 |
| Inner Quarter Repair / Condition | 2.0 |
| Frame Rail Repair / Condition | 3.0 |
| Rocker Panel Repair / Condition | 4.0 |
| Section Condition Grade | 2.7 |

Conventional Frame Condition

| | |
|----------------------------------|-----|
| Frame Rail Repair / Condition | 2.0 |
| Cross Member Repair / Condition | 2.0 |
| Radiator Core Repair / Condition | 2.0 |
| Trunk Pan Repair / Condition | 2.0 |
| Spring Pod Repair / Condition | 2.0 |
| Torque Box Repair / Condition | 2.0 |
| Wheel House Repair / Condition | 2.0 |
| Section Condition Grade | 2.0 |

Section Notes: UNDERCARRIAGE IS IN GOOD CONDITION FOR AGE OF VEHICLE. NO CORROSION. LOOKS SOLID. NO REPAIRS. REAR PAN AND SUBFRAME ARE IN GOOD CONDITION AND DO NOT SHOW SIGNS OF PULLING SPOT WELDS AT THIS TIME. SHOWS A COUPLE INSTANCES OF HITTING GROUND.

Test Drive Results

| | |
|-------------------------|-----|
| Acceleration | 2.0 |
| Shifting | 3.0 |
| Steering | 2.0 |
| Braking | 3.0 |
| Ride / Handling | 2.0 |
| Rattles / Noises | 3.0 |
| Warning Lights | 1.0 |
| Section Condition Grade | 2.3 |

Condition Summary

| | |
|--------------------|-----|
| Body | 2.5 |
| Interior | 2.1 |
| Features / Options | 2.0 |
| Mechanical | 2.5 |
| Electrical | 2.0 |
| Structural | 2.4 |
| Test Drive | 2.3 |

| | |
|-----------------------|-----|
| Overall Vehicle Grade | 2.2 |
|-----------------------|-----|

Section Notes: GOOD POWER, GEARBOX A BIT CATCHY DURING SHIFTS, CLUTCH FEELS A BIT WORN, STEERS AND BRAKES AS DESIGNED. VIBRATION NOISE FROM HEAT SHIELD PRESENT.

Inspectors Notes: VEHICLE IS IN GOOD CONDITON. IT DOES SHOW A BIT OF WEAR AND TEAR AND SOME PREVIOUS REPAIRS TO THE REAR HALF OF THE CAR BODY. THE VEHICLE DRIVES GOOD BUT FEELS THE MILEAGE ON THE CAR. UNDERCARRIAGE IS CLEAN BUT SHOWS A FEW AREAS OF CONTACT WITH THE ROAD.