



WWW.
TESTDRIVETECH
Vehicle Inspection Services .COM

St Rose, Illinois 62230

www.TestDriveTech.com

Phone: 636-388-8378

Email: info@testdrivetech.com

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 10/10/2017

VIN 4USCK73492LJ16095
Year: 2002
Make: BMW
Model: Z3
Mileage: 60598
Hours: NA

Trim: GAS
Vehicle Type: COUPE
Number of Doors: 2
Engine Size: 3.0 L
Transmission Type: MANUAL 5 SPEED
Driveline Type: RWD

Section Notes: VIN VERIFIED BY DOOR TAG AND WINDSHIELD TAG

How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

Left Front Fender	2.0
Left Windshield A-Pillar	2.0
Left Front Door	2.0
Left Center B-Pillar	NA
Left Rear Door	NA
Left C-Pillar	2.0
Left Quarter Panel	2.0
Left Rocker Panel	2.0

Right Front Fender	2.0
Right Windshield A-Pillar	2.0
Right Front Door	3.0
Right Center B-Pillar	NA
Right Rear Door	NA
Right C-Pillar	2.0
Right Quarter Panel	2.0
Right Rocker Panel	2.0

Section Condition Grade 2.0

Section Condition Grade 2.2

Section Notes: VEHICLE FINISH IS IN GOOD CONDITION. SHOWS A COUPLE DINGS AND CHIPS TO BE EXPECTED WITH THE MILEAGE SHOWN.

Front Body Condition

Hood	3.0
Front Bumper	3.0
Headlamps	3.0
Windshield Cowl	2.0
Front Roof Top	2.0
Section Condition Grade	2.6

Rear Body Condition

Trunk	2.0
Rear Bumper	3.0
Tail Lamps	2.0
Deck Cowl	2.0
Rear Roof Top	2.0
Section Condition Grade	2.2

Section Notes: VEHICLE SHOWS SOME LIGHT CHIPPING ON THE FRONT EDGE OF THE HOOD AND BUMPER AS WELL AS SOME SCRATCHING ON THE LOWER EDGE OF THE FRONT BUMPER. REAR BUMPER HAS A COUPLE SCRATCHES ON THE LEFT REAR CORNER. SOME LIGHT PEELING OF CHROME CLAD ON CARGO DOOR TRIM.

Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	2.0
Steering Wheel Condition	2.0
Driver Seat Condition	4.0
Passenger Seat Condition	2.0
Front Carpet Condition	2.0
Left Front Door Panel	2.0
Left Rear Door Panel	NA
Cargo Interior Sides	2.0
Front Center Console / Arm Rest	2.0
Section Condition Grade	2.3

Rear Interior Condition

Rear Seat Type	NA
3rd Seat Present	NA
Rear Seat Condition	NA
Rear Deck Condition	NA
Rear Carpet Condition	2.0
3rd Seat Condition	NA
Right Front Door Panel	2.0
Right Rear Door Panel	NA
Cargo Floor & Roof	2.0
Rear Center Console / Arm Rest	NA
Section Condition Grade	2.0

Section Notes: INTERIOR IS NICE AND CLEAN, FREE OF ODORS. DRIVER'S SEAT TRACK BUSHINGS ARE WORN AND ALLOWING THE SEAT TO SLIDE IN THE TRACK. DEALER STATES THEY WILL BE REPAIRING THIS AND HAVE THE PARTS ON HAND.

Tire Condition

Tire Brand	GOODYEAR
Front Tire Size	225/45R17
Left Front Tire Tread	2.0
Right Front Tire Tread	2.0
Rear Tire Size	245/40R17
Left Rear Tire Tread	2.0
Right Rear Tire Tread	2.0
Section Condition Grade	2.0

Wheel Condition

Wheel Type	ALLOY
Left Front Wheel Condition	2.0
Right Front Wheel Condition	2.0
Left Rear Wheel Condition	2.0
Right Rear Wheel Condition	2.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	YES
Section Condition Grade	2.0

Section Notes: TIRES SHOW TO BE NEWER BUT NOT BRAND NEW. WHEELS ARE IN GOOD CONDITION.

Interior Option Operation

Left Front Seat Operation	4.0
Right Front Seat Operation	2.0
Rear Seat Operation	NA
3rd Seat Operation	NA
Stereo Operation	4.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	NA
Section Condition Grade	3.3

Exterior Option Operation

Left Front Window Operation	2.0
Right Front Window Operation	2.0
Left Rear Window Operation	2.0
Right Rear Window Operation	2.0
Cargo Door Operation	2.0
Door Locks Operation	2.0
Windshield Wiper Operation	2.0
Rear Defrost Operation	2.0
Section Condition Grade	2.0

Section Notes: DRIVER SEAT HAS PLAY IN TRACK FORWARD AND AFT. STEREO IS CURRENTLY LOCKED OUT AND NEEDS CODE TO RESET DUE TO

Interior Lighting Condition

Dash Lamps Operation	1.0
Interior Lighting Operation	1.0
Map Lights Operation	1.0
Dome Lights Operation	1.0
Hood Lamp Operation	1.0
Seat Belt Light Operation	1.0
Section Condition Grade	1.0

Exterior Lighting Condition

Low Beam Head Light Operation	1.0
High Beam Head Light Operation	1.0
Parking Lamp Operation	1.0
4-Way Flasher Operation	1.0
Left Turn Operation	1.0
Right Turn Operation	1.0
Section Condition Grade	1.0

Section Notes: LIGHTS WORKING WELL. WIRING IN GOOD CONDITION.

Engine Mechanical Condition

Engine Block Condition	2.0
Engine Hoses Condition	2.0
Engine Oil Leaks	2.0
Fuel Leaks	1.0
Air Filter Condition	1.0
Radiator Condition	1.0
Section Condition Grade	1.5

Transmission Mechanical Condition

Trans Housing Condition	2.0
Tran Lines Condition	2.0
Trans Fluid Condition	2.0
Trans Fluid Leaks Condition	1.0
Trans Cooler Condition	2.0
Trans Shifter Condition	2.0
Section Condition Grade	1.8

Section Notes: POWERTRAIN APPEAR TO BE IN GOOD CONDITION. ENGINE UNDER COVER IS DRY. NO LEAKS OR ISSUES FOUND. BELTS ARE IN GOOD CONDITION AS WELL AS WIRING. ALL FLUIDS FULL.

Brakes Mechanical Condition

Front Brake Material	2.0
Front Brake Rotors / Drums	2.0
Rear Brake Material	2.0
Rear Brake Rotors / Drums	2.0
Brake Lines Condition	2.0
Parking Brake Operation	2.0
Section Condition Grade	2.0

Steering Mechanical Condition

Rack-n-Pinion Condition	2.0
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	2.0
Alignment Condition	1.0
Section Condition Grade	1.8

Section Notes: FRONT AND REAR BRAKE PADS ARE NEWER (75%), ROTORS ARE ORIGINAL AND NOT MACHINED OR TURNED. NO PULLING OR

Suspension Mechanical Condition

Front Shocks Condition	2.0
Rear Shocks Condition	2.0
Bushings Condition	2.0
Sway Bar Links Condition	3.0
Suspension Control Condition	NA
Control Arms Condition	2.0
Section Condition Grade	2.2

Electrical Systems Condition

Diagnostic Trouble Codes Present	NO
Check Engine Light On / Off	OFF
Airbag Light On / Off	OFF
ABS Light On / Off	OFF
Wiring Condition	2.0
Battery Condition	2.0
Section Condition Grade	2.0

Section Notes: SUSPENSION IN GOOD CONDITION. REAR SWAY BAR LINK BUSHINGS SHOW WEAR BUT ARE STILL OK. ELECTRICAL IS IN GOOD CONDITION NO ISSUES TO REPORT. OBD II SYSTEM SCAN CLEAR, ALL SYSTEM FUNCTIONING AS DESIGNED.

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	2.0
Firewall Repair / Condition	2.0
Floor Pans Repair / Condition	2.0
Apron Repair / Condition	2.0
Inner Quarter Repair / Condition	2.0
Frame Rail Repair / Condition	2.0
Rocker Panel Repair / Condition	2.0
Section Condition Grade	2.0

Conventional Frame Condition

Frame Rail Repair / Condition	2.0
Cross Member Repair / Condition	2.0
Radiator Core Repair / Condition	2.0
Trunk Pan Repair / Condition	2.0
Spring Pod Repair / Condition	2.0
Torque Box Repair / Condition	2.0
Wheel House Repair / Condition	2.0
Section Condition Grade	2.0

Section Notes: UNDERCARRIAGE IS IN GOOD CONDITION FOR AGE OF VEHICLE. NO CORROSION. LOOKS SOLID. NO REPAIRS. REAR PAN AND SUBFRAME ARE IN GOOD CONDITION AND DO NOT SHOW SIGNS OF PULLING SPOT WELDS AT THIS TIME.

Test Drive Results

Acceleration	2.0
Shifting	2.0
Steering	2.0
Braking	2.0
Ride / Handling	2.0
Rattles / Noises	2.0
Warning Lights	1.0
Section Condition Grade	1.9

Condition Summary

Body	2.4
Interior	2.1
Features / Options	2.0
Mechanical	2.0
Electrical	2.0
Structural	2.0
Test Drive	1.9
Overall Vehicle Grade	2.0

Section Notes: GOOD POWER, GOOD SHIFTS, STEERS AND BRAKES AS DESIGNED.

Inspectors Notes: VEHICLE IS IN OVERALL GOOD CONDITION AND HAS BEEN WELL KEPT. IT DOES SHOW SOME AREAS THAT NEED IMPROVEMENT. CAR DRIVES AND PERFORMS AS DESIGNED.