



WWW.
TESTDRIVETECH
VEHICLE INSPECTION SERVICES .COM

St Rose, Illinois 62230

www.TestDriveTech.com

Phone: 636-388-8378

Email: info@testdrivetech.com

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 11/10/2017

VIN F1HLL10585
Year: 1951
Make: FORD
Model: F1
Mileage: 26,897
Hours: NA

Trim: PICKUP
Vehicle Type: TRUCK
Number of Doors: 2
Engine Size: FLAT HEAD V8
Transmission Type: 3 SPEED W/ OD
Driveline Type: RWD

Section Notes: VIN VERIFIED BY A-PILLAR TAG. FIREWALL TAG UNREADABLE.

How Each
Inspection Section Is
Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

Left Front Fender	2.0
Left Hood Cowl	2.0
Left Front Door	2.0
Left Center B-Pillar	NA
Left Rear Door	NA
Left C-Pillar	2.0
Left Side Panel	2.0
Left Rocker Panel	2.0

Right Front Fender	2.0
Right Hood Cowl	3.0
Right Front Door	2.0
Right Center B-Pillar	NA
Right Rear Door	NA
Right C-Pillar	2.0
Left Side Panel	2.0
Right Rocker Panel	2.0

Section Condition Grade 2.0

Section Condition Grade 2.2

Section Notes: PAINT IS IN GOOD CONDITION. IT DOES SHOW SOME OF ITS AGE AND THICKNESS. MAJORITY OF PANELS HAVE BEEN REPLACED. COWL ON PASSENGER SIDE HAS CRACK IN PAINT IN THE BODY SEAM.

Front Body Condition

Hood	2.0
Front Bumper	3.0
Headlamps	1.0
Windshield Cowl	2.0
Front Roof Top	2.0
Section Condition Grade	2.0

Rear Body Condition

Trunk	3.0
Rear Bumper	3.0
Tail Lamps	2.0
Deck Cowl	NA
Rear Roof Top	2.0
Section Condition Grade	2.5

PAINT IN GOOD CONDITION. FRONT BUMPER HAS ODD DUCT TAPE

Section Notes: NEAR CENTER. UNSURE WHAT IT IS COVERING. DID NOT REMOVE.

Front Interior Condition

Front Seat Type	BENCH
Dashboard Condition	1.0
Steering Wheel Condition	3.0
Driver Seat Condition	1.0
Passenger Seat Condition	1.0
Front Carpet Condition	NA
Left Front Door Panel	1.0
Left Rear Side Panel	1.0
Cargo Interior Sides	1.0
Front Center Console / Arm Rest	NA
Section Condition Grade	1.3

Rear Interior Condition

Rear Seat Type	NA
3rd Seat Present	NA
Rear Seat Condition	NA
Rear Deck Condition	NA
Rear Carpet Condition	NA
3rd Seat Condition	NA
Right Front Door Panel	1.0
Right Rear Side Panel	1.0
Truck Bed	1.0
Rear Center Console / Arm Rest	NA
Section Condition Grade	1.0

Section Notes: INTERIOR LOOKS NICE. SEAT BACK SHOWS OLD SEAT STUFFING NOT FULLY REMOVED AND IS CAUGHT UP IN THE HOG RINGS. STEERING WHEEL SHOWS IT AGE AND SLIGHT CRACKING AROUND HORN BUTTON.

Tire Condition

Front Tire Size	6.00R16
Left Front Tire Tread	1.0
Right Front Tire Tread	1.0
Rear Tire Size	6.00R16
Left Rear Tire Tread	1.0
Right Rear Tire Tread	1.0
Valve Caps Present	YES
Section Condition Grade	1.0

Wheel Condition

Wheel Type	STEEL W CAPS
Left Front Wheel Condition	1.0
Right Front Wheel Condition	1.0
Left Rear Wheel Condition	1.0
Right Rear Wheel Condition	1.0
Spare Tire / Wheel Present	NO
Jack / Emergency Tools Present	NO
Section Condition Grade	1.0

TIRES AND WHEELS IN GOOD CONDITION. NO SPARE. FOUND ONLY A

Section Notes: TOOL IN BOX ABOVE FUEL TANK.

Interior Option Operation

Front Seat Operation	1.0
	NA
Rear Seat Operation	NA
Heater / Fan	3.0
Stereo Operation	1.0
Navigation Operation	NA
Front Seat Belts Present	NA
Rear Seat Belts Present	NA
Section Condition Grade	1.7

Exterior Option Operation

Left Front Window Operation	1.0
Right Front Window Operation	1.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Cargo Door Operation	1.0
Door Locks Operation	NA
Windshield Wiper Operation	1.0
Rear Defrost Operation	NA
Section Condition Grade	1.0

Section Notes: ALL FEATURES WORKING AS DESIGNED. HEATER BLOWER FAN DOES NOT PUT OUT MUCH AIR AND HAS A SLIGHT NOISE BUT DOES KICK ON AND OPERATE.

Interior Lighting Condition

Dash Lamps Operation	1.0
Interior Lighting Operation	NA
Glove Box Lights Operation	NA
Dome Lights Operation	NA
Hood Lamp Operation	NA
Seat Belt Light Operation	NA
Section Condition Grade	1.0

Exterior Lighting Condition

Low Beam Head Light Operation	1.0
High Beam Head Light Operation	1.0
Parking Lamp Operation	1.0
4-Way Flasher Operation	NA
Left Turn Operation	1.0
Right Turn Operation	1.0
Section Condition Grade	1.0

Section Notes: ALL LIGHTS WORKING AS DESIGNED

Engine Mechanical Condition

Engine Block Condition	1.0
Engine Hoses Condition	1.0
Engine Oil Leaks	3.0
Fuel Leaks	1.0
Air Filter Condition	1.0
Radiator Condition	1.0
Section Condition Grade	1.3

Transmission Mechanical Condition

Trans Housing Condition	1.0
Tran Lines Condition	NA
Trans Fluid Condition	NA
Trans Fluid Leaks Condition	3.0
Trans Cooler Condition	NA
Trans Shifter Condition	5.0
Overdrive Condition	1.0
Section Condition Grade	3.0

Section Notes: ENGINE, TRANSMISSION IN VERY GOOD CONDITION. SOME SMALL SLIGHT LEAKAGE NOTICED FROM REAR OF ENGINE AND CENTER OF TRANSMISSION BUT NOTHING MAJOR. TRANSMISSION VERY HARD TO GET INTO REVERSE. ALL OTHER GEARS OK. OVERDRIVE WORKS. ENGINE SERIAL NUMBER IS UNREADABLE, TRANSMISSION ONLY SHOWED CASTING NUMBERS. AXLE ONLY HAS PATENT NUMBER.

Brakes Mechanical Condition

Front Brake Material	1.0
Front Brake Rotors / Drums	1.0
Rear Brake Material	1.0
Rear Brake Rotors / Drums	1.0
Brake Lines Condition	1.0
Parking Brake Operation	1.0
Section Condition Grade	1.0

Steering Mechanical Condition

Rack-n-Pinion Condition	NA
Tie Rods Condition	1.0
Steering Linkage Condition	1.0
Steering Column Condition	1.0
Pump / Gearbox Condition	NA
Alignment Condition	1.0
Section Condition Grade	1.0

Section Notes: VEHICLE STOPS WELL AND STRAIGHT. STEERING IN GOOD CONDITION. NO CATCHING NO PULLING.

Suspension Mechanical Condition

Front Shocks Condition	1.0
Rear Shocks Condition	1.0
Bushings Condition	1.0
Sway Bar Links Condition	1.0
Suspension Control Condition	1.0
Control Arms Condition	1.0
Section Condition Grade	1.0

Electrical Systems Condition

Oil Pressure Light Test	NA
Engine Coolant Light Test	NA
Seat Belt Light Test	NA
Brake Warning Lamp	NA
Wiring Condition	1.0
Battery Condition	1.0
Section Condition Grade	1.0

Section Notes: SUSPENSION IN GOOD CONDITION. HORN WORKS HOWEVER, INTERNAL BUTTON SPRING MUST BE BROKEN AS HORN WOULD NOT SHUT OFF. IT IS NOT DISCONNECTED AT THE RELAY BOX UNDER THE HOOD. DASH GAUGES DID NOT RESPOND TO KEY ON OR OFF. THEY CONTINUE TO READ IN THE CENTER WITH KEY OFF.

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	2.0
Firewall Repair / Condition	2.0
Floor Pans Repair / Condition	2.0
Apron Repair / Condition	2.0
Inner Quarter Repair / Condition	2.0
Frame Rail Repair / Condition	2.0
Rocker Panel Repair / Condition	2.0
Section Condition Grade	2.0

Conventional Frame Condition

Frame Rail Repair / Condition	2.0
Cross Member Repair / Condition	2.0
Radiator Core Repair / Condition	2.0
Trunk Pan Repair / Condition	2.0
Spring Pod Repair / Condition	2.0
Torque Box Repair / Condition	2.0
Wheel House Repair / Condition	2.0
Section Condition Grade	2.0

Section Notes: NO UNDERCARRIAGE ISSUES FOUND. UNDERCARRIAGE VERY CLEAN, NO RUST, FRAME IN VERY GOOD CONDITION.

Test Drive Results

Acceleration	3.0
Shifting	4.0
Steering	2.0
Braking	1.0
Ride / Handling	2.0
Rattles / Noises	2.0
Warning Lights	2.0

Section Condition Grade 2.3

Condition Summary

Body	3.0
Interior	3.0
Features / Options	3.0
Mechanical	3.0
Electrical	3.0
Structural	2.0
Test Drive	2.3

Overall Vehicle Grade 2.8

Section Notes: VEHICLE RUNS AND DRIVES WELL. IT STARTS GOOD FOR AGE AND SET UP. TRANSMISSION SHIFTER NEEDS ADJUSTED SO TRANS WILL GO INTO REVERSE EASIER. OVERDRIVE DOES KICK IN. VEHICLE ONLY TESTED IN PARKING LOT DUE TO DEALER POLICY.

Inspectors Notes: VEHICLE IS IN GOOD TO VERY GOOD CONDITION. IT HAS UNDERWENT A GOOD PROFESSIONAL RESTORATION BACK TO ITS ORIGINAL CONDITION SEVERAL YEARS BACK. VEHICLE DOES HAVE SOME AREAS FOR IMPROVEMENT TO BE A SOLID #2 VEHICLE. RIGHT NOW IT IS A GOOD #3.