



St Rose, Illinois 62230
 www.TestDriveTech.com
 Phone: 636-388-8378
 Email: info@testdrivetech.com

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 11/8/2017

VIN CD5309L / 5253CC
 Year: 1968
 Make: TRIUMPH
 Model: TR250
 Mileage: 9,739
 Hours: NA

Trim: 250
 Vehicle Type: CONVERTIBLE
 Number of Doors: 2
 Engine Size: INLINE 6
 Transmission Type: 4 SPEED MANUAL W/OD
 Driveline Type: RWD

Section Notes: VIN VERIFIED TRIM TAG AND FIREWALL TAG

How Each
 Inspection Section Is
 Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

Left Front Fender	1.0
Left Hood Cowl	1.0
Left Front Door	1.0
Left Center B-Pillar	NA
Left Rear Door	NA
Left C-Pillar	1.0
Left Quarter Panel	1.0
Left Rocker Panel	1.0

Right Front Fender	1.0
Right Hood Cowl	1.0
Right Front Door	1.0
Right Center B-Pillar	NA
Right Rear Door	NA
Right C-Pillar	1.0
Right Quarter Panel	1.0
Right Rocker Panel	1.0

Section Condition Grade 1.0

Section Condition Grade 1.0

Section Notes: VEHICLE BODY IS IN VERY GOOD CONDITION. SOME MINOR FILLER IN PANELS HOWEVER JUST ENOUGH TO GET A PERFECTLY SMOOTH FINISH.

Front Body Condition

Hood	2.0
Front Bumper	2.0
Headlamps	1.0
Windshield Cowl	1.0
Front Roof Top	1.0

Section Condition Grade 1.4

Rear Body Condition

Trunk	1.0
Rear Bumper	2.0
Tail Lamps	1.0
Deck Cowl	1.0
Rear Roof Top	2.0

Section Condition Grade 1.4

Section Notes: FRONT AND REAR BUMPER SHOW MINOR SCRATCHES FROM DUST ETC BUT IN GOOD CONDITION. REAR TOP (WINDOW AREA) SHOWS AGE BUT STILL INTACT AND IN GOOD CONDITION. SOME PAINT OVERSPRAY ON BOTH INNER SIDES OF HOOD WHEN IN UP POSITION COVERING SOME OF THE STRIPES. NOT NOTICABLE WITH THE HOOD DOWN.

Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	1.0
Steering Wheel Condition	1.0
Driver Seat Condition	1.0
Passenger Seat Condition	1.0
Front Carpet Condition	1.0
Left Front Door Panel	1.0
Left Rear Side Panel	1.0
Cargo Interior Sides	1.0
Front Center Console / Arm Rest	1.0
Section Condition Grade	1.0

Rear Interior Condition

Rear Seat Type	NA
3rd Seat Present	NA
Rear Seat Condition	NA
Rear Deck Condition	NA
Rear Carpet Condition	1.0
3rd Seat Condition	NA
Right Front Door Panel	1.0
Right Rear Side Panel	1.0
Cargo Floor & Roof	1.0
Rear Center Console / Arm Rest	NA
Section Condition Grade	1.0

Section Notes: INTERIOR IN VERY GOOD CONDITION.

Tire Condition

Front Tire Size	205/70R15
Left Front Tire Tread	1.0
Right Front Tire Tread	1.0
Rear Tire Size	205/70R15
Left Rear Tire Tread	1.0
Right Rear Tire Tread	1.0
Valve Caps Present	YES
Section Condition Grade	1.0

Wheel Condition

Wheel Type	ALLOY
Left Front Wheel Condition	1.0
Right Front Wheel Condition	1.0
Left Rear Wheel Condition	1.0
Right Rear Wheel Condition	1.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	YES
Section Condition Grade	1.0

Section Notes: TIRES AND WHEELS IN GOOD CONDITION.

Interior Option Operation

Left Front Seat Operation	1.0
Right Front Seat Operation	1.0
Rear Seat Operation	NA
Heater / Fan	1.0
Stereo Operation	1.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	NA
 Section Condition Grade	 1.0

Exterior Option Operation

Left Front Window Operation	1.0
Right Front Window Operation	1.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Cargo Door Operation	1.0
Door Locks Operation	1.0
Windshield Wiper Operation	1.0
Rear Defrost Operation	1.0
 Section Condition Grade	 1.0

Section Notes: ALL FEATURES WORKING AS DESIGNED.

Interior Lighting Condition

Dash Lamps Operation	1.0
Interior Lighting Operation	1.0
Glove Box Lights Operation	NA
Dome Lights Operation	NA
Hood Lamp Operation	1.0
Seat Belt Light Operation	NA
 Section Condition Grade	 1.0

Exterior Lighting Condition

Low Beam Head Light Operation	1.0
High Beam Head Light Operation	1.0
Parking Lamp Operation	1.0
4-Way Flasher Operation	1.0
Left Turn Operation	1.0
Right Turn Operation	1.0
 Section Condition Grade	 1.0

Section Notes: ALL LIGHTS WORKING AS DESIGNED

Engine Mechanical Condition

Engine Block Condition	1.0
Engine Hoses Condition	1.0
Engine Oil Leaks	1.0
Fuel Leaks	1.0
Air Filter Condition	1.0
Radiator Condition	2.0

Transmission Mechanical Condition

Trans Housing Condition	1.0
Tran Lines Condition	NA
Trans Fluid Condition	NA
Trans Fluid Leaks Condition	2.0
Trans Cooler Condition	NA
Trans Shifter Condition	1.0

Compression Test Findings #1 174; #2 160; #3 159; #4 149; #5 150; #6 148

Section Condition Grade	1.2	Section Condition Grade	1.3
-------------------------	-----	-------------------------	-----

Section Notes: ENGINE, TRANSMISSION IN VERY GOOD CONDITION. SOME SMALL SLIGHT LEAKAGE NOTICED AROUND TRANSMISSION BUT NOTHING MAJOR. APPEARS SOMEONE APPLIED CLEAR SEALANT AROUND REAR HOUSING. RADIATOR HAS A BIT OF ROUGH PATCHES NEAR FAN LIKE IT WAS BUMPED DURING INSTALLATION BUT STILL IN GOOD CONDITION. COMPRESSION TEST WELL WITHIN NORMAL. REAR CYL'S SHOW SLIGHTLY LESS AS IF THE VALVES HAVE A SLIGHT BIT OF BUILD UP BUT STILL GOOD

Brakes Mechanical Condition

Front Brake Material	1.0
Front Brake Rotors / Drums	1.0
Rear Brake Material	1.0
Rear Brake Rotors / Drums	1.0
Brake Lines Condition	1.0
Parking Brake Operation	1.0
Section Condition Grade	1.0

Steering Mechanical Condition

Rack-n-Pinion Condition	NA
Tie Rods Condition	1.0
Steering Linkage Condition	1.0
Steering Column Condition	1.0
Pump / Gearbox Condition	1.0
Alignment Condition	1.0
Section Condition Grade	1.0

Section Notes: VEHICLE STOPS WELL AND STRAIGHT. STEERING IN GOOD CONDITION.
NO CATCHING NO PULLING.

Suspension Mechanical Condition

Front Shocks Condition	1.0
Rear Shocks Condition	1.0
Bushings Condition	1.0
Sway Bar Links Condition	1.0
Suspension Control Condition	1.0
Control Arms Condition	1.0
Section Condition Grade	1.0

Electrical Systems Condition

Oil Pressure Light Test	PASS
Engine Coolant Light Test	PASS
Seat Belt Light Test	NA
Brake Warning Lamp	NA
Wiring Condition	1.0
Battery Condition	1.0
Section Condition Grade	1.0

SUSPENSION IN GOOD CONDITION. ELECTRONICS AND DIAGNOSTICS

Section Notes: CHECKED AND ARE FREE OF ISSUE.

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	1.0
Firewall Repair / Condition	1.0
Floor Pans Repair / Condition	1.0
Apron Repair / Condition	1.0
Inner Quarter Repair / Condition	1.0
Frame Rail Repair / Condition	1.0
Rocker Panel Repair / Condition	1.0
Section Condition Grade	1.0

Conventional Frame Condition

Frame Rail Repair / Condition	1.0
Cross Member Repair / Condition	1.0
Radiator Core Repair / Condition	1.0
Trunk Pan Repair / Condition	1.0
Spring Pod Repair / Condition	1.0
Torque Box Repair / Condition	1.0
Wheel House Repair / Condition	1.0
Section Condition Grade	1.0

Section Notes: NO UNDERCARRIAGE ISSUES FOUND. UNDERCARRIAGE VERY CLEAN,
NO RUST, FRAME IN VERY GOOD CONDITION.

Test Drive Results

Acceleration	1.0
Shifting	1.0
Steering	1.0
Braking	1.0
Ride / Handling	1.0
Rattles / Noises	1.0
Warning Lights	1.0
Section Condition Grade	1.0

Condition Summary

Body	1.2
Interior	1.0
Features / Options	1.0
Mechanical	1.2
Electrical	1.0
Structural	1.0
Test Drive	1.0
Overall Vehicle Grade	1.1

Section Notes: VEHICLE RUNS AND DRIVES EXCEPTIONALLY WELL. PLENTY OF POWER, GOOD SHIFTS, GOOD SOLID STOPS, NO PULLING, GOOD ALIGNMENT.

Inspectors Notes: VEHICLE IS IN EXCEPTIONAL CONDITION. IT HAS UNDERWENT A GOOD PROFESSIONAL RESTORATION BACK TO ITS ORIGINAL CONDITION AND GREAT ATTENTION TO DETAIL WAS GIVEN TO MANY AREAS WHICH INCREASE THE VALUE OF THIS VEHICLE. THE RESTORATION SHOW A VERY YOUNG AGE AS OPPOSED TO THE 8-10 THAT IS STATED BY THE DEALER. THIS CAR IS IN VERY GOOD CONDITION AND VERY CLOSE TO A FULL #1 CONCOURSE CAR