



WWW.  
**TESTDRIVETECH**  
VEHICLE INSPECTION SERVICES .COM

St Rose, Illinois 62230  
WWW.TESTDRIVETECH.COM  
PHONE: 636-388-8378  
EMAIL: INFO@TESTDRIVETECH.COM

# TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



## Vehicle Identification

Inspection Date: 11/14/2017

VIN FJ43-111044	Trim: NA
Year: 1983	Vehicle Type: SUV
Make: TOYOTA	Number of Doors: 2
Model: LAND CRUISER	Engine Size: INLINE 6
Mileage: 17,940	Transmission Type: 4 SPEED
Hours: NA	Driveline Type: 4X4

**Section Notes:** VIN VERIFIED BY STAMP ON PASSENGER SIDE FRAME RAIL

### How Each Inspection Section Is Graded

*Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.*

### Left Side Body Condition

### Right Side Body Condition

Left Front Fender	3.0	Right Front Fender	3.0
Left Hood Cowl	3.0	Right Hood Cowl	3.0
Left Front Door	4.0	Right Front Door	4.0
Left Center B-Pillar	NA	Right Center B-Pillar	NA
Left Rear Door	NA	Right Rear Door	NA
Left C-Pillar	3.0	Right C-Pillar	3.0
Left Quarter Panel	3.0	Right Quarter Panel	4.0
Left Rocker Panel	3.0	Right Rocker Panel	3.0

**Section Condition Grade** 3.2

**Section Condition Grade** 3.3

**Section Notes:** BODY PANELS MOSTLY IN GOOD CONDITION. PAINT SHOWS NICE. DRIVER AND PASSENGER SIDE DOOR HANDLES ARE BROKEN. PASSENGER SIDE QUARTER PANEL REAR CORNER HAS SOME CRACKING IN PAINT.

**Front Body Condition**

Hood	3.0
Front Bumper	3.0
Headlamps	2.0
Windshield Cowl	4.0
Front Roof Top	3.0
Section Condition Grade	3.0

**Rear Body Condition**

Cargo Doors	3.0
Rear Bumper	3.0
Tail Lamps	3.0
Deck Cowl	NA
Rear Roof Top	3.0
Section Condition Grade	3.0

HOOD IS IN GOOD CONDITION. SHOWS SOME PITTING ON THE LEADING EDGE. WINDSHIELD COWL JUST UNDER WINDOW FRAME SHOWS SOME CORROSION STARTING BUT NOT TOO DEEP YET.

**Front Interior Condition**

Front Seat Type	BUCKETS
Dashboard Condition	3.0
Steering Wheel Condition	3.0
Driver Seat Condition	3.0
Passenger Seat Condition	3.0
Front Carpet Condition	3.0
Left Front Door Panel	4.0
Left Rear Side Panel	3.0
Cargo Interior Sides	3.0
Front Center Console / Arm Rest	3.0
Section Condition Grade	3.1

**Rear Interior Condition**

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	3.0
Rear Floor Condition	3.0
Rear Carpet Condition	NA
3rd Seat Condition	NA
Right Front Door Panel	3.0
Right Rear Side Panel	3.0
Trunk Floor	3.0
Rear Center Console / Arm Rest	NA
Section Condition Grade	3.0

Section Notes: INTERIOR IS IN AVERAGE CONDITION. THE DOOR PANELS AND TRIM NEED SOME TLC.

**Tire Condition**

Front Tire Size	31X10.50R15
Left Front Tire Tread	1.0
Right Front Tire Tread	1.0
Rear Tire Size	31X10.50R15
Left Rear Tire Tread	1.0
Right Rear Tire Tread	1.0
Valve Caps Present	YES
Section Condition Grade	1.0

**Wheel Condition**

Wheel Type	SPLIT RING WHEELS
Left Front Wheel Condition	1.0
Right Front Wheel Condition	1.0
Left Rear Wheel Condition	1.0
Right Rear Wheel Condition	1.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	YES
Section Condition Grade	1.0

Section Notes: FACTORY ORIGINAL AND ARE SPLIT RINGS. USE CAUTION WHEN MOUNTING / DISMOUNTING TIRES AND WHEELS.

### Interior Option Operation

Left Front Seat Operation	1.0
Right Front Seat Operation	1.0
Rear Seat Operation	NA
Heater / Fan	2.0
Stereo Operation	6.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	NA

Section Condition Grade 2.5

### Exterior Option Operation

Left Front Window Operation	3.0
Right Front Window Operation	4.0
Left Rear Window Operation	2.0
Right Rear Window Operation	2.0
Cargo Door Operation	1.0
Door Locks Operation	YES
Windshield Wiper Operation	3.0
Rear Defrost Operation	NA

Section Condition Grade 2.5

STEREO DOES NOT POWER ON. PASSENGER SIDE WINDOW

Section Notes: VERY SLOW TO OPERATE AND NEEDS A BIT OF HELP.

### Interior Lighting Condition

Dash Lamps Operation	1.0
Interior Lighting Operation	6.0
Glove Box Lights Operation	NA
Dome Lights Operation	6.0
Hood Lamp Operation	NA
Seat Belt Light Operation	NA

Section Condition Grade 4.3

### Exterior Lighting Condition

Low Beam Head Light Operation	1.0
High Beam Head Light Operation	1.0
Parking Lamp Operation	1.0
4-Way Flasher Operation	5.0
Left Turn Operation	5.0
Right Turn Operation	5.0

Section Condition Grade 3.0

Section Notes: INTERIOR DOME LAMP WIRE IS CUT AT TOP RIGHT OF ROOF PANEL SO IT IS NOT WORKING. 4 WAY FLASHERS WORK HOWEVER REQUIRE PLAYING WITH THE TURN SIGNAL SWITCH TO OPERATE CORRECTLY. ALSO, LEFT REAR TURN BULB IS INOP AND REAR LAMP LENSES DO NO MATCH. FRONT LENSES SHOW CRACKING BUT ARE STILL INTACT.

### Engine Mechanical Condition

Engine Block Condition	2.0
Engine Hoses Condition	2.0
Engine Oil Leaks	3.0
Fuel Leaks	1.0
Air Filter Condition	1.0
Radiator Condition	1.0

Section Condition Grade 1.7

### Transmission Mechanical Condition

Trans Housing Condition	1.0
Tran Lines Condition	NA
Trans Fluid Condition	2.0
Trans Fluid Leaks Condition	3.0
Trans Cooler Condition	NA
Trans Shifter Condition	1.0
Overdrive Condition	NA

Section Condition Grade 1.8

Section Notes: ENGINE, TRANSMISSION IN GOOD CONDITION. SOME SLIGHT LEAKAGE NOTICED FROM THE ENGINE OIL PAN, TRANSMISSION REAR SEAL AND REAR AXLE SEAL AS WELL AS AROUND THE KNUCKLES ON THE FRONT AXLE.

**Brakes Mechanical Condition**

Front Brake Material	2.0
Front Brake Rotors / Drums	2.0
Rear Brake Material	2.0
Rear Brake Rotors / Drums	2.0
Brake Lines Condition	2.0
Parking Brake Operation	1.0
Section Condition Grade	1.8

**Steering Mechanical Condition**

Rack-n-Pinion Condition	NA
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	1.0
Alignment Condition	1.0
Section Condition Grade	1.6

Section Notes: VEHICLE STOPS WELL AND STRAIGHT. STEERING IN GOOD CONDITION. NO CATCHING NO PULLING.

**Suspension Mechanical Condition**

Front Shocks Condition	2.0
Rear Shocks Condition	2.0
Bushings Condition	3.0
Sway Bar Links Condition	NA
Suspension Control Condition	NA
Control Arms Condition	NA
Section Condition Grade	2.3

**Electrical Systems Condition**

Oil Pressure Light Test	YES
Engine Coolant Light Test	YES
Seat Belt Light Test	NA
Brake Warning Lamp	NA
Wiring Condition	4.0
Battery Condition	2.0
Section Condition Grade	3.0

SUSPENSION IN GOOD CONDITION OVERALL FOR AGE BUT NEEDS BUSHINGS FRESHENED UP AS MANY ARE DRY AND WORN BUT STILL PERFORMING WELL. ELECTRICAL SYSTEM TESTED AND WORKING WELL. WIRING IN FAIR CONDITION BUT NEEDS CLEANED UP AND CHECKED OVER DEEPER.

**Unibody Frame Condition**

A,B,C,D Pillar Repair / Condition	2.0
Firewall Repair / Condition	2.0
Floor Pans Repair / Condition	5.0
Apron Repair / Condition	2.0
Inner Quarter Repair / Condition	2.0
Frame Rail Repair / Condition	2.0
Rocker Panel Repair / Condition	2.0
Section Condition Grade	2.4

**Conventional Frame Condition**

Frame Rail Repair / Condition	2.0
Cross Member Repair / Condition	2.0
Radiator Core Repair / Condition	2.0
Trunk Pan Repair / Condition	2.0
Spring Pod Repair / Condition	2.0
Torque Box Repair / Condition	2.0
Wheel House Repair / Condition	2.0
Section Condition Grade	2.0

Section Notes: CRACKS IN PASSENGER SIDE FLOOR PANS FOUND. TOTALLING ABOUT 10 INCHES. THESE NEED REPAIRED SO THEY DO NOT SPREAD FURTHER AND CAUSE FURTHER DAMAGE.

## Test Drive Results

Acceleration	2.0
Shifting	2.0
Steering	2.0
Braking	1.0
Ride / Handling	2.0
Rattles / Noises	3.0
Warning Lights	3.0

Section Condition Grade 2.1

## Condition Summary

Body	3.5
Interior	3.0
Features / Options	3.5
Mechanical	3.0
Electrical	3.0
Structural	3.5
Test Drive	2.1

Overall Vehicle Grade 3.1

**Section Notes:** VEHICLE RUNS AND DRIVES WELL. HANDLES AS DESIGNED. SHIFTS GOOD BUT DOES SHOW SOME WEAR IN THE CLUTCH. STOPS WELL AND DRIVES STRAIGHT. I DID NOTICE THAT THE 4X4 WARNING LIGHT DOESN'T OPERATE WHEN IN 4X4 BUT THE INDICATOR JUST BELOW THAT WITH THE "!" TURNS OFF WHEN THE 4X4 IS ENGAGED. ENGINE IDLES EASY, GOES THROUGH RPMS WELL AND REVS STRONG.

**Inspectors Notes:** VEHICLE IS IN A GOOD ORIGINAL CONDITION. IT DOES SHOW ITS AGE AND NEEDS SOME REPAIRS TO THE DOOR HANDLES, PAINT, FLOOR PANS, ELECTRICAL SYSTEM AND WINDOWS BUT OVERALL A GOOD SOLID TRUCK.