



St Rose, Illinois 62230

www.TestDriveTech.com

Phone: 636-388-8378

Email: info@testdrivetech.com

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 11/6/2017

VIN JN1CZ14S0EX005527

Trim: 50TH ANNIVERSARY

Year: 1984

Vehicle Type: T-TOP COUPE

Make: DATSUN / NISSAN

Number of Doors: 2

Model: 300Z

Engine Size: V6 TURBO

Mileage: 25,113

Transmission Type: 5 SPEED MANUAL

Hours: NA

Driveline Type: RWD

Section Notes: VIN VERIFIED WINDSHIELD TAG, JAM TAG AND APRON TAG

How Each
Inspection Section Is
Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

Left Front Fender	2.0
Left Hood Cowl	2.0
Left Front Door	2.0
Left Center B-Pillar	NA
Left Rear Door	NA
Left C-Pillar	3.0
Left Quarter Panel	3.0
Left Rocker Panel	3.0

Right Front Fender	2.0
Right Hood Cowl	2.0
Right Front Door	2.0
Right Center B-Pillar	NA
Right Rear Door	NA
Right C-Pillar	2.0
Right Quarter Panel	2.0
Right Rocker Panel	2.0

Section Condition Grade 2.5

Section Condition Grade 2.0

Section Notes: VEHICLE BODY IS IN GOOD CONDITION. SOME MINOR IMPERFECTIONS IN ROCKER PANELS AND QUARTERS BUT VERY NICE SMOOTH FINISH AND SHUTTINGS. REAR BUMPER AND LR QUARTER SHOW TO HAVE BEEN REPAINTED.

Front Body Condition

Hood	2.0
Front Bumper	2.0
Headlamps	2.0
Windshield Cowl	2.0
Front Roof Top	2.0

Section Condition Grade 2.0

Rear Body Condition

Trunk	2.0
Rear Bumper	3.0
Tail Lamps	2.0
Deck Cowl	2.0
Rear Roof Top	2.0

Section Condition Grade 2.2

VEHICLE BODY IS IN GOOD CONDITION. SOME MINOR IMPERFECTIONS

Section Notes: IN ROCKER PANELS AND QUARTERS BUT VERY NICE SMOOTH FINISH AND SHUTTINGS. REAR BUMPER AND LR QUARTER SHOW TO HAVE BEEN REPAINTED.

Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	2.0
Steering Wheel Condition	2.0
Driver Seat Condition	2.0
Passenger Seat Condition	2.0
Front Carpet Condition	2.0
Left Front Door Panel	2.0
Left Rear Side Panel	2.0
Cargo Interior Sides	2.0
Front Center Console / Arm Rest	2.0
Section Condition Grade	2.0

Rear Interior Condition

Rear Seat Type	NA
3rd Seat Present	NA
Rear Seat Condition	NA
Rear Deck Condition	NA
Rear Carpet Condition	2.0
3rd Seat Condition	NA
Right Front Door Panel	1.0
Right Rear Side Panel	2.0
Cargo Floor & Roof	3.0
Rear Center Console / Arm Rest	NA
Section Condition Grade	2.0

Section Notes: INTERIOR IN VERY GOOD CONDITION. CARGO INSULATION PULLING AWAY FROM BACKING BUT STILL OK.

Tire Condition

Front Tire Size	16 INCH
Left Front Tire Tread	2.0
Right Front Tire Tread	2.0
Rear Tire Size	16 INCH
Left Rear Tire Tread	2.0
Right Rear Tire Tread	2.0
Valve Caps Present	YES

Section Condition Grade 2.0

Wheel Condition

Wheel Type	ALLOY
Left Front Wheel Condition	3.0
Right Front Wheel Condition	3.0
Left Rear Wheel Condition	3.0
Right Rear Wheel Condition	3.0
Spare Tire / Wheel Present	NA
Jack / Emergency Tools Present	YES

Section Condition Grade 3.0

TIRES ARE NEW. WHEELS SHOW SOME MINOR SCUFFS AND SCRATCHES

Section Notes: BUT ARE STILL PRESENTABLE.

Interior Option Operation

Left Front Seat Operation	2.0
Right Front Seat Operation	2.0
Rear Seat Operation	NA
Heater / Fan	2.0
Stereo Operation	1.0
Navigation Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	NA

Section Condition Grade 1.8

Exterior Option Operation

Left Front Window Operation	3.0
Right Front Window Operation	3.0
Left Rear Window Operation	NA
Right Rear Window Operation	NA
Cargo Door Operation	1.0
Door Locks Operation	2.0
Windshield Wiper Operation	2.0
Rear Defrost Operation	2.0

Section Condition Grade 2.2

ALL FEATURES WORKING AS DESIGNED HOWEVER WINDOWS ARE A BIT

Section Notes: SLUGGISH BUT STILL IN WORKING CONDITION.

Interior Lighting Condition

Dash Lamps Operation	1.0
Interior Lighting Operation	1.0
Glove Box Lights Operation	NA
Dome Lights Operation	1.0
Hood Lamp Operation	NA
Seat Belt Light Operation	1.0

Section Condition Grade 1.0

Exterior Lighting Condition

Low Beam Head Light Operation	1.0
High Beam Head Light Operation	1.0
Parking Lamp Operation	1.0
4-Way Flasher Operation	1.0
Left Turn Operation	1.0
Right Turn Operation	1.0

Section Condition Grade 1.0

Section Notes: ALL LIGHTS WORKING AS DESIGNED.

Engine Mechanical Condition

Engine Block Condition	1.0
Engine Hoses Condition	1.0
Engine Oil Leaks	2.0
Fuel Leaks	1.0
Air Filter Condition	1.0
Radiator Condition	2.0

Section Condition Grade 1.3

Transmission Mechanical Condition

Trans Housing Condition	1.0
Tran Lines Condition	NA
Trans Fluid Condition	NA
Trans Fluid Leaks Condition	2.0
Trans Cooler Condition	NA
Trans Shifter Condition	1.0

Section Condition Grade 1.3

Section Notes: ENGINE, TRANSMISSION IN VERY GOOD CONDITION. SOME SMALL SLIGHT LEAKAGE NOTICED AROUND TRANSMISSION BUT NOTHING MAJOR. ENGINE WOULD BENEFIT FROM NEW PLUGS AND SOME DRIVING TO CLEAN OUT SOME OLD FUEL ALSO RECOMMEND A FUEL FILTER CHANGE AS THE CAR HAS A SLIGHT ROUGH IDLE AND HESITATION OFF THROTTLE

Brakes Mechanical Condition

Front Brake Material	3.0
Front Brake Rotors / Drums	2.0
Rear Brake Material	3.0
Rear Brake Rotors / Drums	2.0
Brake Lines Condition	2.0
Parking Brake Operation	1.0
Section Condition Grade	2.2

Steering Mechanical Condition

Rack-n-Pinion Condition	2.0
Tie Rods Condition	3.0
Steering Linkage Condition	3.0
Steering Column Condition	1.0
Pump / Gearbox Condition	1.0
Alignment Condition	1.0
Section Condition Grade	1.8

Section Notes: VEHICLE STOPS WELL AND STRAIGHT. STEERING IN GOOD CONDITION.
NO CATCHING NO PULLING. BRAKES SHOW TO BE AT 50% LIFE
REMAINING. TIE RODS SHOW LOTS OF SURFACE RUST AND AGE.

Suspension Mechanical Condition

Front Shocks Condition	3.0
Rear Shocks Condition	3.0
Bushings Condition	3.0
Sway Bar Links Condition	3.0
Suspension Control Condition	3.0
Control Arms Condition	3.0
Section Condition Grade	3.0

Electrical Systems Condition

Oil Pressure Light Test	PASS
Engine Coolant Light Test	PASS
Seat Belt Light Test	PASS
Brake Warning Lamp	OFF
Wiring Condition	1.0
Battery Condition	1.0

Section Condition Grade 1.0

SUSPENSION IN GOOD CONDITION BUT MOST BUSHINGS SHOW THEIR

Section Notes: AGE. ELECTRONICS AND DIAGNOSTICS CHECKED AND ARE FREE OF
ISSUE.

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	3.0
Firewall Repair / Condition	3.0
Floor Pans Repair / Condition	3.0
Apron Repair / Condition	3.0
Inner Quarter Repair / Condition	3.0
Frame Rail Repair / Condition	3.0
Rocker Panel Repair / Condition	3.0
Section Condition Grade	3.0

Conventional Frame Condition

Frame Rail Repair / Condition	3.0
Cross Member Repair / Condition	3.0
Radiator Core Repair / Condition	3.0
Trunk Pan Repair / Condition	3.0
Spring Pod Repair / Condition	3.0
Torque Box Repair / Condition	3.0
Wheel House Repair / Condition	3.0
Section Condition Grade	3.0

Section Notes: NO MAJOR UNDERCARRIAGE ISSUES FOUND. UNDERCARRIAGE DOES
SHOW LARGE AMOUNTS OF SURFACE RUST AND FACTORY
UNDERCOATING FLAKING OFF BUT NO SOFT SPOTS IN PANS OR FRAME.

Test Drive Results

Acceleration	3.0
Shifting	3.0
Steering	2.0
Braking	2.0
Ride / Handling	2.0
Rattles / Noises	2.0
Warning Lights	1.0
Section Condition Grade	2.1

Condition Summary

Body	3.0
Interior	3.0
Features / Options	2.0
Mechanical	3.0
Electrical	2.0
Structural	3.0
Test Drive	2.1

Overall Vehicle Grade	2.6
-----------------------	-----

Section Notes: VEHICLE RUNS AND DRIVES WELL. IT DOES SHOW SIGNS OF NEEDING A TUNE UP AND SOME REGULAR MAINTENANCE. STOPS WELL, STEERS WELL AND HAS AVERAGE POWER WITH OUT MUCH MAJOR ISSUE.

Inspectors Notes: VEHICLE IS IN GOOD ORIGINAL CONDITION. VEHICLE DOES SHOW SOME SIGNS OF A COUPLE AREAS HAVING BEEN REPAINTED IN THE PAST BUT OVERALL IN GOOD CONDITION.