



St Rose, Illinois 62230  
 www.TestDriveTech.com  
 Phone: 636-388-8378  
 Email: info@testdrivetech.com

# TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



## Vehicle Identification

Inspection Date: 11/6/2017

VIN WBSFV9C54FD594383  
 Year: 2015  
 Make: BMW  
 Model: M5  
 Mileage: 13,167  
 Hours: NA

Trim: M5  
 Vehicle Type: COUPE  
 Number of Doors: 4  
 Engine Size: 4.4L V8  
 Transmission Type: AUTOMATIC  
 Driveline Type: RWD

**Section Notes:** VIN VERIFIED WINDSHIELD TAG, JAM TAG AND APRON TAG

### How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

### Left Side Body Condition

### Right Side Body Condition

Left Front Fender	1.0
Left Hood Cowl	1.0
Left Front Door	1.0
Left Center B-Pillar	1.0
Left Rear Door	1.0
Left C-Pillar	1.0
Left Quarter Panel	1.0
Left Rocker Panel	1.0

Right Front Fender	1.0
Right Hood Cowl	1.0
Right Front Door	1.0
Right Center B-Pillar	1.0
Right Rear Door	1.0
Right C-Pillar	1.0
Right Quarter Panel	1.0
Right Rocker Panel	1.0

Section Condition Grade 1.0

Section Condition Grade 1.0

**Section Notes:** VEHICLE BODY IS IN GOOD CONDITION. COMMON SCRATCHES ON UNDERSIDE OF FRONT BUMPER, SOME SLIGHT SCRATCHES ON CORNERS OF FRONT AND REAR BUMPER.S

**Front Body Condition**

Hood	2.0
Front Bumper	3.0
Headlamps	2.0
Windshield Cowl	2.0
Front Roof Top	2.0
Section Condition Grade	2.2

**Rear Body Condition**

Trunk	2.0
Rear Bumper	2.0
Tail Lamps	2.0
Deck Cowl	2.0
Rear Roof Top	2.0
Section Condition Grade	2.0

VEHICLE BODY IS IN GOOD CONDITION. COMMON SCRATCHES ON

Section Notes: UNDERSIDE OF FRONT BUMPER, SOME SLIGHT SCRATCHES ON CORNERS OF FRONT AND REAR BUMPER.S

**Front Interior Condition**

Front Seat Type	BUCKETS
Dashboard Condition	2.0
Steering Wheel Condition	2.0
Driver Seat Condition	2.0
Passenger Seat Condition	2.0
Front Carpet Condition	2.0
Left Front Door Panel	2.0
Left Rear Side Panel	2.0
Cargo Interior Sides	2.0
Front Center Console / Arm Rest	2.0
Section Condition Grade	2.0

**Rear Interior Condition**

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	2.0
Rear Deck Condition	2.0
Rear Carpet Condition	2.0
3rd Seat Condition	NA
Right Front Door Panel	2.0
Right Rear Side Panel	2.0
Cargo Floor & Roof	2.0
Rear Center Console / Arm Rest	2.0
Section Condition Grade	2.0

Section Notes: INTERIOR IN VERY GOOD CONDITION.

**Tire Condition**

Front Tire Size	265/35ZR20
Left Front Tire Tread	1.0
Right Front Tire Tread	1.0
Rear Tire Size	295/30ZR20
Left Rear Tire Tread	1.0
Right Rear Tire Tread	1.0
Valve Caps Present	YES
Section Condition Grade	1.0

**Wheel Condition**

Wheel Type	POWDER COATED
Left Front Wheel Condition	2.0
Right Front Wheel Condition	2.0
Left Rear Wheel Condition	2.0
Right Rear Wheel Condition	2.0
Spare Tire / Wheel Present	NA
Jack / Emergency Tools Present	YES
Section Condition Grade	2.0

TIRES ARE NEW. WHEELS SHOW SOME MINOR SCUFFS AND SCRATCHES

Section Notes: BUT ARE STILL VERY PRESENTABLE.

**Interior Option Operation**

Left Front Seat Operation	2.0
Right Front Seat Operation	2.0
Rear Seat Operation	NA
Heater / Fan	2.0
Stereo Operation	1.0
Navigation Operation	1.0
Front Seat Belts Present	YES
Rear Seat Belts Present	YES

Section Condition Grade 1.6

**Exterior Option Operation**

Left Front Window Operation	2.0
Right Front Window Operation	2.0
Left Rear Window Operation	2.0
Right Rear Window Operation	2.0
Cargo Door Operation	1.0
Door Locks Operation	2.0
Windshield Wiper Operation	2.0
Rear Defrost Operation	2.0

Section Condition Grade 1.9

ALL FEATURES WORKING AS DESIGNED.

Section Notes:

**Interior Lighting Condition**

Dash Lamps Operation	1.0
Interior Lighting Operation	1.0
Glove Box Lights Operation	1.0
Dome Lights Operation	1.0
Hood Lamp Operation	NA
Seat Belt Light Operation	1.0

Section Condition Grade 1.0

**Exterior Lighting Condition**

Low Beam Head Light Operation	1.0
High Beam Head Light Operation	1.0
Parking Lamp Operation	1.0
4-Way Flasher Operation	1.0
Left Turn Operation	1.0
Right Turn Operation	1.0

Section Condition Grade 1.0

Section Notes: ALL LIGHTS WORKING AS DESIGNED.

**Engine Mechanical Condition**

Engine Block Condition	1.0
Engine Hoses Condition	1.0
Engine Oil Leaks	1.0
Fuel Leaks	1.0
Air Filter Condition	1.0
Radiator Condition	1.0

Section Condition Grade 1.0

**Transmission Mechanical Condition**

Trans Housing Condition	1.0
Tran Lines Condition	1.0
Trans Fluid Condition	1.0
Trans Fluid Leaks Condition	1.0
Trans Cooler Condition	1.0
Trans Shifter Condition	1.0

Section Condition Grade 1.0

Section Notes: ENGINE, TRANSMISSION IN VERY GOOD CONDITION.

**Brakes Mechanical Condition**

Front Brake Material	2.0
Front Brake Rotors / Drums	2.0
Rear Brake Material	2.0
Rear Brake Rotors / Drums	2.0
Brake Lines Condition	2.0
Parking Brake Operation	1.0
Section Condition Grade	1.8

**Steering Mechanical Condition**

Rack-n-Pinion Condition	2.0
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	2.0
Alignment Condition	1.0
Section Condition Grade	1.8

Section Notes: VEHICLE STOPS WELL AND STRAIGHT. STEERING IN GOOD CONDITION. NO CATCHING NO PULLING. BRAKES SHOW TO BE AT 75% LIFE REMAINING.

**Suspension Mechanical Condition**

Front Shocks Condition	2.0
Rear Shocks Condition	2.0
Bushings Condition	2.0
Sway Bar Links Condition	2.0
Suspension Control Condition	2.0
Control Arms Condition	2.0
Section Condition Grade	2.0

**Electrical Systems Condition**

Oil Pressure Light Test	PASS
Engine Coolant Light Test	PASS
Seat Belt Light Test	PASS
Brake Warning Lamp	OFF
Wiring Condition	1.0
Battery Condition	1.0
Section Condition Grade	1.0

SUSPENSION, STEERING AND ELECTRICAL SYSTEMS IN VERY GOOD

Section Notes: CONDITION.

**Unibody Frame Condition**

A,B,C,D Pillar Repair / Condition	1.0
Firewall Repair / Condition	1.0
Floor Pans Repair / Condition	1.0
Apron Repair / Condition	1.0
Inner Quarter Repair / Condition	1.0
Frame Rail Repair / Condition	1.0
Rocker Panel Repair / Condition	1.0
Section Condition Grade	1.0

**Conventional Frame Condition**

Frame Rail Repair / Condition	1.0
Cross Member Repair / Condition	1.0
Radiator Core Repair / Condition	1.0
Trunk Pan Repair / Condition	1.0
Spring Pod Repair / Condition	1.0
Torque Box Repair / Condition	1.0
Wheel House Repair / Condition	1.0
Section Condition Grade	1.0

Section Notes: NO UNDERCARRIAGE ISSUES FOUND.

**Test Drive Results**

<b>Acceleration</b>	1.0
<b>Shifting</b>	1.0
<b>Steering</b>	1.0
<b>Braking</b>	1.0
<b>Ride / Handling</b>	1.0
<b>Rattles / Noises</b>	1.0
<b>Warning Lights</b>	1.0
<b>Section Condition Grade</b>	1.0

**Condition Summary**

<b>Body</b>	2.0
<b>Interior</b>	2.0
<b>Features / Options</b>	1.0
<b>Mechanical</b>	2.0
<b>Electrical</b>	1.0
<b>Structural</b>	1.0
<b>Test Drive</b>	1.0
<b>Overall Vehicle Grade</b>	1.4

**Section Notes:** VEHICLE RUNS AND DRIVES LIKE NEW. STOPS WELL, STEERS WELL AND HAS AVERAGE POWER WITH OUT AN ISSUES.

**Inspectors Notes:** VEHICLE IS IN GOOD ORIGINAL CONDITION. HAS A FEW BUMPS AND BRUISES ON THE BUMPERS BUT OVERALL A VERY CLEAN AND WELL MAINTAINED VEHICLE.