



WWW.
TESTDRIVETECH
VEHICLE INSPECTION SERVICES .COM

St Rose, Illinois 62230

WWW.TESTDRIVETECH.COM

PHONE: 636-388-8378

EMAIL: INFO@TESTDRIVETECH.COM

TEST DRIVE TECHNOLOGIES VEHICLE INSPECTION SERVICES



Vehicle Identification

Inspection Date: 4/2/2018

VIN 124379N651900	Trim: Z28
Year: 1969	Vehicle Type: HARDTOP COUPE
Make: CHEVROLET	Number of Doors: 2
Model: CAMARO	Engine Size: V8
Mileage: 41,436	Transmission Type: 4 SPEED MANUAL
Hours: NA	Driveline Type: RWD

Section Notes: VIN VERIFIED BY DASH TAG. ENGINE SHOWS A NUMBER JUST BELOW THE HEAD ON THE ENGINE BLOCK OF C0514DZ WHICH DOES NOT MATCH THE VIN OR BODY TAG

How Each Inspection Section Is Graded

Each area of the vehicle is graded based on the standard grading scale adopted by the vehicle inspection industry. The number "1" represents the best of the best and cream of the crop. The number "6" represents a salvage vehicle that is only good for parts. The majority of today's used cars and classic cars fall into the "3-4" grading scale.

Left Side Body Condition

Right Side Body Condition

Left Front Fender	3.0	Right Front Fender	3.0
Left Hood Cowl	3.0	Right Hood Cowl	3.0
Left Front Door	4.0	Right Front Door	4.0
Left Center B-Pillar	NA	Right Center B-Pillar	NA
Left Rear Door	NA	Right Rear Door	NA
Left C-Pillar	3.0	Right C-Pillar	3.0
Left Quarter Panel	3.0	Right Quarter Panel	3.0
Left Rocker Panel	3.0	Right Rocker Panel	3.0

Section Condition Grade 3.2

Section Condition Grade 3.2

Section Notes: VEHICLE SHOWS AN OLDER RESTORATION. PAINT STILL SHOWS NICE HOWEVER DOES HAVE SEVERAL CHIPS AND SCRATCHES THAT LOOK TO HAVE BEEN TOUCHED UP BY HAND. DOORS HAVE SOME PANEL WAVE BELOW THE BODY LINE AS WELL AS SOME LIGHT DINGS.

Front Body Condition

Engine Cover	3.0
Front Bumper	3.0
Headlamps	1.0
Front Glass	2.0
Front Roof Top	3.0
Left Side Stainless Trim	4.0
Section Condition Grade	2.7

Rear Body Condition

Trunk / Tailgate	3.0
Rear Bumper	3.0
Tail Lamps	2.0
Rear Glass	2.0
Rear Roof Top	3.0
Right Side Stainless Trim	4.0
Section Condition Grade	2.8

Section Notes: STAINLESS ALL AROUND CAR SHOWS MINOR DINGS AND SCRATCHES THROUGHOUT AND WILL NEED REMOVED AND POLISHED TO BE SHOW READY. DRIP RAILS IN ROOF HAVE ROUGH SEAM SEALER TO THE EYE BUT ARE STILL FAIR.

Front Interior Condition

Front Seat Type	BUCKETS
Dashboard Condition	3.0
Steering Wheel Condition	2.0
Driver Seat Condition	3.0
Passenger Seat Condition	3.0
Front Carpet Condition	2.0
Left Front Door Panel	2.0
Left Rear Side Panel	2.0
Trunk Interior Sides	4.0
Front Center Console / Arm Rest	3.0
Section Condition Grade	2.7

Rear Interior Condition

Rear Seat Type	BENCH
3rd Seat Present	NA
Rear Seat Condition	3.0
Rear Deck Condition	3.0
Rear Carpet Condition	3.0
3rd Seat Condition	NA
Right Front Door Panel	2.0
Right Rear Side Panel	2.0
Trunk Floor	3.0
Rear Center Console / Arm Rest	NA
Section Condition Grade	2.7

Section Notes: DASHBOARD APPEARS TO BE AN AFTERMARKET REPLACEMENT. YOU CAN TELL BY THE SHARP EDGES ALONG THE SIDES NEAR THE WINDSHIELD. STILL LOOKS GOOD AND TIGHT THOUGH. TRUNK WAS FOUND WET, ASSUME THAT THE SEALS ARE LEAKING. INNER QUARTERS AND WHEEL HOUSES SHOW CORROSION AND POOR WELDS.

Tire Condition

Front Tire Size	E70-15
Left Front Tire Tread	2.0
Right Front Tire Tread	2.0
Rear Tire Size	E70-15
Left Rear Tire Tread	2.0
Right Rear Tire Tread	2.0
Valve Caps Present	YES
Section Condition Grade	2.0

Wheel Condition

Wheel Type	RALLY WHEELS W RINGS
Left Front Wheel Condition	3.0
Right Front Wheel Condition	3.0
Left Rear Wheel Condition	3.0
Right Rear Wheel Condition	3.0
Spare Tire / Wheel Present	YES
Jack / Emergency Tools Present	YES
Section Condition Grade	3.0

Section Notes: TIRES AND WHEELS IN GOOD CONDITION. STAINLESS RINGS SHOW LIGHT SCRATCHES BUT STILL IN GOOD CONDITION.

Interior Option Operation

Left Front Seat Operation	1.0
Right Front Seat Operation	1.0
Rear Seat Operation	NA
Heater / Fan	2.0
Stereo Operation	NA
Sunroof Operation	NA
Front Seat Belts Present	YES
Rear Seat Belts Present	NO

Section Condition Grade 1.3

Exterior Option Operation

Left Front Window Operation	2.0
Right Front Window Operation	2.0
Left Rear Window Operation	5.0
Right Rear Window Operation	5.0
Cargo Door Operation	3.0
Door Locks Operation	1.0
Windshield Wiper Operation	1.0
Antenna Operation	NA

Section Condition Grade 2.7

HEATER BLOWER AND SELECTOR WORKS WELL. NO STEREO INSTALLED.

Section Notes: REAR WINDOWS GET STUCK 50% WAY UP / DOWN AND REQUIRE HAND TO PULL OR PUSH ALONG. TRUNK LOCK HARD TO OPERATE

Interior Lighting Condition

Dash Lamps Operation	1.0
Interior Lighting Operation	3.0
Glove Box Lights Operation	NA
Map Lights Operation	NA
Hood Lamp Operation	NA
Seat Belt Light Operation	NA
Horn Operation	6.0

Section Condition Grade 3.3

HORN NOT WORKING.

Section Notes:

Exterior Lighting Condition

Low Beam Head Light Operation	1.0
High Beam Head Light Operation	1.0
Parking Lamp Operation	1.0
4-Way Flasher Operation	1.0
Left Turn Operation	1.0
Right Turn Operation	1.0
Reverse Lights Operation	1.0

Section Condition Grade 1.0

Engine Mechanical Condition

Engine Block Condition	2.0
Engine Hoses Condition	1.0
Engine Oil Leaks	5.0
Coolant Leaks	1.0
Air Filter Condition	1.0
Radiator Condition	1.0

Section Condition Grade 1.8

Transmission Mechanical Condition

Trans Housing Condition	2.0
Tran Lines Condition	NA
Trans Fluid Condition	5.0
Trans Fluid Leaks Condition	1.0
Trans Cooler Condition	NA
Trans Shifter Condition	3.0

Section Condition Grade 2.8

Section Notes: ENGINE AND TRANSMISISON DO NOT MATCH VIN ON CAR. ENGINE SHOWS A PRETTY BAD OIL LEAK FROM REAR MAIN AREA OR OIL PAN. TRANSMISSION COVERED IN OIL FROM ENGINE OR IS LEAKING ALSO (UNABLE TO TELL FOR SURE). TRANS SHIFTER HITS CONSOLE WHEN SHIFTING INTO 2ND AND 4TH.

Brakes Mechanical Condition

Front Brake Material	2.0
Front Brake Rotors / Drums	2.0
Rear Brake Material	2.0
Rear Brake Rotors / Drums	2.0
Brake Lines Condition	2.0
Parking Brake Operation	1.0
Section Condition Grade	1.8

Steering Mechanical Condition

Rack-n-Pinion Condition	NA
Tie Rods Condition	2.0
Steering Linkage Condition	2.0
Steering Column Condition	2.0
Pump / Gearbox Condition	NA
Alignment Condition	1.0
Section Condition Grade	1.8

Section Notes: BRAKES IN GOOD CONDITION. STOPS FIRMLY AND STRAIGHT. STEERING IN GOOD CONDITION. STEERS WELL AND STRAIGHT WITH SLIGHT PLAY.

Suspension Mechanical Condition

Front Shocks Condition	2.0
Rear Shocks Condition	2.0
Bushings Condition	2.0
Sway Bar Links Condition	2.0
Suspension Control Condition	NA
Control Arms Condition	2.0
Section Condition Grade	2.0

Electrical Systems Condition

Oil Pressure Gauge	1.0
Engine Temp Gauge	1.0
Amperage / Voltage Gauge	1.0
Fuel Gauge	6
RPM / Speedometer Gauges	NA
Wiring Condition	1.0
Battery Condition	2.0
Section Condition Grade	2.0

SUSPENSION IN GOOD CONDITION. GAUGES WORK EXCEPT FUEL

Section Notes: GAUGE. HAD TO TAP ON IT TO GET IT TO MOVE.

Unibody Frame Condition

A,B,C,D Pillar Repair / Condition	2.0
Firewall Repair / Condition	2.0
Floor Pans Repair / Condition	3.0
Apron Repair / Condition	2.0
Inner Quarter Repair / Condition	4.0
Body Mounts Repair / Condition	3.0
Rocker Panel Repair / Condition	3.0
Section Condition Grade	2.7

Conventional Frame Condition

Frame Rail Repair / Condition	3.0
Cross Member Repair / Condition	3.0
Radiator Core Repair / Condition	3.0
Trunk Pan Repair / Condition	3.0
Spring Pod Repair / Condition	3.0
Torque Box Repair / Condition	3.0
Wheel House Repair / Condition	4.0
Section Condition Grade	3.1

VEHICLE SHOWS SEVERAL REPAIRS TO FLOOR PANS AND INNER ROCKER

Section Notes: PANELS. ALSO SHOWS CORROSION ON INNER WHEEL HOUSE AND INNER QUARTERS AND IS NOT COATED.

Test Drive Results

Acceleration	2.0
Shifting	2.0
Steering	2.0
Braking	2.0
Ride / Handling	2.0
Rattles / Noises	4.0
Warning Lights	1.0

Section Condition Grade 2.1

Condition Summary

Body	3.5
Interior	3.0
Features / Options	3.0
Mechanical	3.5
Electrical	2.0
Structural	2.8
Test Drive	2.1

Overall Vehicle Grade 2.8

Section Notes: VEHICLE WAS TEST DRIVEN UP TO 55 MPH. CAR HANDLES WELL AND BRAKES GOOD. CLUTCH FEELS GOOD AND TRANSMISSION SHIFTS WELL. ENGINE HAS DECENT POWER AND GOOD IDLE BUT SEEMS TO STICK SLIGHTLY. NORMAL RATTLES AND SOUNDS OF A CLASSIC CAR.

Inspectors Notes: CAR SHOWS TO HAVE HAD A RESTORATION SOME TIME AGO. SEVERAL BODY ISSUES EXIST FROM AGE. SEVERAL AREAS FOR IMPROVEMENT TO MAKE THE CAR MORE ENJOYABLE. WOULD MAKE A GOOD DRIVER OR OCCASIONAL SHOW CAR. NEEDS SOME TLC AND WORK TO BE A #2 CAR.